

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 589S**AAD1811-161***Not Authored
61 Sing & 50501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 589S

VF1ABL15AUC278428

RENAULT

LATITUDE

19.11.2018

AIG**PART****LIST**

1	DOOR PANEL FRT RH	\$	<i>BT/way</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>SL</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>N</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>N</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>SL</i> 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>SL</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>SL</i> 120.97
1	DOOR PANEL REAR RH	\$	<i>BT/way</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>SL</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>N</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>SL</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>SL</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>SL</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>SL</i> 176.82

Trans-cab Auto Services Pte Ltd**AAD1811-161**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 589S

1	DOOR MOULDING CLIP L70Y	\$	na 5.92	}	X
1	DOOR MOULDING SCREW L70Y	\$	na 6.91		
1	DOOR CASING REAR RH	\$	sn 1,509.06		
1	DOOR WATER SHIELD REAR RH	\$	sn 30.39		
1	DOOR CASING CLIP	\$	na 12.63		
1	DOOR CASING LIGHT L70Y	\$	sn 48.74		
1	DOOR FINISHER INNER REAR RH	\$	sn 323.44		
1	DOOR FINISHER BRACKET INNER REAR RH	\$	na 46.97		
1	DOOR FINISHER BRACKET INNER REAR RH	\$	na 20.33		
1	DOOR FINISHER BRACKET INNER REAR RH	\$	na 20.33		
1	DOOR FINISHER BRACKET INNER REAR RH	\$	na 20.33		
1	DOOR GRAB HANDLE REAR RH	\$	sn 210.96		
1	DOOR BLIND REAR RH	\$	sn 741.80		
1	DOOR WHEATHSTRIP REAR RH	\$	sn 410.66		
1	DOOR SEAL REAR RH	\$	sn 162.02		
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn 229.31		
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn 334.69		
1	DOOR WAIST SEAL INNER REAR RH	\$	sn 115.64		
1	DOOR MIRROR ASSY RH	\$	sn 1,483.40		

\$	20,094.54
----	------------------

10% \$	2,009.45
--------	-----------------

\$	18,085.09
----	------------------

Specical Nett

1	REAR DOOR STICKER '6555-3333'	\$	na 80.00	60sn	}	X
1SET	WHEELARCH CLIP FRT LH	\$	na 30.50	X		
1	FRONT DOOR STICKER 'Trans-cab'	\$	na 80.00	60sn		
1	FRONT DOOR STICKER 'Chassis'	\$	na 50.00	15sn		
1	DOOR CHECK BOLT	\$	na 22.69			
1	DOOR GUIDE SCREW	\$	na 10.85			
1	DOOR HINGE BOLT	\$	na 10.85			
1	DOOR HINGE NUT RH	\$	na 14.60			
1	DOOR CHECK BOLT	\$	na 22.69			
1	DOOR CHECK NUT	\$	na 3.75			
1	DOOR LOCK SCREW L70Y	\$	na 6.12			
1	DOOR CATCH SCREW L70Y	\$	na 10.06			

Trans-cab Auto Services Pte Ltd

AAD1811-161

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 589S

TOTAL	\$	342.13
-------	----	--------

TOTAL PARTS	\$	18,427.22
-------------	----	-----------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	400/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To rust-proofing of the affected areas.	\$	170.00	60/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60/ 120/
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60/

TOTAL	\$	7,870.00
-------	----	----------

Over All Total	\$	26,297.22
----------------	----	-----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**10 DAYS**

2 1/2 days