



Section A - Accident Details

Registration Number	SHD6055L
Case Reference Number	TAX/11/18/2068
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	KELVIN LAU
Type of Accident	Head To Side
Accident Date and Time	15/11/2018 6:55 PM
Accident Reported Date and Time	16/11/2018 2:07 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098774
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	16/11/2018 3:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



1/2/18

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,183.00	\$400.00
Total Spray Cost	\$2,232.00	\$500.00
Total Spare Part Cost	\$17,012.63	\$4,363.84
Total Other Cost	\$1,356.00	\$160.00
TOTAL COST	\$21,783.63	\$5,423.84 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / AIG
ARC / Surveyor Sign Off Date	16/11/2018 4:57 PM	19/11/2018 2:01 PM
Signature		
Remarks	PART BY PART REPAIR. 3 DAYS. CHECK ITEMS PHOTOS. BEFORE PAINT PHOTOS.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0143	Invoice Number	
Quotation Date	14.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,183.00	\$400.00
Total Labour	\$1,183.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,232.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$50.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$1,356.00	\$160.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given
		28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Not Given
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Check
		53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check
		81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Check
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Check
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check
		52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check
		75536470 20	MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check
		53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Check
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
			COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check
		53808470 20	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Check
		52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Check
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check
		53301471 10	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Not Given
		53828470 70	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Check
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
Total					\$20,108.96		\$4,244.57		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace
		53214470 50	SUPPORT, RADIATOR UPPER LH	1.00	\$76.70	25.00	\$57.53	Replace	Replace
Total					159.00		119.25		

25,052.46#

CONFIRMED PART BY PART REPAIR \$ 5423.84 / 4 DAYS.

NAZUKIC
HJ