

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Nov 2018 Edit Reg		19 Nov 2018 00:00 Edit Adj Rpt	S\$5,423.84 Edit Estimates	S\$5,423.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MICRO CREDIT (CAR LEASING) PTE LTD , Co. Reg. No.: 200910504E									
Main Claimant: SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K									
Vehicle Reg. No.: SHD6055L		Date of Loss: 15/11/2018 17:00 - :59 [11 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4712175468SG		Policy/Cover Note No.: 0999994683 (Third Party Only)							
Vehicle Reg. No. (Insured): SJT1028R		Policy No. (Claimant): D-18090213MFSH							
		Excess:							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Claimant's Insurer: MS First Capital Insurance Ltd (HQ) - Tel: 62222311									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 30/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD6055L (4712175468SG)**
[SJT1028R]
TP
SMRT TAXIS PTE LTD
Nov 15 2018 5:00PM
[MICRO CREDIT (CAR LEASING) PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/01/19 17:32	Video - Accident	Load MP4	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/19 17:40	General View	Load JPG	☒
2	20/02/19 17:40	General View	Load JPG	☒
3	20/02/19 17:40	General View	Load JPG	☒
4	20/02/19 17:40	General View	Load JPG	☒
5	20/02/19 17:40	General View	Load JPG	☒
6	20/02/19 17:40	General View	Load JPG	☒
7	20/02/19 17:40	General View	Load JPG	☒
8	20/02/19 17:40	General View	Load JPG	☒
9	20/02/19 17:40	General View	Load JPG	☒
10	20/02/19 17:40	General View	Load JPG	☒
11	20/02/19 17:40	General View	Load JPG	☒
12	20/02/19 17:40	General View	Load JPG	☒
13	20/02/19 17:40	General View	Load JPG	☒
14	20/02/19 17:40	Dismantled Parts	Load JPG	☒
15	20/02/19 17:40	Dismantled Parts	Load JPG	☒
16	20/02/19 17:40	Dismantled Parts	Load JPG	☒
17	20/02/19 17:40	Replacement Part Photo	Load JPG	☒
18	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
19	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
20	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
21	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
22	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
23	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
24	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
25	20/02/19 17:41	Replacement Part Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/18 19:01	TP ESTIMATE- MARKED	Load PDF	
2	21/11/18 19:01	TP GIA REPORT	Load PDF	
3	18/06/19 10:29	LETTER TO OI	Load PDF	
4	25/02/20 14:49	Email to TP maintain rejection	Load PDF	
5	28/05/20 11:47	EMAIL TO SMRT - REJECT TP CLAIM	Load PDF	
6	28/05/20 11:52	APPROVAL FROM AIG TO REJECT TP CLAIM	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	22/11/18 10:10	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG18021051/NKA3S2**Date:** 30/06/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994683
Claimant Vehicle No :	SHD6055L	Insured Vehicle No :	SJT1028R
Date of Loss:	15/11/2018	Nature of Claim:	TP
		Claim No:	4712175468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6055L	Engine No:	2ZRS106792
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU303574881
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	83005 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,281.46	4,363.84	15,917.62	78.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,771.00	1,060.00	3,711.00	77.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	25,052.46	5,423.84	19,628.62	78.35

INSPECTION

Date of Assignment:	19/11/2018	
Date Inspected:	19/11/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
2	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	1		*COVER, FR BUMPER (DISC 25%)	Cracked	495.50 F	*371.63 F
4	1		*FENDER SUB-ASSY, FR, LH (DISC 25%)	Deformed	933.10 F	*699.83 F
5	1		*SUPPORT, FR BUMPER LH (DISC 25%)	Bent	82.30 F	*61.73 F
6	1		*SUPPORT, RADIATOR UPPER LH (DISC 25%)	Cracked	76.70 F	*57.53 F
7	1		*UNIT, HEADLAMP, LH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
8	1		*LAMP ASSY, FOG, LH (DISC 10%)	Cracked	910.20 F	*819.18 F
9	1		*PANEL SUB-ASSY, FRONT DOOR LH	Serviceable	1,249.60 F	*- F
10	1		*BATTERY	Serviceable	1,584.90 F	*- F
11	1		*ABSORBER, FR BUMPER LOWER	Serviceable	117.00 F	*- F
12	1		*SUPPORT, RADIATOR UPPER LH	Serviceable	76.70 F	*- F
13	1		*ABSORBER, FR BUMPER	Serviceable	70.30 F	*- F
14	1		*WHEEL, DISC FRONT	Serviceable	1,555.10 F	*- F
15	1		*WIRE, ENGINE ROOM MAIN	Serviceable	6,138.00 F	*- F
16	1		*COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	Serviceable	486.40 F	*- F
17	1		*EXTENSION SUBASSY, LH	Serviceable	116.30 F	*- F
18	1		*APRON SUB-ASSY, FRONT FENDER, LH	Serviceable	944.20 F	*- F
19	1		*SUPPORT, FR BUMPER LH	Serviceable	82.30 F	*- F
20	1		*GRILLE, RADIATOR	Serviceable	165.00 F	*- F
21	1		*REINFORCEMENT FRONT LOWER	Serviceable	238.50 F	*- F
22	1		*MOULDING LH	Serviceable	83.30 F	*- F
23	1		*LINER, FR FENDER, LH	Serviceable	194.30 F	*- F
24	1		*PAD, FR WHEEL LH	Serviceable	57.70 F	*- F
25	1		*TYRE	Serviceable	126.74 F	*- F
26	1		*COVER, FR BUMPER LH	Serviceable	28.10 F	*- F
27	1		*REINFORCEMENT FRONT UPPER	Serviceable	691.10 F	*- F
28	1		*HOOD SUB-ASSY	Serviceable	938.40 F	*- F
29	1		*PROTECTOR, FR FENDER LH	Serviceable	90.40 F	*- F
30	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*- F
31	1		*COOLANT	Not Necessary	12.32 F	*- F
32	1		*SEAL SUB-ASSY, LH	Serviceable	50.20 F	*- F

F=Franchise part.

Total Parts (\$\$) **20,281.46** **4,363.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,183.00	400.00
2	SPRAY PAINT.	New	2,232.00	500.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	40.00
4	TO CHECK & RESET SYSTEM FUNCTION.	New	350.00	50.00
5	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
6	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
8	TO REMOVE AND REFIT WIRE HARDESS.	New	250.00	0.00
9	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
10	TO TOP UP A/C GAS.	New	120.00	0.00
11	TO WASH AMD VACUUM.	New	60.00	0.00
12	TOEING CHARGE.	New	56.00	40.00
Gross Labour Cost (\$\$)			4,771.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >