

Adrian LEE - AXA



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

20/11/2018

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPAYA
Joy

KMH1D841CMJU687975

Accident date: 19/11/2018

Estimated repair cost for vehicle no: SJP8311Y HYUNDAI ELANTRA 1.6 A '18

CHASSIS: KMHD841CMJU687975

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$1,358.00 -1048
2	2	Rear Boot Lid Hinge <i>New</i>	\$84.30	\$168.60 +
3	1	Rear Boot Lid Emblem Logo <i>2 new</i>		\$28.80 -
4	1	Rear Boot Lid Elantra Logo		\$38.50 -
5	2	Rear Boot Lid Side Reflector <i>over</i>	\$168.80	\$337.60 +
6	1	Rear Boot Lid Inner Lock <i>paid</i>		\$116.20 -
7	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$80.60 -
8	1	Rear Boot Lid Inner Trim Board <i>2 new</i>		\$144.60 +
9	8	Rear Boot Lid Inner Trim Board Clip <i>1 new</i>	\$6.50	\$52.00 + 384.50
10	2	Rear Tail Lamp <i>LH cut</i>	\$876.00	\$1,752.00 -876
11	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$28.00	\$56.00 +
12	1	Rear Bumper <i>rehard</i>		\$489.00 -
13	10	Rear Bumper Clip <i>New</i>	\$6.50	\$65.00 -30
14	2	Rear Bumper Side Retainer <i>New</i>	\$40.00	\$80.00 -
15	2	Rear Bumper Side Reflector <i>LH cut</i>	\$38.00	\$76.00 -38
16	1	Rear Bumper Reinforcement <i>Best</i>		\$328.00 -
17	2	Rear Bumper Reinforcement Bracket <i>new</i>	\$34.00	\$68.00 -
18	5	Rear Bumper Top & Lower Bracket <i>sent</i>	\$36.00	\$180.00 -
19	1	Rear Bumper Lower <i>rehard</i>		\$242.80 -
20	1	Rear Bumper Reverse Sensor <i>2nd</i>		\$380.00 200 (200)
21	1	Rear R/H Bumper Side Lower Cover <i>cut</i>		\$95.50 -
22	1	Rear L/H Fender Inner Trim Board <i>new</i>		\$287.00 +
23	10	Rear L/H Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00 +
24	1	Rear End Panel <i>rehard</i>		\$379.00 -
25	1	Rear End Panel Top Garnish <i>rehard</i>		\$105.00 +
26	1	Rear Spare Tyre Panel <i>Repair</i>		\$416.00 +
27	1	Rear Spare Tyre Panel Top Cover <i>new</i>		\$225.00 +
28	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 +
29	1	Rear Exhaust <i>new</i>		\$798.30 +

3731.90 S.N. 200
298552

Subtotal :- \$8,862.50

Labour charges

To remove & refit cushion & trim board		\$280.00 60
To remove & refit reverse sensor		\$100.00 60
To remove & refit rear exhaust		\$280.00 +
To check wiring	1810	\$60.00 30
Tuff Kote		\$100.00 40
Panel beating		\$1,600.00 800
Spray painting		\$1,600.00 800

Subtotal :- \$4,020.00

Total:- \$12,882.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
H/S 2/11/18
06hys
total 4995.52
H/S: AK.
AK.