



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR PC5977T\*M

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT  
8 SHENTON WAY #24-01  
SINGAPORE 068811

Work: 64733122

## Vehicle & Document Information

WIP No 28467  
Reg No/Reg Date PC5977T\*M / 31/05/2017  
Date In/Mileage PC5977T\*M  
Chassis No WDF44770523262498  
Engine No 65195033919272  
Make/Model MBCV/VITO TOURER 116VTS/E 4X2  
Colour/Trim 021 197 Obsidian B1/ NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	21/11/2018/ 09:29	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : B28674059MKF // 8-11-18  
DRIVE IN/ 8-11-18 // TP-CAR No. SKA64708 - AXA

DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT

A BPIRES

RESPRAY FRONT BUMPER

A BPILAB

DISASSEMBLE AND INSTALL ATTACHED FRONT BUMPER & REFINISH.

A BPILAB

USE XENTRY TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STA

M LEFT HEADLAMP UNIT

lt.

1.00

3178.32 00.00

120.00 ✓

720.00 600.

960.00 600.

380.00 200.

3178.32 ✓

ESTIMATE

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Adrian L

P/P 18/07/19.

03 Days.

Confirmed & accepted by

7% GST on **Nett** 5,358.32 375.08

**Total Payable** 5,733.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg