



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR PC5977T*M

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811

Work: 64733122

Vehicle & Document Information

WIP No 28467
Reg No/Reg Date PC5977T*M / 31/05/2017
Date In/Mileage 0
Chassis No WDF44770523262498
Engine No 65195033919272
Make/Model MBCV/VITO TOURER 116VTS/E 4X2
Colour/Trim 021 197 Obsidian Bl/ NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
CS100001	Cash	21/11/2018/ 09:29	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M. BPNSUN

POLICY NO. ACC. DATE : B28674059MKF // 8-11-18

DRIVE IN: 18-11-18 // TP CAR NO. SKA64708 - AXA

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT

A BPIRES

RESPRAY FRONT BUMPER

A BPILAB

DISASSEMBLE AND INSTALL ATTACHED FRONT BUMPER & REFINISH

A BPILAB

USE XENTRY TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STA

M LEFT HEADLAMP UNIT

1.00 3178.32 00.00

120.00 ✓

720.00 600.

960.00 600.

380.00 200.

3178.32 ✓

3293.41

ESTIMATE

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Adrian Ly

P/P 18/07/19.

03 Days.

Confirmed & accepted by

Nett 5,358.32
7% GST on 5358.32 375.08

Total Payable 5,733.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR PC5977T*M

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811

Work: 64733122

Vehicle & Document Information
WIP No 28467
Reg No/Reg Date PC5977T*M / 31/05/2017
Date In/Mileage 26/07/2019/ -43883
Chassis No WDF44770523262498
Engine No 65195033919272
Make/Model MBCV/VITO TOURER 116VTS/E 4X2
Colour/Trim 021 197 Obsidian B1/ NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
CSI00001	Cash	30/07/2019/ 09:54	K0	301 / Kerlyn Ong				

Description of Goods / Services								
M. BPNSUN POLICY NO/ACC DATE : 828674059MKF // 8-11-18 DRIVE IN/ : 8-11-18 // TP-CAR No. SKA64708 - AXA DATE IN/DATE SURVEY: 18/7/19 - Adrian-LKK DIRECT SETTLEMENT : 29/11/2018 // LKK - VIC								
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT								120.00
A BPIRES RESPRAY FRONT BUMPER								600.00
A BPILAB DISASSEMBLE AND INSTALL ATTACHED FRONT BUMPER & REFINISH							0.10	380.00
A BPILAB USE XENTRY TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STA								3293.41
X LEFT HEADLAMP UNIT							1.00	3293.41 00.00

Finalization

Confirmed & accepted by

7% GST on 5353.41

Nett 5,353.41
374.74

Total Payable 5,728.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg