

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

## ESTIMATE REPAIR

Pg 1

AXA Insurance Pte Ltd

Date: 16.11.2018

Owner's Name : Loh Yoke Chan

Vehicle No : SCY6888Z

Claim Type: Third Party Claim

Vehicle Make & Model : Volkswagen Golf 1.4 A

Chassis No: WVWZZZ1KZCW156056

Registration Date : 13 Jan 2012 (YOM 2011) COE Expiry Date 13 Jan 2012

DOA: 16.11.2018

| No | Description                                           | Unit | List (\$)   |
|----|-------------------------------------------------------|------|-------------|
| 1  | FRONT BONNET <i>Bnc /</i>                             | 1    | \$ 1,080.00 |
| 2  | FRONT BONNET HINGE <i>BA /</i>                        | 2    | \$ 180.00   |
| 3  | FRONT BONNET STOPPER <i>NA /</i>                      | 2    | \$ 30.00    |
| 4  | FRONT BONNET SEAL <i>NA /</i>                         | 2    | \$ 70.00    |
| 5  | FRONT BONNET RUBBER <i>NA /</i>                       | 1    | \$ 85.00    |
| 6  | FRONT BONNET LOCK <i>BA /</i>                         | 1    | \$ 198.00   |
| 7  | FRONT BONNET STAND <i>X need 8 T bar</i>              | 1    | \$ 55.00    |
| 8  | FRONT BONNET STAND CLIP <i>X</i>                      | 1    | \$ 18.00    |
| 9  | FRONT BONNET LOCK BRACE PANEL <i>X</i>                | 1    | \$ 115.00   |
| 10 | FRONT BONNET INSULATOR <i>NA /</i>                    | 1    | \$ 268.00   |
| 11 | FRONT BONNET INSULATOR CLIPS <i>NA /</i>              | 10   | \$ 35.00    |
| 12 | FRONT BONNET CABLE <i>X</i>                           | 1    | \$ 65.00    |
| 13 | FRONT HEADLAMP LH <i>BRO /</i>                        | 1    | \$ 680.00   |
| 14 | FRONT HEADLAMP RH <i>CRA /</i>                        | 1    | \$ 680.00   |
| 15 | FRONT HEADLAMP LOWER BRACKET LH <i>clear BA CRA /</i> | 1    | \$ 138.00   |
| 16 | FRONT HEADLAMP LOWER BRACKET RH <i>2 X</i>            | 1    | \$ 138.00   |
| 17 | FRONT HEADLAMP GASKET LH <i>NA ?</i>                  | 1    | \$ 95.00    |
| 18 | FRONT HEADLAMP GASKET RH <i>NA ?</i>                  | 1    | \$ 95.00    |
| 19 | FRONT HEADLAMP TOP PANEL <i>BA /</i>                  | 2    | \$ 112.00   |
| 20 | FRONT HEADLAMP SUPPORT PANEL <i>?</i>                 | 2    | \$ 220.00   |
| 21 | FRONT FOGLAMP LH <i>CRA /</i>                         | 1    | \$ 192.60   |
| 22 | FRONT FOGLAMP RH <i>X</i>                             | 1    | \$ 192.60   |
| 23 | FRONT FOGLAMP GARNISH LH <i>SEA /</i>                 | 1    | \$ 138.60   |
| 24 | FRONT FOGLAMP GARNISH RH <i>3 X</i>                   | 1    | \$ 138.60   |
| 25 | FRONT FOGLAMP GARNISH CHROME LH <i>SEA /</i>          | 1    | \$ 65.00    |
| 26 | FRONT FOGLAMP GARNISH CHROME RH <i>X</i>              | 1    | \$ 65.00    |

Total (A) : \$ 5,149.40

Less 10% \$ 514.94

Total: \$ 4,634.46

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

## ESTIMATE REPAIR

Pg 2

AXA Insurance Pte Ltd

Date: 16.11.2018

Owner Owner's Name : Loh Yoke Chan

Vehicle No : SCY6888Z

Claim Type: Third Party Claim

Vehicle Make & Model : Volkswagen Golf 1.4 A

Chassis No: WVWZZZ1KZCW156056

Registration Date : 13 Jan 2012 (YOM 2011) COE Expiry Date 13 Jan 2012

DOA: 16.11.2018

| No | Description                          | Unit | List (\$)   |
|----|--------------------------------------|------|-------------|
| 27 | FRONT FENDER CLOSING ELEMENT LH ?    | 1    | \$ 99.00    |
| 28 | FRONT FENDER CLOSING ELEMENT RH ?    | 1    | \$ 99.00    |
| 29 | FRONT FENDER CLOSING ELEMENT CLIPS ? | 8    | \$ 24.00    |
| 30 | FRONT FENDER LH ?                    | 1    | \$ 550.00   |
| 31 | FRONT FENDER RH ?                    | 1    | \$ 550.00   |
| 32 | FRONT FENDER SHIELD LH(FRONT) ?      | 1    | \$ 127.00   |
| 33 | FRONT FENDER SHIELD LH (REAR) X      | 1    | \$ 148.50   |
| 34 | FRONT FENDER SHIELD RH(FRONT) X      | 1    | \$ 127.00   |
| 35 | FRONT FENDER SHIELD RH (REAR) X      | 1    | \$ 148.50   |
| 36 | FRONT FENDER SHIELD CLIPS ?          | 20   | \$ 70.00    |
| 37 | FRONT BUMPER ?                       | 1    | \$ 880.00   |
| 38 | FRONT BUMPER SIDE RETAINER ?         | 2    | \$ 220.00   |
| 39 | FRONT BUMPER CLIPS ?                 | 10   | \$ 35.00    |
| 40 | FRONT BUMPER TOW COVER X             | 1    | \$ 65.00    |
| 41 | FRONT GRILLE WITH CHROME ?           | 1    | \$ 560.00   |
| 42 | FRONT GRILLE CLIPS ?                 | 10   | \$ 35.00    |
| 43 | FRONT LOWER GRILLE ?                 | 1    | \$ 190.90   |
| 44 | FRONT SUPPORT PANEL ?                | 1    | \$ 780.00   |
| 45 | FRONT REINFORCEMENT ?                | 1    | \$ 480.90   |
| 46 | RADIATOR (OUTER) ?                   | 1    | \$ 680.00   |
| 47 | RADIATOR (INNER) ?                   | 1    | \$ 580.00   |
| 48 | RADIATOR FAN MOTOR ASSY ? X          | 1    | \$ 1,050.00 |
| 49 | RADIATOR TANK X                      | 1    | \$ 80.00    |
| 50 | RADIATOR TOP HOSE X                  | 1    | \$ 220.00   |
| 51 | RADIATOR PIPE LOWER X                | 1    | \$ 160.00   |
| 52 | DISCHARGE PIPE X                     | 1    | \$ 368.00   |

Total (B) : \$ 8,327.80

Less 10% \$ 832.78

Total: \$ 7,495.02

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL:62715133/ 62717433 FAX:62745715

Pg 3

DOA: 16.11.2018

|             |    |           |
|-------------|----|-----------|
| Total (C) : | \$ | 13,442.15 |
| Less 10%    | \$ | 1,344.22  |
| Total:      | \$ | 12,097.94 |

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL:62715133/ 62717433 FAX:62745715

Pg 4

DOA: 16.11.2018

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL:62715133/62717433 FAX:62745715

## Pg 5

DOA: 16.11.2018

| No | Description                                                                                                  | Unit | List (\$)         |
|----|--------------------------------------------------------------------------------------------------------------|------|-------------------|
|    | <b>Labour</b>                                                                                                |      |                   |
| 1  | Spray Painting to All Affected Areas                                                                         | 1    | \$ 1000 / 1600.00 |
| 2  | Labour Remove / Refix Accident Damages parts to knock , jack, cut weld<br>and realign accident affected area | 1    | \$ 1200 / 2000.00 |
| 3  | Check Wiring System & Light                                                                                  | 1    | \$ 30 / 100.00    |
| 4  | Anti Rust Treatment                                                                                          | 1    | \$ 80 / 120.00    |
| 5  | To Check & Adjust Wheel Aligment                                                                             | 1    | \$ X / 100.00     |
| 6  | To Remove/Refix/Replace Dashboard                                                                            | 1    | \$ 150 / 350.00   |
| 7  | To Check Water Leaking                                                                                       | 1    | \$ 30 / 150.00    |
| 8  | To Realign / Adjust Front Main Chassis                                                                       | 1    | \$ 150 / 300.00   |
| 9  | To Remove / Replace Front Windscreen                                                                         | 1    | \$ 120 / 180.00   |
| 10 | To Remove/Replace/Refix Front Seat Belt & Bucket                                                             | 1    | \$ 200 / 300.00   |
| 11 | To Remove/Replace Airbag LH ,Steering Airbag and Lower Airbag                                                | 1    | \$ 400 / 600.00   |
| 12 | To Remove/Replace/Refix Airbag Contro Unit                                                                   | 1    | \$ 200 / 500.00   |
| 13 | Upholstery Details Cleaning                                                                                  | 1    | \$ 50 / 220.00    |
| 14 | Computer Diagnostic                                                                                          | 1    | \$ 100 / 350.00   |
| 15 | Reprogramming Airbag System                                                                                  | 1    | \$ 150 / 350.00   |
|    | Rasul                                                                                                        |      |                   |
|    | Hp 90010068                                                                                                  |      |                   |
|    | 12 14 days                                                                                                   |      |                   |
|    | L/S                                                                                                          |      |                   |
|    | 21/11/18 @ 1430                                                                                              |      |                   |
|    | Resuming after repair                                                                                        |      |                   |

|             |    |          |
|-------------|----|----------|
| Total (E) : | \$ | 7,220.00 |
|-------------|----|----------|

|              |    |           |
|--------------|----|-----------|
| Grand Total: | \$ | 31,695.42 |
|--------------|----|-----------|