## **ESTIMATED ACCIDENT REPAIR COST**



PAGE 1

ACCIDENT TIME REPORTED	18:50HRS	BUS REGISTRA NUMBER	ATION	SBS3334T	
ACCIDENT DATE	19-Nov-18	BUS TYPE (SD,	/DD)	DD	
BUS CAPTAIN NAME	AARON ANG	BUS ROUTE N	UMBER		
THIRD PARTY CLAIM AGAINST	FWD Singapore Pte. Ltd.	BUS ADVERTS	(Y/N)	N	
SECTION 1: PARTS &	CONSUMABLE ITEMS (MATERIAL COST	г)			
NO.	Part or Iter	n Description		Quantity	Total Cost
1	O/S/F COR	NER BUMPER report		1	× \$160.00
2	O/S/F BE	ZEL LIGHT X500		1	× \$190.90
3	O/S/F D	ZELLIGHT X500 EFLECTOR repair		1	≯ \$390.00
				7% GST	\$51.86
		0		PARTS TOTAL COST	\$792.76
SECTION 2: ASSESSM	ENT / REPAIR / SPRAY PAINT (LABOUR	R COST)			
	LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)				
TO DISMANTLE & REPLACE DAMAGED PARTS 32:					\$1,300.00
SPRAY PAINTING 320					\$1,280.00
		7			
				7% GST	\$180.60
				LABOUR TOTAL COST	\$2,760.60
SPRAY PAINTING \$640 PER	PANEL			645	

## **ESTIMATED ACCIDENT REPAIR COST**



SECTION 3: REPAIRS TO BI	IS ADVERTISMENT VIN	NYLS/PANELS (ADVI	ERTISEMENT COST)
--------------------------	---------------------	-------------------	------------------

TOTAL ADVERTISEMENT REPAIR COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

**TOTAL TOWING COST** 

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

BUS TYPE (SD / DD)	DD	Number of Days Bus in Workshop	3	
LOSS OF USE COST			\$1,200.00	

SUMMARY				
SECTION NO.	COST			
1	\$792.76			
2	\$2,760.60			
3	-			
4	-			
5	\$1,200.00			
GRAND TOTAL	\$4,753.36			

Pasul
Hp 90010068

I days
21/11/18@1615

Resures after repair

PAGE 2

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: