

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9959U**AAD1811-158***Not Authorized*
11 Sep @ 1300h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9959U

VF1ABL15AUC273418

RENAULT

LATITUDE

17.11.2018

CHINA TAIPING

PART		LIST	
1	DOOR PANEL FRT LH	\$	<i>N</i> 2,844.66
1	DOOR HINGE UPPER LH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>N</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>N</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97
1	DOOR MIRROR ASSY LH	\$	<i>Bu</i> 1,483.40 ✓
1	BUMPER COVER REAR	\$	<i>Sn</i> 1,108.46 X
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 X
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
		\$	10,343.58
10%		\$	1,034.36
		\$	9,309.22

Special Nett

1	FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00 X
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69 X
1	DOOR GUIDE SCREW	\$	<i>nn</i> 10.85 X
1	DOOR HINGE BOLT	\$	<i>nn</i> 10.85 X

Trans-cab Auto Services Pte Ltd

AAD1811-158

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9959U

1	DOOR HINGE NUT RH	\$	nn 14.60	X
1	DOOR CHECK BOLT	\$	nn 22.69	X
1	DOOR CHECK NUT	\$	nn 3.75	X
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	X
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	X

TOTAL \$ 181.63**TOTAL PARTS \$ 9,490.85****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	801
Putty and spray painting of the affected portion.	\$	3,000.00	2201
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LUMP SUM (REPAIR DAY)

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 7,870.00**Over All Total \$ 17,360.85****10 DAYS**

1 day