

22/03/2002

ASS. REC. BY:

REF: CG/CTU8021088/T15602

Special Instruction:

Surveyor
Mullman

T. J. J. J.

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CT

Date/Time:

21.11.2018 4:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 3703X

Insured:

STU 1809J

at Workshop m/s

Wearnes

Tel:

8126 1257

of

249 Alexandra Rd

Policy No:

DMPCSN306053180

Claim No:

SNM18D05346C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13.11.2018

CA / REV / REP. / REV 24 HRS 'Wp'

23.11.2018 @ 2pm - 2:30pm

H.O.D. Endorsement:

Date/Time:

21.11.2018 5:10pm

Person Contacted:

Paul

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJD 3703X - X
	STU 1809J - PCG / QBE / 5006548 / Angus 2
	DAF = 14042015

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2018		21 Nov 2018 16:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NORHAFIS BIN MOHAMED, ID: S8340318G		[Created by insurer]
Main Claimant:	WENDY TAN YIN CHERN, ID: S7711813F		
Vehicle Reg. No.:	SJD3703X	Date of Loss:	13/11/2018 12:00 - :59
Claim Type:	TP / SNM18D05346C02	Policy/Cover Note No.:	DMPCSN306053180 (Comprehensive)
Vehicle Reg. No. (Insured):	SGU1809J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/11/2018]		
Adj Asg. Remarks:	EST \$14,521.30, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Friday, 12 April 2019 10:09 AM
To: 'Paul Ong Qing Yong'
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SJD3703X Finalise

Sensitivity: Confidential

Hi Paul,

COR \$4246.95 , 3 days.

Regards
Taufikh
Lkk AUTO

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Monday, 11 March 2019 9:38 AM
To: 'Taufikh (LKK Auto)'
Subject: SJD3703X Finalise
Importance: High
Sensitivity: Confidential

Attached for finalise

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

* with insurance reply
 Email 15/11/18
 * DIC-Collection this 429611
 * liability cleared
 * survey on 28/11/18 @ 2pm

ACCIDENT STATEMENT	
Date Of Report	13/11/2018 18:08
Date Of Accident	13/11/2018 12:50
Exact Location Of Accident	BUKIT TIMAH ROAD TOWARDS FARRER ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJD3703X
Insured/Policyholder	
Name Of Registered Owner	WENDY TAN YIN CHERN
NRIC No	S7711813F
Email Address	WENDY.TAN.YC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96927610
Alternative Phone No	OTHERS-96927610
Vehicle Particulars	
Manufacturer	INFINITI
Model	Q60-2.0 T COUPE (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	C0079487
Driver	
Name of Driver	WENDY TAN YIN CHERN
NRIC No	S7711813F
Date Of Birth	04/05/1977
Occupation	INDOOR
Date Of Driving Pass	14/01/1995
Driving Experience	23 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96927610
Fax Number	
Contact Number	OTHERS-96927610
Email Address	WENDY.TAN.YC@GMAIL.COM

Address	1 SWISS VIEW #03-03
Postcode	288007
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGU1809J
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NORHAFIS BIN MOHAMED
NRIC/Passport Number	S8340318G
Contact Number	90685674
Address	BLK 287C COMPASSVALE CRESCENT #03-181
Postcode	543287
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing w ith my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

I, driver of 8JD370SX was travelling towards Fawer Rd via the slip road from Bukit Timah Rd. I stopped at the "giveaway" markings and was hit from behind by vehicle number 8G4T809J, driven by Mr Norhafiz Bin Mohamed (S8340318 E).
The accident occurred at 12.51pm on 13 Nov 2018.
Video footage available.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.


13/11/18

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

95256 - C00001 SL: SERVICE SALES - PC

Ms Wendy Tan Yin Chern
4 PANDAN VALLEY
#05-407

Singapore 597628

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 15/11/2018
WIP No. . : 38280
Veh.In/Out:
*Tel.No. . : Mobile: 96927610
Reg.No. . : SJD3703X
Reg.date . : 18/01/2018
Mileage .. : 0
Chassis No: JN1GCAV37Z0400041

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Ms Wendy Tan Yin Che

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR SENSOR, REAR BEAM, ETC	0	3600.00	0		3,600.00 S	
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR PANEL, ETC	0	2400.00	0		2,400.00 S	
802	TO REPLACE REAR EXHAUST	0	1800.00	0		1,800.00 S	
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0	3N	60.00 S	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	390.00	0		390.00 S	
	FACE-RR BUMPER	1.0 EA	800.10			800.10 S	
	FASCIA-REAR BUM	1.0 EA	536.30			536.30 S	
	ENERGY ABSORBER	1.0 EA	98.00			98.00 S	
	REINF-BUMPER RR	1.0 EA	567.40			567.40 S	
	FINISHER-REAR B	1.0 EA	56.00			56.00 S	
	FINISHER-REAR B	1.0 EA	56.00			56.00 S	

Tayhm 97495749
"WP"
28/11/18 @ 1415
Reamy before paint
03 days.
sur@lkhauto.com.

SERVICE ESTIMATE

95256 - C00001 SL: SERVICE SALES - PC

Ms Wendy Tan Yin Chern

4 PANDAN VALLEY

#05-407

Singapore 597628

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 15/11/2018

WIP No. : 38280

Veh.In/Out:

*Tel.No. : Mobile: 96927610

Reg.No. : SJD3703X

Reg.date. : 18/01/2018

Mileage : 0

Chassis No: JN1GCAV37Z0400041

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Ms Wendy Tan Yin Che

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET-BUMPER	1.0 EA	30.80			30.80	S ?
	BRACKET-BUMPER	1.0 EA	30.80			30.80	S ?
	FINISHER-REAR B	1.0 EA	28.00			28.00	S ?
	RETAINER-BUMPER	1.0 EA	42.00			42.00	S ?
	RETAINER-BUMPER	1.0 EA	42.00			42.00	S ?
	MUFFLER ASSY	1.0 EA	1405.60			1,405.60	S ?
	DIFFUSER ASSY	2.0 EA	81.20			162.40	S ?
	GASKET	2.0 EA	16.80			33.60	S ?
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20	S ?
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ?
						494.19	

Gross Total. 13,571.30

Labour Total 8,250.00
 Parts Total 5,321.30
 Package Total 0.00

Net..... 13,571.30

GST @ 7.0% 949.99

Total..... 14,521.30

Paid..... 0.00

Please pay 14,521.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

- Link Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 11/03/2019
 SINGAPORE 079909 WIP No. . : 38280
 Veh.In/Out: 28/11/2018 14/12/2018
 *Tel.No. . : 63896111
 Reg.No. . : SJD3703X
 Closed by : Patricia Kueh Anak S Reg.date .: 18/01/2018
 Svc Consultant : ACC Mileage ... : 5,152
 Remarks : Ms Wendy Tan Yin Che Chassis No: JN1GCAV37Z0400041

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR	0	900.00	0		900.00	S
	BRACKET,REAR SENSOR						
800	TO PUTTY SPRAY PAINT ON REAR	0	1200.00	0		1,200.00	S
	BUMPER,REAR PANEL,ETC						
R06	TO INSTALL REAR NUMBER PLATE	0	60.00	0		60.00	S
	INCLUDE HOLDER						
280	TO CHECK WIRING INCLUDE	0	390.00	0		390.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	FACE-RR BUMPER	1.0 EA	800.10	10		720.09	S
	FASCIA-REAR BUM	1.0 EA	536.30	10		482.67	S
	ADHESIVE SEALER FL2	1.0 EA	549.10	10		494.19	S <i>rel ✓</i>

Gross Total. 4,246.95

Labour Total 2,550.00
Parts Total 1,696.95
Package Total 0.00

Net..... 4,246.95
 GST @ 7.0% 297.29
 Total..... 4,544.24
 Paid..... 0.00
 Please Pay.. 4,544.24

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Nov 2018		21 Nov 2018 16:57 Edit Adj Rpt	S\$4,246.95 Edit Estimates	S\$4,246.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NORHAFIS BIN MOHAMED , ID: S8340318G								
Main Claimant:	WENDY TAN YIN CHERN , ID: S7711813F								
Vehicle Reg. No.:	SJD3703X	Date of Loss:	13/11/2018 12:00 - :59 [9 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05346C02	Policy/Cover Note No.:	DMPCSN306053180 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGU1809J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/11/2018]								
Adj Asg. Remarks:	EST \$14,521.30, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJD3703X (SNM18D05346C02)**
[SGU1809J]

TP






































WENDY TAN YIN CHERN

Nov 13 2018 12:00PM




[NORHAFIS BIN MOHAMED]




















Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Jin Auto Services Pte Ltd (Defu)								Thumbnail	Print			
1	13/11/18 17:30	Video - Accident [Linked Accident Report Documents]								Load MP4				
2	13/11/18 17:30	Video - Accident [Linked Accident Report Documents]								Load MP4				
3	13/11/18 17:30	Video - Accident [Linked Accident Report Documents]								Load MP4				
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Jin Auto Services Pte Ltd (Defu)								Thumbnail	Print			
1	13/11/18 17:32	Accident Statement								Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Jin Auto Services Pte Ltd (Defu)								Thumbnail	Print			
1	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
2	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
3	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
4	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
5	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
6	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
7	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
8	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
9	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
10	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
11	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
12	13/11/18 17:30	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
13	13/11/18 17:30	Scene Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
14	13/11/18 17:30	Scene Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
15	13/11/18 17:30	Scene Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			
2	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			
3	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			
4	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			
5	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			
6	12/04/19 10:17	General View								Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
7	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/04/19 10:17	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	12/04/19 10:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/11/18 16:56	REPAIR EST	 Load PDF	
2	21/11/18 16:56	TP GIA	 Load PDF	
3	21/11/18 16:56	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	13/11/18 17:29	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 17:29	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 17:29	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 17:29	Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 17:29	Certificate of Insurance [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Video			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print	
1	13/11/18 17:30	Video - Accident	 Load MP4		
2	13/11/18 17:30	Video - Accident	 Load MP4		
3	13/11/18 17:30	Video - Accident	 Load MP4		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	13/11/18 17:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	13/11/18 17:30	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	13/11/18 17:30	Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
14	13/11/18 17:30	Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
15	13/11/18 17:30	Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	13/11/18 17:29	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 17:29	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 17:29	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 17:29	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 17:29	Certificate of Insurance	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021088/T1SBE2

Date: 12/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN306053180

Claimant Vehicle No: SJD3703X Insured Vehicle No: SGU1809J

Date of Loss: 13/11/2018 Nature of Claim: TP Claim No: SNM18D05346C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD3703X

Make & Model: INFINITI Q60, 2.0 T COUPE (A) Engine No: 274AE071264A

Reg. Date: 18/01/2018 (Man. Year: 2017) Chassis No: JN1GCAV37Z0400041

Colour: Grey Odometer: 10897 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R19 Rear Tyre Size: 255/40 R19

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,381.30	1,756.95	3,624.35	67.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,190.00	2,490.00	5,700.00	69.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,571.30	4,246.95	9,324.35	68.71
+ GST 7.00/7.00% (S\$)	949.99	297.29	652.70	68.71
Nett Amount (S\$)	14,521.29	4,544.24	9,977.05	68.71

INSPECTION

Date of Assignment: 21/11/2018

Date Inspected: 28/11/2018 Inspected At: Wearnes Automotive Pte Ltd (Alexandra Road)
249 Alexandra Road
Singapore 159935

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2019)
Parts:	M1-COUPE	INFINITI Q60 2.0 T COUPE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD3703X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE INCLUDE HOLDER	Bent	60.00 FS	*60.00 FS
2	1		*FACE-RR BUMPER	Deformed	800.10 FS	*720.09 FS
3	1		*FASCIA-REAR BUM	Cracked	536.30 FS	*482.67 FS
4	1		*ENERGY ABSORBER	Not Necessary	98.00 FS	*- FS
5	1		*REINF-BUMPER RR	Not Necessary	567.40 FS	*- FS
6	1		*FINISHER-REAR B	Not Necessary	56.00 FS	*- FS
7	1		*FINISHER-REAR B	Not Necessary	56.00 FS	*- FS
8	1		*BRACKET-BUMPER	Not Necessary	30.80 FS	*- FS
9	1		*BRACKET-BUMPER	Not Necessary	30.80 FS	*- FS
10	1		*FINISHER-REAR B	Not Necessary	28.00 FS	*- FS
11	1		*RETAINER-BUMPER	Not Necessary	42.00 FS	*- FS
12	1		*RETAINER-BUMPER	Not Necessary	42.00 FS	*- FS
13	1		*MUFFLER ASSY	Not Necessary	1,405.60 FS	*- FS
14	2		*DIFFUSER ASSY	Not Necessary	162.40 FS	*- FS
15	2		*GASKET	Not Necessary	33.60 FS	*- FS
16	1		*BODY PANEL SEALANT X	Not Necessary	883.20 FS	*- FS
17	1		*ADHESIVE SEALER FL2	Necessary	549.10 FS	*494.19 FS
					Total Parts (S\$)	5,381.30 1,756.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, REAR BRACKET, REAR SENSOR, REAR BEAM, ETC	New	3,600.00	900.00
2	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR PANEL, ETC	New	2,400.00	1,200.00
3	TO REPLACE REAR EXHAUST	New	1,800.00	0.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	390.00	390.00
Gross Labour Cost (S\$)			8,190.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >