

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 7555 L.

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and rhs headlight. To repair rhs front fender. Re-organise crash management components. Reinstall all parts removed. ✓	\$ 1,800.00 500
3	To respray front bumper and rhs front fender. ✓	\$ 1,400.00 580 1100
4	To carry out diagnostic check. ✓	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 3,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7555 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rebun d</i>	\$ 1,849.00	✓ 1479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	x
3	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 30.00	+
4	FRONT BUMPER GRILLE-CENTER	\$ 171.00	x
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 180.00	+
6	FRONT BUMPER AIR GUIDE-RH <i>for</i>	\$ 73.00	✓ 57.84
7	RADIATOR GRILLE	\$ 972.00	+
8	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	x
9	FOAM FILLER PIECE	\$ 107.00	+
10	FRONT BUMPER CARRIER	\$ 702.00	x
11	FRONT BUMPER GUIDE SECTION	\$ 32.00	+
12	FRONT BUMPER COVER	\$ 109.00	x
13	SIGN 'CAUTION'	\$ 12.00	x
14	AIR CONDITONER STICKER <i>HL</i>	\$ 7.00	x
15	FRONT BUMPER SUPPORT-RH <i>HL</i>	\$ 24.00	x
16	FRONT LOCK CARRIER BRACKET	\$ 118.00	+
17	LED HEADLIGHT-RH	\$ 6,973.00	x
18	LED HEADLIGHT LIFT CYLINDER-RH	\$ 184.00	x
19	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	+
20	WHEEL HOUSING LINER ATTACHMENT PARTS <i>HL</i>	\$ 78.00	x
SUB- TOTAL SPARE PARTS		\$ 12,193.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7555 L .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL SPOILER -RH	\$	63.00 + ✓ 50.16
22	FRONT WHEEL SPOILER END PLATE-RH	\$	31.00 ✓
23	FRONT STONE CHIP GUARD-RH	\$	44.00 ✓
24	FRONT NO. PLATE	S/N \$	25.00 *
25	SUNDRIES <i>Not New</i>	\$	300.00 ? X
TOTAL SPARE PARTS		:	\$ 12,656.00
TOTAL LABOUR CHARGES		:	\$ 3,752.00
GRAND TOTAL		:	\$ 16,408.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Ling.

Surveyed Date

: 21/11/18.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised Repairs, 09 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1316/2018/GW
Date	:	19-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 26 dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Aw Weng Zhi, Dennis
Address	:	100 Coronation Road West Singapore 269321
Telephone	:	HP +65 91283000
Type of Claim	:	Own Damage Claims
Policy No.	:	1700085815
Vehicle No	:	SLV 7555 L
Model Code	:	Audi A4 Sedan 1.4 TFSI
Model / Year	:	Dec-17
Engine No	:	CVN 049910
Chassis No	:	WAUZZZF45JA041955
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Nov-18
Place of Accident	:	At Junc of Paya Lebar Rd and Exit From PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 7555 L.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and rhs headlight. To repair rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 1,800.00	\$ 500.00
3	To respray front bumper and rhs front fender.	\$ 1,400.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 3,752.00	\$ 2,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7555 L

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	
3	FRONT BUMPER SECURING STRIP	\$ 30.00	
4	FRONT BUMPER GRILLE-CENTER	\$ 171.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 180.00	
6	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	\$ 57.84
7	RADIATOR GRILLE	\$ 972.00	
8	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	
9	FOAM FILLER PIECE	\$ 107.00	
10	FRONT BUMPER CARRIER	\$ 702.00	
11	FRONT BUMPER GUIDE SECTION	\$ 32.00	
12	FRONT BUMPER COVER	\$ 109.00	
13	SIGN 'CAUTION'	\$ 12.00	
14	AIR CONTDITIONER STICKER	\$ 7.00	
15	FRONT BUMPER SUPPORT-RH	\$ 24.00	
16	FRONT LOCK CARRIER BRACKET	\$ 118.00	
17	LED HEADLIGHT-RH	\$ 6,973.00	
18	LED HEADLIGHT LIFT CYLINDER-RH	\$ 184.00	
19	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	
20	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 78.00	
SUB- TOTAL SPARE PARTS :		\$ 12,193.00	\$ 1,537.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7555 L .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	1,537.04
21	FRONT WHEEL SPOILER -RH		\$ 63.00	50.16
22	FRONT WHEEL SPOILER END PLATE-RH		\$ 31.00	
23	FRONT STONE CHIP GUARD-RH		\$ 44.00	
24	FRONT NO. PLATE	S/N	\$ 25.00	
25	SUNDRIES		\$ 300.00	
	TOTAL SPARE PARTS	:	\$ 12,656.00	\$ 1,587.20
	TOTAL LABOUR CHARGES	:	\$ 3,752.00	\$ 2,152.00
	GRAND TOTAL	:	\$ 16,408.00	\$ 3,739.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLV 7555 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1316/2018/MAS

23 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLV 7555 L, Audi A4 Sedan 1.4 TFSI S-tro

With reference to the above-mentioned vehicle, no. **SLV 7555 L**, claimant, **Mr. Aw Weng Zhi, Dennis**, please find the related document per attached.

1. A copy of the Original invoice no. 85013469 – S\$3,679.94
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLV 7555 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2233
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2233
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408629
Telephone: 6388 2233

Customer Service:
Service Appointment: 6366 2323
24-hour Breakdown Service: 9826 1233
Email: customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:08

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013469 Date: 18/02/2019 Order: SLV755SL Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SLV755SL (V 35362) Regn Date: 05/12/2017 Mileage: 17128 WIP No.: 32147
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45JA041955 Engine: CVN 049910 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, TO REPAIR RHS FRONT FENDER, REORGANISE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A0W0053888E	SPOILER Less 020%	1.00	62.70	50.16
X	A0W0007065C GRU	COVER Less 020%	1.00	1849.00	1,479.20
X	A0W0121764	AIR DUCT Less 020%	1.00	72.30	57.84

Parts 1,587.20
Labour 0.00
Sublet 2,152.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,439.20

7% GST 240.74

Grand Total 3,679.94



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLV 7555 L

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1316/2018/GW
10 December 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI
Vehicle Chassis No. : WAUZZZF45JA041955
Vehicle Regn No. : SLV 7555 L
Vehicle Mileage : 17128KM
Vehicle Owner : Mr. Aw Weng Zhi, Dennis
Certificate No : 1700085815
Own Damage Excess : S\$ 321.00 (inclusive of 7% GST)
Accident Date : 15/11/2018
Place : At Junc Of Paya Lebar Rd And Exit From PIE
Repair Cost : \$ 3,679.94
WIP No. : 32147
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


3 PM 11/12/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Nov 2018		21 Nov 2018 18:31 Edit Adj Rpt	S\$3,739.20 Edit Estimates	S\$3,739.20 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AW WENG ZHI, DENNIS, ID: S8105062G			Date of Loss:	15/11/2018 00:00 - :59 [11 Months and 10 Days From LTA Reg Date (Man Yr)]
Vehicle Reg. No.:	SLV7555L			Policy/Cover Note No.:	1700085815 (Comprehensive)
Claim Type:	OD / 2750836987SG			Excess:	S\$300.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/11/2018]				
Driver/Custodian:	YEO LI FANG (34 / Female), NRIC: S8419564B, Tel: +6596778326 Email: yeolifang@gmail.com				

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (22/11/2018): SLV7555L / OD / 15/11/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV7555L (2750836987SG)

OD

Nov 15 2018 12:00AM

[AW WENG ZHI, DENNIS]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
			1 per page ▼	☒
Video			Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		
1	15/11/18 15:09	Video - Accident [Linked Accident Report Documents]	1 Load MP4	
			3 per page ▼	☒
Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	22/11/18 14:39	General View	1 Load JPG	☒
2	22/11/18 14:39	Chassis Number	1 Load JPG	☒
3	22/11/18 14:39	General View	1 Load JPG	☒
4	22/11/18 14:39	General View	1 Load JPG	☒
5	22/11/18 14:39	General View	1 Load JPG	☒
6	22/11/18 14:39	General View	1 Load JPG	☒
7	22/11/18 14:39	General View	1 Load JPG	☒
8	22/11/18 14:39	General View	1 Load JPG	☒
9	22/11/18 14:39	General View	1 Load JPG	☒
10	22/11/18 14:39	General View	1 Load JPG	☒
11	22/11/18 14:39	General View	1 Load JPG	☒
12	22/11/18 14:39	General View	1 Load JPG	☒
13	22/11/18 14:39	General View	1 Load JPG	☒
14	22/11/18 14:39	General View	1 Load JPG	☒
15	22/11/18 14:39	General View	1 Load JPG	☒
16	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
17	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
18	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
19	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
20	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
21	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
22	01/02/19 16:14	Reinspection Photo	1 Load JPG	☒
			1 per page ▼	☒
Documentation			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	22/11/18 14:38	DRIVING & INS CERT.pdf	1 Load PDF	
2	22/11/18 14:38	ESTIMATE MARKED.pdf	1 Load PDF	
3	19/02/19 17:07	ESTIMATE MARKED 1.pdf	1 Load PDF	
4	01/03/19 10:17	DISCHARGE VOUCHER	1 Load PDF	
5	01/03/19 10:17	WORKSHOP INVOICE	1 Load PDF	

Linked Accident Report Documents

View [View in Browser](#) ▼

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/11/18 15:09	Video - Accident	 Load MP4	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/11/18 15:26	Accident Statement	 Load HTM	☒

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/11/18 14:36	Accident Photo	 Load JPG	☒
2	15/11/18 14:36	Accident Photo	 Load JPG	☒
3	15/11/18 14:36	Accident Photo	 Load JPG	☒
4	15/11/18 14:36	Accident Photo	 Load JPG	☒
5	15/11/18 14:36	Accident Photo	 Load JPG	☒
6	15/11/18 14:36	Accident Photo	 Load JPG	☒
7	15/11/18 14:36	Accident Photo	 Load JPG	☒
8	15/11/18 14:36	Accident Photo	 Load JPG	☒
9	15/11/18 14:36	Accident Photo	 Load JPG	☒
10	15/11/18 14:36	Accident Photo	 Load JPG	☒
11	15/11/18 14:36	Accident Photo	 Load JPG	☒
12	15/11/18 14:36	Accident Photo	 Load JPG	☒
13	15/11/18 14:36	Accident Photo	 Load JPG	☒
14	15/11/18 14:36	Accident Photo	 Load JPG	☒
15	15/11/18 14:36	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	15/11/18 15:25	Sketch Plan	 Load JPG	☒
2	15/11/18 15:25	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18021097/ASBS2
Date: 01/03/2019

REFERENCE

Insured/Claimant: AW WENG ZHI, DENNIS Policy No: 1700085815
Date of Loss: 15/11/2018 Nature of Claim: OD Claim No: 2750836987SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV7555L** Engine No: CVN049910
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Chassis No: WAUZZZF45JA041955
Reg. Date: 05/12/2017 (Man. Year: 2017) Odometer: 16341 km
Colour: Black
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,656.00	1,587.20	11,068.80	87.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,752.00	2,152.00	1,600.00	42.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,408.00	3,739.20	12,668.80	77.21
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	16,108.00	3,439.20	12,668.80	78.65
+ GST 7.00/7.00% (S\$)	1,127.56	240.74	886.82	78.65
Nett Amount (S\$)	17,235.56	3,679.94	13,555.62	78.65

INSPECTION

Date of Assignment: 21/11/2018 Premium Automobiles Pte Ltd (UBI)
Date Inspected: 21/11/2018 Inspected At: 55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	30.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	180.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Torn	73.00 FS	*57.84 FS
7	1		*RADIATOR GRILLE	Not Necessary	972.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	118.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION	Not Necessary	32.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Not Necessary	109.00 FS	*- FS
13	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	7.00 FS	*- FS
15	1		*FRONT BUMPER SUPPORT - RH	Not Necessary	24.00 FS	*- FS
16	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	118.00 FS	*- FS
17	1		*LED HEADLIGHT - RH	Not Necessary	6,973.00 FS	*- FS
18	1		*LED HEADLIGHT LIFT CYLINDER - RH	Not Necessary	184.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	209.00 FS	*- FS
20	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
21	1		*FRONT WHEEL SPOILER - RH	Cracked	63.00 FS	*50.16 FS
22	1		*FRONT WHEEL SPOILER END PLATE - RH	Not Necessary	31.00 FS	*- FS
23	1		*FRONT STONE CHIP GUARD - RH	Not Necessary	44.00 FS	*- FS
24	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					12,656.00	1,587.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,800.00	500.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	New	1,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			3,752.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >