

ASS. REC. BY:

REF: CS/FCI18021105/Kad3nt

Special Instruction:

Surveyor:
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time: 22/11/18 9.22am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 9016R

Insured:

SHC 0591A

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Blk 7, Sin Ming Ind. Est #01-76

Policy No:

Claim No:

D1800826AMFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9.47am @ 22/11/18

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SME 9016R -x

SHC 0591A - CS3/FCI18003920 / M/b 2

DOA: 19/2/2018

23/11/18-

VNI

4/12/18-

Vehicle not in yet.

12/12/18 @

2.14pm revised to Sithara by email.

Kenneth confirmed 15 @ 1900, 3 days (Red @ 1673.92, 47%).

MV: @ 27K (est); CTA: @ 14479; NV: @ 17521.

ASS. REC. BY:

REF: 1-021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 9016R

Yr Regn:

11, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Airwave

c.c

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

93055

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GJI

1305761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

20/11/18

D.O.I.

10/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12

File pass to Catherine

RECEIVED 20 DEC 2018

Date/Time, File Pass to?

1) 20/12/18

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fixtures

Others

TOTAL

130

50

50+50

17

297

Report Format :

7P

Lump Sum / I.B.F. (\$

1900

MOTOR SURVEY ASSIGNMENT

Date	21-11-2018	Our Ref No. D18008269MFSH
Accident Date	20-11-2018	Claim Type. Third Party
Insured Vehicle	SHC0591A	Third Party Vehicle. SME9016R
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76	
Contact Person.	KENNY	
Contact No.	64538686/ 64538686	Fax No. 64596550
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 12 December 2018 2:14 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008269MFSH/1
Attachments: CSFCI18021105Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SME 9016R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 22 November 2018 9:50 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008269MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 22 November 2018 9:22 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008269MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008269MFSH

Date: 12 December 2018

Our Ref: CS/FCI18021105/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SME 9016R.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/12/2018 at the premises of M/s ALAN'S UNITED, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,528.80 .
Revised Estimate Amount	: S\$ 1,858.64 .
"Check" Items Amount	: S\$ 956.16 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front n/s rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5470H
Vehicle Details	
Vehicle No.:	SME9016R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5M A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L15A5207027
Chassis No.:	GJ11305761
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,299.00
Original Registration Date:	14 Nov 2008
First Registration Date:	14 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$15,299.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$14,479.00
Total Rebate Amount:	\$14,479.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Dec 2018

OK

Grab

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5105169592

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle

: **SME9016R**

Chassis Number

: GJ11305761

2. Name of Policyholder

: OW SENG YIP

3. Effective Date of Insurance

: 05 Nov 2018

4. Expiry Date of Insurance

: 04 Nov 2019

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use for the carriage of goods (other than samples) in connection with any trade or business.

(c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: S\$500
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: OW SENG YIP
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : SONA INSURANCE AGENCIES (00000573757)


Date of Issue : 02 Nov 2018 13:59 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05888

Vehicle Insured : SHC591A

Accident Date : 20-Nov-2018

Date : 21-Nov-2018

Our Ref : 218193 (FIRST) / CHAN

PAGE : 1

OW SENG YIP
18 PARRY ROAD
Singapore 547201

*Not Authorized
1/12/18
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR HONDA AIRWAVE SME9016R

1 pc N/s headlamp
1 pc Front bumper fascia
2 pcs Front bumper side retainer
1 pc Front bumper reinforcement
1 pc Front support panel

	CM	625.80	✓
	Bu	1,150.00	✓
@ S\$ 22.50	also	45.00	✓
		320.20	✓
	R	620.00	X
		2,761.00	
Less 20% :		552.20	

2,208.80

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To putty and spray replaced parts

600.00 400

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 ? 750

Total : S\$ 3,528.80

Singapore Dollars Three Thousand Five Hundred and Twenty Eight and Cents Eighty Only

3528.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHC591A (FIRST)

Accident Date : 20-11-2018

Date : 11-12-2018

Our Ref : 218193 / CHAN

OW SENG YIP

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR HONDA AIRWAVE SME9016R

1 PC N/S HEADLAMP LOWER BRACKET

	0.11	\$56.40	✓
LESS 20%		\$11.28	
		<u>\$45.12</u>	

Singapore Dollars Forty Five And Cents Twelve Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05888

Vehicle Insured : SHC591A

Accident Date : 20-Nov-2018

Date : 21-Nov-2018

Our Ref : 218193 (FIRST) / CHAN

PAGE : 1

OW SENG YIP
18 PARRY ROAD
Singapore 547201

*Not Authorized
1/2m 3?
Reservy After Paint*

ESTIMATED COST OF REPAIR FOR HONDA AIRWAVE SME9016R

1 pc N/s headlamp
1 pc Front bumper fascia
2 pcs Front bumper side retainer
1 pc Front bumper reinforcement
1 pc Front support panel

CM	625.80	✓
Bu	1,150.00	✓
@ S\$ 22.50	45.00	✓
B ₁	320.20	✓
R	620.00	X
	2,761.00	
Less 20% :	552.20	
	2,208.80	

*2118.50
423.30
1694.80
2,208.80*

218193

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To putty and spray replaced parts

600.00 *400*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 *750*

Total : S\$ 3,528.80

Singapore Dollars Three Thousand Five Hundred and Twenty Eight and Cents Eighty Only

*S.P 45.12
P 1694.80
L 670.00
2409.92
481.98
1927.94*

*4 sum
1900 ✓ ok
3 days
KENNEDY PLS Confirm
7128*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021105/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 591A	Veh. Inspected	SME 9016R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18008269MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	22/11/2018
2. Vehicle Particulars & Condition				
	Make & Model	HONDA AIRWAVE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GJ11305761	Colour	METALLIC GREY
	Odometer	93055	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	BRIDGESTONE	8 mm
	L/H Front Tyre	205/55 R16	BRIDGESTONE	8 mm
	R/H Rear Tyre	205/55 R16	BRIDGESTONE	8 mm
	L/H Rear Tyre	205/55 R16	BRIDGESTONE	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	20/11/2018	Inspection Date	10/12/2018
	Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 9016R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S HEADLAMP	CRACKED	625.80	625.80
1	FRONT BUMPER FASCIA	BUCKLED	1,150.00	1,150.00
2	FRONT BUMPER SIDE RETAINER @\$22.50	N/S DISTORTED	45.00	22.50
1	FRONT BUMPER REINFORCEMENT	BENT	320.20	320.20
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	620.00	-
1	N/S HEADLAMP LOWER BRACKET (ADDITIONAL)	DISTORTED	56.40	56.40
	LESS 20% DISCOUNT		-563.48	-434.98
			2,253.92	1,739.92
LABOUR				
	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM.		20.00	20.00
	TO PUTTY AND SPRAY REPLACED PARTS.		600.00	400.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		700.00	250.00
			1,320.00	670.00
GRAND TOTAL			3,573.92	2,409.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/FCI18021105/Kqd3n2

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,479.00=NETT VALUE: \$12,521.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.