

MING HUA AUTO SERVICES

160 Sin Ming Drive, #02-16, Singapore 575722

Tel: 6266 1605 / 9768 6328 // Fax: 6556 1015

Email: minghuaauto@yahoo.com.sg

Vehicle number: JHA9649

Vehicle Made & Model: PROTON WIRA

Qty	List Items	Amount \$
2	Front fenders - L/R @ 280 DD	280 560.00 /
2	Front fender lamps - L/R @ 22 CRA	22 44.00 /
1	Front bonnet NN	460.00 X
1	Front bonnet lock NN	85.00 X
2	Front bonnet hinges - L/R @ 30 NN	60.00 X
1	Front bumper DD	380.00 /
1	Front door - RH DD	686.00 /
1	Front door side mirror CRA	190 285.00 /
1	Front door glass CRA	246.00 /
1	Front door glass outer moulding DD	112.00 /
1	Front door glass run channel NN	135.00 X
1	Front door glass regulator BT	245.00 /
1	Front door glass regulator motor SVC	280.00 X
1	Front door outer handle R	112.00 X
1	Front door inner lock SVC	260.00 X
1	Front door inner board BT	340 445.00 /
1	Front door w/strip TN	122.00 /
1	Front door protector NEC	68 89.00 /
2	Front shock absorbers - L/R @ 286	572.00 X
2	Front lower arms @ 320	640.00 X
2	Front knuckle arms @ 315	630.00 X
2	Front wheel bearings @ 115	230.00 X
1	Front windscreen glass CRA	480.00 /
1	Front windscreen top moulding NEC	35.00 /
2	Front windscreen side mouldings - L/R @ 135 NEC	270.00 /
1	Front wiper panel garnish NN	132.00 X
1	Rear door - RH DD	686.00 /
1	Rear door protector NEC	68 72.00 /
1	Rear door outer handle CRA	95 112.00 /
1	Rear door glass run channel NN	135.00 X
1	Rear door glass regulator NN	245.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle number: JHA9649Vehicle Made & Model: PROTON WIRA

1	Rear door inner lock	SVC	
1	Rear door inner board	NN	
1	Rear fender	DD	
1	Rear bumper	DD	
1	Rear shock absorber - RH	}	NN
1	Rear lower arm		
1	Rear tailing arm		
1	Rear wheel hub bearing		
1	Rear windscreen moulding	NEC	
1	Centre pillar - RH	NN	

D.O.I - 22/11/18	
Estimate Received - 29/11/18	
L/s	
Huwa Jio (Lkk)	590
7 days	
	280.00 X
	445.00 X
	680.00 ✓
	380.00 ✓
	286.00 X
	195.00 X
	365.00 X
	255.00 X
	35.00 ✓
	445.00 X

Sub-total	12,211.00
Less 10%	1,221.10
Total List	10,989.90

Special Nett Items

1	Front sport rims - (L/R @ 300	DD	
1	Front tyres - (L/R @ 180	CUT	
1 set	Front windscreen sealant	NEC	
1 set	F/R door sticker	NEC	
1	Rear sport rim	NN	
1	Rear tyre	NN	
1 set	Rear windscreen sealant	NEC	

Total Special Nett 1,780.00

Labour charges

To remove, refix front & rear windscreen	240	300.00 ✓
Towing charges	50	120.00 ✓
To remove, refix front undercarriage	200	500.00 ✓
To remove, refix rear undercarriage		200.00 X
To check wheel alignment	60	120.00 ✓
To respray undercoating		150.00 X
To remove, refix front & rear interior trims to assist repair	100	180.00 ✓
To respray painting and etc	1200	1,800.00 ✓
Panel beating, cut, weld remove & replacing above parts	1400	1,800.00 ✓
Total Labour		5,170.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 17,939.90