

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0500/2018
DATE : 12-NOV-2018

INDIA INTERNATIONAL INSURANCE PTE LTD

DIRECT SETTLEMENT

S()
TEL :
FAX :

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

OWNER'S NAME : MS YAM WEI YING
ADDRESS : BLK 165 POH HUAT ROAD WEST
#05-15
S(546694)
TELEPHONE NO : 97868549

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

12/11/2018

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGN3298G
VEHICLE NO : SKW1552R
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2187943A
CHASSIS NO : SJNFEAJ11U1481936
MILEAGE : 1 KM
DATE IN : 12/11/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 24/10/2018

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1552R

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 REVERSE SENSOR(J11) ?	SENSOR-TE5140			180.00
2 SUNDRIES ?	NPN			50.00
3 ORNAMENT-BACK D X	90892-4EA0A	87.00		
4 EMBLEM-REAR X	90890-4EA0A	59.70		
5 CLIP(10X1.2) rec	01553-05933	12.00		
6 CANOE RIVET(2X6.5) rec	76882-0M000	13.00		
7 BRACKET-BUMPER RH X	85220-4EA0A	35.90		
8 BRACKET-BUMPER LH rec	85221-4EA0A	35.90		
9 CLIP(3X7.4) rec	85284-JD00A	22.20		
10 FASCIA-RR BUMP DE	85022-4EA0H	717.00		
SUB TOTAL		982.70	0.00	230.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		196.54	0.00	0.00
GRAND TOTAL		786.16	0.00	230.00
OVERALL TOTAL		1016.16		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW1552R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPAIR REAR TAILGATE, REAR END PANEL, RENEW REAR BUMPER COVER, RR Fender LH	1170.00	780
5	ZZ/002	S/PAINT REAR BUMPER COVER, REAR TAILGATE & REAR END PANEL, RR Fender LH	750.00	/
TOTAL LABOUR CHARGES			2250.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW1552R

TOTAL LABOUR CHARGES	2250.00
TOTAL SPARE PARTS CHARGES	1016.16
GRAND TOTAL	3266.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	RASUL - HP 90010068
SURVEYED DATE	:	03/01/19 @ 1625
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00 P/P
REMARKS	:	Resurvey by paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.