

Cecilin

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/3HR/0500/2018
DATE : 12-NOV-2018

INDIA INTERNATIONAL INSURANCE PTE LTD

S()

TEL :

FAX :

OWNER'S NAME : MS YAM WEI YING
ADDRESS : BLK 165 POH HUAT ROAD WEST
#05-15
S(546694)
TELEPHONE NO : 97868549

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGN3298G
VEHICLE NO : SKW1552R
MODEL CODE : FRLARBJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2187943A
CHASSIS NO : SJNFEAJ11U1481936
MILEAGE : 1 KM
DATE IN : 12/11/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 24/10/2018

12/11/2018

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1552R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR(J11) <i>7 X SVL</i>	SENSOR-TE5140			180.00
2	SUNDRIES <i>7. net</i>	NPN			30.00 20
3	ORNAMENT-BACK D <i>X NY</i>	90892-4EA0A	87.00		
4	EMBLEM-REAR <i>X NY</i>	90890-4EA0A	59.70		
5	CLIP(10X1.2) <i>net</i>	01553-05933	12.00		
6	CANOE RIVET(2X6.5) <i>net</i>	76882-0M000	13.00		
7	BRACKET-BUMPER RH <i>X SVL</i>	85220-4EA0A	35.90		
8	BRACKET-BUMPER LH <i>net</i>	85221-4EA0A	35.90		
9	CLIP(3X7.4) <i>net</i>	85284-JD00A	22.20		
10	FASCIA-RR BUMP <i>net</i>	85022-4EA0H	717.00		
SUB TOTAL			982.70	0.00	230.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			196.54	0.00	0.00
GRAND TOTAL			786.16	0.00	230.00
OVERALL TOTAL			1016.16		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW1552R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	X n n
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X n n
4	IZ/001	REPAIR REAR TAILGATE, REAR END PANEL, RENEW REAR BUMPER COVER, R/R FENDER LH	1170.00	780
5	IZ/002	S/PAINT REAR BUMPER COVER, REAR TAILGATE & REAR END PANEL. R/R FENDER LH	750.00	/
TOTAL LABOUR CHARGES			2250.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW1552R

TOTAL LABOUR CHARGES	2250.00
TOTAL SPARE PARTS CHARGES	1016.16
GRAND TOTAL	3266.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

RASUL - HP 90010068
03/01/19 @ 1625

0.00

5 days

0.00

P/P

Resurvey 64 paint

PLEASE NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0500/2018
DATE : 12-NOV-2018

DS $\Rightarrow$ Rasul

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

ZHR

OWNER'S NAME : MS YAM WEI YING
ADDRESS : BLK 165 POH HUAT ROAD WEST
#05-15
S(546694)
TELEPHONE NO : 97868549

Recommend Repair

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SGN3298G
VEHICLE NO : SKN1552R
MODEL CODE : PRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2187943A
CHASSIS NO : SJNFEAJ11U1481936
MILEAGE : 1 KM
DATE IN : 12/11/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 24/10/2018

5 Pays

LOR $\Rightarrow$ 90 x 5

$\Rightarrow$ 450 + GST

$\Rightarrow$ \$481.50

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TINAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW1552R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	ZZ/001	REPAIR REAR TAILGATE, REAR END PANEL, RENEW REAR BUMPER COVER	1170.00	780.00
5	ZZ/002	S/PAINT REAR BUMPER COVER, REAR TAILGATE & REAR END PANEL	750.00	750.00
TOTAL LABOUR CHARGES			2250.00	1640.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW1552R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR(J11)	SENSOR-TE5140			180.00 X
2	SUNDRIES	NPN			20.00 OK
3	ORNAMENT-BACK D	90892-4EA0A	87.00		X
4	EMBLEM-REAR	90890-4EA0A	59.70		X
5	CLIP(10X1.2)	01553-05933	12.00		OK
6	CANOE RIVET(2X6.5)	76882-0M000	13.00		OK
7	BRACKET-BUMPER RH	85220-4EA0A	35.90		X
8	BRACKET-BUMPER LH	85221-4EA0A	35.90		OK
9	CLIP(3X7.4)	85284-JD00A	22.20		OK
10	FASCIA-RR BUMP	85022-4EA0H	717.00		OK
SUB TOTAL			800.10	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			160.02	0.00	0.00
GRAND TOTAL			640.08	0.00	20.00
OVERALL TOTAL			660.08		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKW1552R

NETT ITEM	800.10
LESS 20.00%)	-160.02
NETT AMOUNT	640.08
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	1640.00
TOTAL SPARE PARTS CHARGES	660.08
TOTAL CHARGES	2300.08
ADD 7 % GST	161.01
GRAND TOTAL	2461.09