

22/03/2018

ASS. REC. BY:

REF:

CS / ALH 18021115 / Utbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Syazairdin

of

ALH

Date/Time:

22/11/2018 11:03am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 4860H

Insured:

SKT 205061

at Workshop m/s

Siong Hai

Tel:

6555 7272

of

Blk 1 Kaki Bukit Ave 6 #02-03

Policy No:

210044973

Claim No:

17203197056

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

22/11/2018 11:00am

Person Contacted:

Ahmad

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 4860H -x

SKT 205061 -x

lump sum \$3000 (Red: 11,137.57; 58%)

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 11/12 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$ 3000)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

250

20

270

RECEIVED 11 DEC 2018

- Pre repair inspection request - SLK4860H VS SKT2050G (OI) DOA: 21/11/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Abu Kassim, Noor Mariesa, Kaur, Baljit, Hor, Yinrul, Fan, Winnie-LW
Sent: 22/11/2018 11:03:38 AM

Hi,

Please refer to the enclosed request from **M/s Hin Tat Augustine & Partners**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Anil Kumar [mailto:anil@htapartners.com.sg]
Sent: Thursday, November 22, 2018 10:56 AM
To: Azlan, Syazairdina
Cc: Ruby Ong; Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Kaur, Baljit; Md Ishak, Mohd Imran; Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul; Fan, Winnie-LW
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT2050G AND SLK4860H ON 21/11/2018 -OUR REF: TCL.GCN.ro.50456.18.shm
Importance: High

WITHOUT PREJUDICE
Save As To Cost

Dear Azlan,

We refer to your email dated even date.

Our client is agreeable to use Marcus Chua from M/s LKK Auto Consultants Pte Ltd from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SLK4860H as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : SIONG HAI MOTOR & TRADING
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Mr Ah Huat (tel: 65557272)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: Azlan, Syazairdina <Syazairdina.Azlan@aig.com>
Sent: Thursday, November 22, 2018 9:46 AM
To: Ruby Ong <ruby@htapartners.com.sg>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT2050G AND SLK4860H ON 21/11/2018

This is a secure, encrypted message. To read it, open the attachment.

這是安全加密信息。如要閱讀此信息，請開啟附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสไว้ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-11-29 09:47 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina Azlan@aig.com

To: ruby@htapartners.com.sg, ShengYang.Lim@aig.com, NoorMarisa.AbuKassim@aig.com, Baljit.Kaur@aig.com, Imran.Ishak@aig.com

Cc: Andy-SY.Fong@aig.com, Lee-

Ying.Chin@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, NoorMarisa.AbuKassim@aig.com, Baljit.Kaur@aig.com, Yin LW.Fan@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKT2050G AND SLK4860H ON 21/11/2018

Date: Thu, 22 Nov 2018 01:46:00 +0000

Without Prejudice

Your Reference : TCL.GCN.ro.50456.18.shm
Our Reference : SKT2050G

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: Wednesday, November 21, 2018 4:17 PM

To: Lim, Sheng Yang; Abu Kassim, Noor Marisa; Kaur, Baljit; Md Ishak, Mohd Imran; Azlan, Syazairdina

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLK 4860H [OUR REF. TCL.GCN.RO.50456.18.SHM]

Importance: High

Your ref: SKT 2050G
Our ref: TCL.GCN.ro.50456.18.shm

WITHOUT PREJUDICE

21 November 2018

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#07-16 AIG Building

By Email Only

Singapore 079120

VERY URGENT

Dear Sirs

CLAIMANT: AMV PTE LTD

ACCIDENT INVOLVING SLK 4860H, SKT 2050G & SJS 5282B ALONG SLIP ROAD OF NAPIER ROAD ONTO TANGLIN ROAD ON 21 NOVEMBER 2018 @ 1225HRS

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 21 November 2018 at about 1225hrs along slip road of Napier Road onto Tanglin Road involving our client's vehicle registration number SLK4860H and vehicle registration number SKT2050G driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 17:33
Date Of Accident	21/11/2018 12:25
Exact Location Of Accident	TANGLIN ROAD SLIP ROAD AFTER NAPIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK4860H
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8S AT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087569127-01 CLASSIC
Cover Note Number	

Driver

Name of Driver	ALFAN FADHLAN BIN YA'AKOP
NRIC No	S9110858E
Date Of Birth	27/03/1991
Occupation	OUTDOOR
Date Of Driving Pass	23/05/2014
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83883525
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 250 YISHUN AVENUE 9 #02-207
Postcode	760250
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT2050G
Vehicle Make/Model/Colour	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KHOO PECK-LI
NRIC/Passport Number	S7516076C
Contact Number	98166254
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJS5282B
Vehicle Make/Model/Colour	HONDA ODYSSEY 2.4 EX-S CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21 NOV 2018

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: va-kb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS TRAVELLING FROM NADIER RD ENTERING TANGLIN RD VIA SLIP ROAD WHERE THE ACCIDENT HAPPENED ON 21 NOV 2018 AT 1225 HRS. CAR (C) CAME TO A STOP AND I MANAGED TO STOP IN TIME. THEN SUDDENLY CAR (B) HIT ME BEHIND CAUSING ME TO JERK IN FRONT AND HIT CAR (C). BUT CAR (C) DROVE OFF.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

G.A94NC SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

21 NOV 2018

IOAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5825Z
Vehicle Details	
Vehicle No.:	SLK4860H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8S AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ZR6842048
Chassis No.:	ZVW506043506
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,089.00
Original Registration Date:	18 Jan 2017
First Registration Date:	18 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$43,198.00
Total Rebate Amount:	\$46,948.00

The information contained herein is correct as at 23 Nov 2018

OK

SIONG HAI MOTOR AND TRADING

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

Fax: 67411019

H/P: 93365311 (Ah Huat)

Vehicle No: SLK4860H

Model: TOYOTA PRIUS

Not Authorized
Rate
H/S 8000/2
22/1/18
When full the 12 pm
6 day.

QTY	List Items	Price \$
1	Front bonnet	11 853.60 X
1	Front bonnet lock	11 130.00 X
1	Front support panel	11 1431.20 X
1	Front support stand panel	11 151.60 X
1	Front support panel top garnish	11 127.80 X
1	Air-con air dust	11 117.80 X
1	Air-con condenser garnish centre	11 129.10 X
2	Air-con condenser garnish L/R	11 180.40 X
1	Front number plate garnish	11 85.80
1	Front bumper	11 1394.40
1	Front bumper reinforcement	11 691.50
1	Front bumper sponge	11 126.80
1	Front bumper top grill	11 159.80
1	Front bumper lower grill	11 168.60 X
1	Front bumper top grill EMBLEM	11 85.30
1	Front bumper towing cover	11 42.60 X
2	Front L/R bumper retainers (1) 104.2	11 208.40
2	Front headlamp L/R (1) 2869.8	11 5739.60 X
1	Rear bootlid inner board	11 249.30 X
1	Rear bootlid inner lock	11 337.50
1	Rear bootlid rubber	11 190.30
1	Rear bootlid number plate garnish	11 882.70 X
1	Rear bootlid EMBLEM	11 89.60
1	Rear L/H top taillamp	11 433.90
1	Rear L/H lower taillamp	11 487.60
1	Rear end panel	11 566.90
1	Rear end panel inner board	11 161.60 X
1	Rear end panel sensor	11 172.80 X
1	Rear end panel top garnish	11 105.50
1	Rear bumper	11 1674.70
1	Rear bumper reinforcement	11 381.90
1	Rear bumper towing cover	11 42.60 X
2	Rear L/R bumper retainers (1) 137.2	11 274.40
1	Rear lower bumper centre	11 552.60
2	Rear L/R lower bumper corner (1) 187.6	11 375.20 X
1	Rear spare tyre top cover	11 504.90 X
1	Rear spare tyre tools sponge	11 441.30
2	Rear L/R bumper reflector (1) 86.9	11 173.80 X

Total \$ 19,923.40
Less 25% \$ 4,980.85

9825.95
7369.46

<u>Special Nett Items</u>	
1 set	Rear bumper reverse sensor
1	Rear bumper clip
1	Rear end panel board clip
1	Front bumper clip
1	Front panel garnish
1	Front bonnet shield clip
1	Front number plate with box

<u>Price \$</u>	
shwd	350.00 200
ner	60.00 ✓
17	45.00 x
ner	60.00 —
NN	75.00 X
NN	45.00 x
2el	80.00 40

\$ 715.00

Labour Cost

To remove,refix front and rear damaged lamps and
check electrical wiring reset
To remove and refix chamber,reverse sensor
To apply undercoating on accident parts
To respray painting
Panel beating,workmanship,remove and replacing
above parts

180 30
150.00 50
250.00 50
1500.00 1280
1400.00 900

\$ 3,480.00

2670

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 19,137.55 10039.46
8031.57

Auto Consultants hence notify
the Repairer of the following:
• Resurvey before/after spray painting
• To spray damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18021115/UTBN2

Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100414973
 Claimant Vehicle No: SLK4860H Insured Vehicle No: SKT2050G
 Date of Loss: 21/11/2018 Nature of Claim: TP Claim No: 1712031970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK4860H
 Make & Model: TOYOTA PRIUS, 1.5 HYBRID (A) Engine No: 2ZR6842048
 Reg. Date: 18/01/2017 (Man. Year: 2016) Chassis No: ZVW506043506
 Colour: Black Odometer: 161202 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Price:
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: CHAO YANG 6 mm Rear Left Side: CHAO YANG 6 mm
 Front Right Side: CHAO YANG 6 mm Rear Right Side: CHAO YANG 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,657.55	7,729.46	7,928.09	50.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,310.00	1,170.00	33.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,137.55	10,039.46	9,098.09	47.54
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	19,137.55	8,000.00	11,137.55	58.20

INSPECTION

Date of Assignment: 22/11/2018
 Date Inspected: 22/11/2018 Inspected At: Siong Hai Motor & Trading (HQ)
 NO 1 KAKI BUKIT AVE 6, #02-03
 AUTOBAY @ KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	853.60 FL	*- FL
2	1		*FRONT BONNET LOCK	Not Necessary	130.00 FL	*- FL
3	1		*FRONT SUPPORT PANEL	Repair	1,431.20 FL	*- FL
4	1		*FRONT SUPPORT STAND PANEL	Not Necessary	151.60 FL	*- FL
5	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	127.80 FL	*- FL
6	1		*AIR-CON AIR DUST	Not Necessary	117.80 FL	*- FL
7	1		*AIR-CON CONDENSER GARNISH CENTRE	Not Necessary	129.10 FL	*- FL
8	2		*AIR-CON CONDENSER GARNISH L/R	Not Necessary	180.40 FL	*- FL
9	1		*FRONT NUMBER PLATE GARNISH	Torn	85.80 FL	*85.80 FL
10	1		*FRONT BUMPER	Dented/Deformed	1,394.40 FL	*1,394.40 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	691.50 FL	*691.50 FL
12	1		*FRONT BUMPER SPONGE	Cracked	126.80 FL	*126.80 FL
13	1		*FRONT BUMPER TOP GRILL	Twisted	159.80 FL	*159.80 FL
14	1		*FRONT BUMPER LOWER GRILL	Not Necessary	168.60 FL	*- FL
15	1		*FRONT BUMPER TOP GRILL EMBLEM	Scratched	85.30 FL	*85.30 FL
16	1		*FRONT BUMPER TOWING COVER	Not Necessary	42.60 FL	*- FL
17	2		*FRONT L/R BUMPER RETAINERS	Bent	208.40 FL	*208.40 FL
18	1		*FRONT HEADLAMP L/R	N/s Cracked	5,739.60 FL	*2,531.35 FL
19	1		*REAR BOOTLID INNER BOARD	Not Necessary	249.30 FL	*- FL
20	1		*REAR BOOTLID INNER LOCK	Bent/Shorted	337.50 FL	*337.50 FL
21	1		*REAR BOOTLID RUBBER	Twisted	190.30 FL	*190.30 FL
22	1		*REAR BOOTLID NUMBER PLATE GARNISH	Repair	882.70 FL	*- FL
23	1		*REAR BOOTLID EMBLEM	Necessary	89.60 FL	*89.60 FL
24	1		*REAR L/H TOP TAILLAMP	Cracked	433.90 FL	*433.90 FL
25	1		*REAR L/H LOWER TAILLAMP	Cracked	487.60 FL	*487.60 FL
26	1		*REAR END PANEL	Dented	566.90 FL	*566.90 FL
27	1		*REAR END PANEL INNER BOARD	Not Necessary	161.60 FL	*- FL
28	1		*REAR END PANEL SENSOR	Not Necessary	172.80 FL	*- FL
29	1		*REAR END PANEL TOP GARNISH	Twisted	105.50 FL	*105.50 FL
30	1		*REAR BUMPER	Dented/Deformed	1,674.70 FL	*681.10 FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	381.90 FL	*381.90 FL
32	1		*REAR BUMPER TOWING COVER	Not Necessary	42.60 FL	*- FL
33	2		*REAR L/R BUMPER RETAINERS	Bent	274.40 FL	*274.40 FL
34	1		*REAR LOWER BUMPER CENTRE	Deformed	552.60 FL	*552.60 FL
35	2		*REAR L/R LOWER BUMPER CORNER	Not Necessary	375.20 FL	*- FL
36	1		*REAR SPARE TYRE TOP COVER	Not Necessary	504.90 FL	*- FL
37	1		*REAR SPARE TYRE TOOLS SPONGE	Torn	441.30 FL	*441.30 FL
38	2		*REAR L/R BUMPER REFLECTOR	Not fitted	173.80 FL	*- FL
39	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
40	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
41	1		*REAR END PANEL BOARD CLIP	Not Necessary	45.00 FS	*- FS
42	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*60.00 FS
43	1		*FRONT PANEL GARNISH	Not Necessary	75.00 FS	*- FS
44	1		*FRONT BONNET SHIELD CLIP	Not Necessary	45.00 FS	*- FS
45	1		*FRONT NUMBER PLATE WITH BOX	Bent	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,638.40	10,185.95
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,980.85	2,456.49
Total Parts (\$\$)	15,657.55	7,729.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIX FRONT AND REAR DAMAGED LAMPS AND CHECK ELECTRICAL WIRING RESET	New	180.00	30.00
2	TO REMOVE AND REFIX CHAMBER,REVERSE SENSOR	New	150.00	50.00
3	TO APPLY UNDERCOATING ON ACCIDENT PARTS	New	250.00	50.00
4	TO RESPRAY PAINTING	New	1,500.00	1,280.00
5	PANEL BEATING,WORKMANSHIP,REMOVE AND REPLACING ABOVE PARTS	New	1,400.00	900.00
Gross Labour Cost (S\$)			3,480.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >