

ASS. REC. BY:

REF:

CS/TP18021126/Ktbnz

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SHC5307X Yr Regn: 8 2006Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Toy Crown C.C. 2986Colour: White / Rv A/C. Insured / Std / NI / NASp. Reading 1 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LXS12- 0026134Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Mil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FalkenFront 6 mm Rear 6 mmR/Bal. 6 mm L/Bal. 6 mmL/Bal. 6 mm D.O.A. 26/3/2003D.O.A. 26/3/2003

Survey held at _____

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 5307X - NTA / INCO9 001432 / JI No Recurvey Date: 28/11/2018
	Lump Sum \$5000. Cred: 16569.13% (76%), 9 days.
	RECEIVED 23 NOV 2018
	Submit invoice first then report.

Date/Time, File Pass to?

Date/Time, File Return to?

- 1) _____ 2) _____
 3) _____ 4) _____
 5) _____ 5) _____

Frell. Report:

Civil Report:

TOTAL
LOSSKIV FOR
LOD

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date: 11/15/165

170 + 165

50

27

80

492

Catherine Chong (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 15 November, 2018 2:19 PM
To: 'Janice Lee (LKKAuto)'
Cc: assignments@lkkauto.com; 'Kenneth Kong (LKKAuto)'
Subject: FW: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along jurong west Ave 2
Attachments: AAD1303-292.pdf; AAD1303-292 - ESTIMATE MARKING.pdf; SHC5807X 22.03.2013 - GIA.pdf

Hi Janice

31/8/2006

Refer to tele-conversation this morning, please provide us the survey invoice for us to prepare the payment.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

DAI
26/3/13

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Wednesday, 14 November, 2018 4:58 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; assignments <assignments@lkkauto.com>; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: FW: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along jurong west Ave 2

Dear Wai Yin,
Thank you for your email.

Dear All,
Kindly assist to check if there is any

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Wednesday, November 14, 2018 4:50 PM
To: Janice Lee (LKKAUTO)
Subject: RE: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along Jurong West Ave 2
Attachments: AAD1303-292.pdf; AAD1303-292 - ESTIMATE MARKING.pdf

Hi Janice

According to our record, Kenneth done the survey on 26.03.13.

We enclosed the estimate marking for your easy reference.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Saturday, 10 November, 2018 12:24 PM
To: claims <claims@transcab.com.sg>
Subject: RE: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along Jurong West Ave 2

Dear Wai Yin,

No record found on our side. Please check again.

Thank you.

Best Regards,
Jannice Lee (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims [<mailto:claims@transcab.com.sg>]
Sent: Friday, November 09, 2018 5:59 PM
To: SUR <sur@lkkauto.com>
Cc: claims@transcab.com.sg
Subject: RE: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along jurong west Ave 2

WITHOUT PREJUDICE

Dear Sir/ Madam

Please refer to the above mention case.

Kindly forward a copy of the survey report to India Insurance, enclosed the GIA report for your easy reference.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Manivel Priyadarshini [<mailto:manivel@iii.com.sg>]
Sent: Thursday, 8 November, 2018 10:20 AM
To: 'claims' <claims@transcab.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>
Subject: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along jurong west Ave 2

Dear Jasmine,

We refer to the above accident,

Please forward survey report/damage photos for our perusal.

Thank You
With Regard's
Priya Manivel

Motor Claims Department
India International Insurance Pte Ltd
Tel : 63476100, Ext-284
Email : manivel@iii.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 23 November 2018 11:44 AM
To: Denise Tay (LKKAUTO); Janice Lee (LKKAUTO)
Cc: SUR; Kenneth Kong (LKKAUTO); assignments
Subject: RE: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along Jurong West Ave 2

WITHOUT PREJUDICE

Dear Denise

We confirmed amount \$5000 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 22 November, 2018 3:39 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: India ref: MCT13030763/001/MP-Your ref: AAD1303-292-Accident involving SHC2155M & SHC5807X on 22.03.18 along Jurong West Ave 2

Dear Wai Yin,

As spoken, repair cost at lump sum \$5000/-.

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Video Recording
Trans-Cab Auto Services Pte Ltd
58 Defu Lane 1
Singapore 539498
Co./ GST Reg. No.: 201019626G

Case Handle by: Andreo
A&D No.: 1303-292

Notification of Accident

<input checked="" type="checkbox"/> TOYOTA CROWN	<input type="checkbox"/> TOYOTA WISH 1.8	<input type="checkbox"/> TOYOTA WISH 2.0	<input type="checkbox"/> MERCEDES BENZ	<input type="checkbox"/> CHEVROLET EPICA
Taxi Registration Number : SHB/C D <u>5807X</u>		Claim Against: <u>III</u>		
Third Party Vehicle Number : <u>SHC2155M</u>				
Date and Time of Accident : <u>22/03/13 0605</u>		Surveyor: <u>Kenneth 26 MAR 2013</u>		
Location : <u>Jurong West Ave 4 X Jurong West St 75</u>				
Accident by Hirer / Relief : <u>Yeo Hiap Soon</u>				
NRIC No. : <u>S1265305J</u>		Reported on: <u>25 MAR 2013</u>		
Estimated no. of repair days : <u>8</u> days		AL Doc. No. <u>(towed to TP)</u>		
Date / Time In: <u>22/03/13 0605</u>		NAV updated Yes / No <u>Yes</u>		
Date / Time Out: <u>23 APR 2013 1400h</u>		NAV updated Yes / No <u>Yes</u>		
Any outstanding Rental		Yes / No <u>No</u>		
Any outstanding Accident Liabilities		Yes / No <u>No</u>		
Any outstanding Deposit		Yes / No <u>No</u>		
Release Vehicle		Yes / No <u>Yes</u>		

If your answer is **YES** for Outstanding and release vehicle, please provide your remark:

Please put a tick [✓] for the item which is applicable:

- Advanced Payment Yes / No
- [✓] 100% against third party. **KIV loss of earnings for 6 months.**
- [] 50% / 50% against third party. **Excess is applicable.**
- [] Fully at fault. **Excess is applicable.**
- [] Late Report. **Excess is applicable.**
- [] Mutual Settlement. Remark _____
- [] No repair / self repaired. Driver claimed no involvement / not at fault.
- [] Windscreen damaged.
- [] Excess is applicable due to resigned.

ACE	
ACE	
ACE	

ACE	
-----	--

Declaration

I, _____ bearing NRIC no. _____ (Hirer / Relief) confirmed no injury sustained pertaining to the above accident.

The above was clearly explained and accepted by me.

Hirer/Relief : _____
(Signature and Date) Use own lawyer to claim for injury
KLOE

No. 58 Defu Lane 1, Singapore 539498
Tel: 6287 6666 Fax: 6281 1400

LOD Submission Date:	_____
DV Received Date:	_____
Invoice No.:	_____
Cheque Received Date:	_____
Completion Date:	_____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/03/2013 13:49
Date Of Accident	22/03/2013 06:05
Exact Location Of Accident	JURONG WEST AVENUE 4 X JURONG WEST STREET 75

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC5807X
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Vehicle Particulars	
Manufacturer	TOYOTA
Model	CROWN-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi
Insurance Company	
Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH
Cover Note Number	
Driver	
Name of Driver	YEO HIAP SOON
NRIC No	S1265305J
Date Of Birth	03/02/1957
Occupation	Outdoor
Date Of Driving Pass	04/07/1977
Driving Experience	35 Years And 8 Months
Gender	Male
Mobile Number	(Local) +65-84545545
Fax Number	
Contact Number	
Email Address	NOEMAIL
Address	BLK 217 JURONG EAST STREET 21
	#05-551
Postcode	600217
Was driver an employee of the Insured's Company	No

If No, Relationship of the Driver with the Insured Other - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident Collision- Cross Junction

Weather Conditions Clear

Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? Yes

Was any other material or property damaged? Yes

Was there any video captured by Car Camera? Yes

Details of Police Action

Was the accident reported to the police? Yes

If Yes, Please state which Police Station

Police Station Name Jurong East Neighbourhood Police Centre

Police Station Address ROAD: No. 92 Boon Lay Way . POSTCODE: 609962 , COUNTRY: Singapore

Police Station Contact TEL NO: 1800-8999999 - FAX NO: 66655791

Was notice of intended Prosecution given? No

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20130323/4100

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC2155M

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name YEO HIAP SOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5807X

Were seat belts worn?

Was injured conveyed to hospital by ambulance? Yes

Address



Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

as Attached.

Describe Circumstances of the Accident

Please refer to Police Report.

Declaration


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan #2 Pg.1





TRAFFIC POLICE
AMENDMENT

Traffic Police Department
Charge Office
10 Ubi Avenue 3
Singapore 408865

NP 168 No.	: F/20130323/4100	Name	: Yeo Hiap Soon
Accident Date/Time	: 22/03/13 @ 0605 hrs	Address	: Blk 217 Jurong East Street 21 #05-551 S(600217)
Vehicle(s) Involved	: SHC2155M SHC5807X	NRIC No	: S1265305J
		Tel No	: 84545545
		Date	: 25/03/2013

Dear Sir / Madam


Accident involving SHC2155M and SHC5807X
along Junctions of Jurong West Avenue 4 on 22/03/2013 at 0605 hours

With reference to the above, I have on 23/03/2013 (date) 2054 hours (time) make a police report at Jurong East Neighbourhood Police Centre (Police Station/NPP/NPC)
In NP 168 – T/20130323/4100

On 25/03/2013 (date), 1412 hours (time) at Hougang Neighbourhood Police Post (Police Station/NPP/NPC), I make the following amendments to the above report;
I would like to make an amendments that the actual accident location was along junction of Jurong West Avenue 4 towards Jurong West Avenue 4 instead of Jurong West Avenue 2 Towards Jurong West Avenue 4.


That's All.

Yours Faithfully,


(Signature)

FOR OFFICIAL USE

If a police officer recorded these amendments, please complete the following.

Name / Rank No	: Cpl T09287 Muhammad Ashiek
Date and Time	: 25/03/2013 at 1412 hrs
Station Dairy No	: 5
Signature	

Sketch Plan #4 Pg.1

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20130323/4100

1 of 3

Report No. T/20130323/4100

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/03/2013 20:54		Vide Report No.:		Station Diary No.: 45	
Informant's Particulars					
Name of Informant: YEO HIAP SOON			Address: APT BLK 217 JURONG EAST STREET 21 #05-551 SINGAPORE 600217		
ID Type / ID No.: NRIC NO / S1265305J			Contact No.: Home/Office: Mobile/Pager: 84545545		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 03/02/1957	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/03/2013 06:05	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 JURONG WEST AVENUE 2 JURONG WEST STREET 64 Junction of Jurong West Ave 2 and Jurong West St 64				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Color	Condition	No of Passenger	Insurance Company	Insurance No	Effective Date	Expiry Date
SHC2155 M	Car	HYUND AI	BLUE	Slightly Damaged	0				
SHC5807 X	Car	TOYOTA	RED	Slightly Damaged	0				

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #5 Pg.1

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20130323/4100

2 of 3

Report No. T/20130323/4100

CONTINUATION OF REPORT

Driver			
Name	YEO HIAP SOON	ID No.	S1265305J
Related Vehicle	SHC5807X (Car)	Contact No.	84545545
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	22/03/2013	Date Discharge	23/03/2013
No. of Days granted Medical Leave (MC)	10	Degree of Injury	Slight
Driver			
Name	Unknown Driver	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

Brief Details. This report shall be signed by the informant.

On 22/03/2013 at about 0605hrs, I was driving my taxi (registration No. SHC5807X, Transcab, Toyota red in colour) along Jurong West Ave2 going towards Jurong West Ave 4. While approaching the junction of Jurong West Ave 2 and Jurong West St 64, the traffic light was green. The traffic was not heavy and it was not raining at the point of time. While driving straight at the junction, my taxi had hit onto another taxi (registration No. SHC2155M, Comfort taxi, Hyundai blue in colour) which was turning right all of a sudden towards Jurong West St 64.

After the accident, I then called the ambulance which arrived shortly and was conveyed to NUH. I was admitted to the hospital for one day and was discharged on 23/03/2013. There was pain on my chest area, on my back and also pain on both of my arm. I did not managed to exchanged particulars with the other party as I was conveyed to NUH. I did not access the damage on both taxi as I was injured at the point of time. I wish to state that the traffic light was green and the traffic was at my favor. I wish to state that the whole accident was recorded by a video camera installed in my taxi. There were no passenger inside my taxi.

Sketch Plan #6 Pg.1

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999



T/20130323/4100

3 of 3

Report No. T/20130323/4100

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D
MD FARIHIN BIN JALALUDDIN

Signature Of Informant:

[Handwritten signature]

Signature Of Interpreter:

[Handwritten signature]

Date:

23/03/2013 20:54


Officer In Charge Of Case:

TP /

Contact No.:

Classification Of Case:

Authentication Stamp
NP168



SN 036

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



28-MAR-2013 09:47

P. 03

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6668 FAX NO.6281 1400
 CO/GST REG NO.201010626G
 SHC5807X - INDIA

Not Attached
1/1mp & ?

Andrea

\$11,200.00

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5807X - Andrea
 LXS12-00026134*
 TOYOTA
 CROWN TAXI
 22.03.2013
 INDIA

5000

PART		LIST	
1	1	Front Bumper Assembly	\$ <i>BT</i> 417.40 ✓
2	1	Front Bumper Reinforcement / Beam	\$ <i>BT</i> 269.35 ✓
3	1	Front Bumper Centre Absorber Foam	\$ <i>Tn</i> 125.00 ✓
4	1	Front Bumper Centre Bracket	\$ <i>BT</i> 15.50 ✓
5	1	Front Bumper Spot Lamp Garnish RH	\$ <i>Sub</i> 50.49 X
6	1	Front Bumper Spot Lamp Garnish LH	\$ <i>Mis</i> 50.49 ✓
7	1	Front Tow Hook Bracket	\$ <i>R</i> 88.00 X
8	1	Bonnet	\$ <i>Buc</i> 849.31 ✓
9	1	Bonnet Under Weatherstrip Seal	\$ <i>Tn</i> 59.99 ✓
10	1	Bonnet Hinge RH	\$ <i>R</i> 44.63 X
11	1	Bonnet Hinge LH	\$ <i>Ois</i> 44.63 ✓
12	1	Bonnet Moulding	\$ <i>CM</i> 161.97 ✓
13	1	Bonnet Lock	\$ <i>BT</i> 75.02 ✓
14	1	Bonnet Insulator	\$ <i>CM</i> 436.72 <i>50851-21836</i>
15	1	Front Headlamp RH	\$ <i>Br</i> 411.54 ✓
16	1	Front Headlamp LH	\$ <i>Br</i> 411.54 ✓
17	1	Front Side Lamp RH	\$ <i>Br</i> 170.60 ✓
18	1	Front Side Lamp LH	\$ <i>Br</i> 170.60 ✓
19	1	Front Support Panel Assy	\$ <i>BT</i> 626.30 ✓
20	1	Front Brace Panel	\$ <i>BT</i> 79.57 ✓
21	1	Front Fender RH	\$ <i>Buz</i> 732.83 ✓
22	1	Front Fender Inner Cowling RH	\$ <i>CM</i> 112.20 ✓
23	1	Front Fender Indicator Lamp RH	\$ <i>Sn</i> 42.06 X
24	1	Front Fender Inner Wheel House Panel RH	\$ <i>R</i> 595.72 X
25	1	Front Fender LH	\$ <i>BT</i> 732.83 ✓
26	1	Front Fender Inner Cowling LH	\$ <i>Tn</i> 112.20 ✓
28	1	Front Fender Indicator Lamp LH	\$ <i>Sn</i> 42.06 X
29	1	Front Fender Inner Wheel House Panel LH	\$ <i>BT</i> 595.72 ✓
30	1	Radiator Assembly	\$ <i>BT/Pn</i> 1,890.20 ✓
31	1	Radiator Fan Blade	\$ <i>Br</i> 186.62 ✓
32	1	Fan Clutch	\$ <i>Tn</i> 642.98 ✓
33	1	Radiator Cowling	\$ <i>CM</i> 184.77 ✓
34	1	Radiator Grille	\$ <i>Mis</i> 392.16 ✓

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGAI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6281 1400
 CO/GST REG NO.201019626G
 SHC5807X - INDIA

Andrea

35	1	Aircon Condenser	\$	Btl/Pvc 1,098.16 ✓
36	1	Aircon Receiver Drier	\$	DJ 143.00 ✓
37	1	Air Cleaner Assembly	\$	Bt 548.92 ✓
38	1	Air Filter	\$	Sn 30.00 X
39	1	Air-Cleaner Intake Duct	\$	DJ 84.64 ✓
40	1	Air-Cleaner Intake Duct Hose (Top)	\$	DJ 61.83 ✓
41	1	Air-Cleaner Intake Hose	\$	Sn 166.18 X
42	1	Air Intake Resonator Top (Square)	\$	CM 132.63 ✓
43	1	Air Resonator Tank Top Bracket	\$	R 28.00 X
44	1	Windscreen Washer Tank - Filler Neck	\$	DJ 80.42 ✓
45	1	Windscreen Washer Tank	\$	CM 48.06 ✓
46	1	Windscreen Washer Tank Motor	\$	Sn 204.62 X
47	1	Front Fuse Box - Top Cover	\$	Sn 93.01 X
48	1	Front Fuse Box Lower Cover	\$	CM 191.37 ✓
49	1	Front Fuse Box Centre Junction	\$	CM 367.17 ✓
50	1	Front Fuse Box Centre Cover	\$	DJ 22.68 ✓
51	1	Front Windscreen Glass	\$	CM 996.40 ✓
52	1	Front Windscreen Moulding	\$	Nu 113.98 ✓
53	1	Front Lower Arm RH	\$	Nu X 517.14 ?
54	1	Front Lower Arm LH	\$	Nu X 517.14 ?

	\$	16,266.35
25%	\$	4,066.59
TOTAL	\$	12,199.76

Spectcal Nett

1 Set	Front Bumper Fastener Clip	\$	Nu 12.00 ✓
1	Front Licence Plate	\$	Bt 35.00 20Sn ✓
2	Bonnet Stopper	\$	M1 10.00 ✓
1 Set	Bonnet Under Weatherstrip Seal Clips	\$	Nu 10.00 ✓
6ps	Bonnet Insulator Clip	\$	Nu 12.00 ✓
1 Set	Front Fender Inner Cowling Clip RH	\$	Nu 40.00 ✓
1 Set	Front Fender Inner Cowling Clip LH	\$	Nu 40.00 ✓
2 Can	Radiator Coolant	\$	Nu 40.00 20Sn ✓
1 Set	Radiator Grille Clips	\$	Nu 10.00 ✓
2	Radiator Top Mounting Bracket	\$	DJ 15.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6281 1400

CO/GST REG NO.201019626G

SHC5807X - INDIA

Andrea

2	Radiator Lower Mounting Bushing	\$	Nu 18.00 ✓
2	Aircon Condenser Bracket	\$	R 30.00 X
2	Aircon Condenser Top Mounting	\$	Sh 15.80 X
1	Battery	\$	Nu 200.00 5081N
1	Battery Tray	\$	R 91.23 X
1	Battery Fastener Bracket	\$	BM 27.55 —
1	Battery Fastener Bolt	\$	R 12.79 X
2	Front Windscreen Sealant	\$	Nu 80.00 405N —
1	Front Windscreen Inner Seal	\$	Nu 60.00 305N —
3 /	ERP Sticker	\$	Nu 10.00 —
TOTAL		\$	<u>769.37</u>

TOTAL PARTS \$ 12,969.13

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And Renewal
Of Parts, Adjust And Realign The Same

\$ 3,500.00 1200

To Rust-Proofing Of The Affected Areas.

\$ 200.00 180

To Check Electrical Lighting Concerned.

\$ 100.00 40

Putty And Spray Painting Of The Affected
Portion.

\$ 2,200.00 1080

To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, To
Enable repair.

\$ Nu 250.00 X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ Nu 300.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6281 1400
 CO/GST REG NO.201019626G
SHC5807X - INDIA

Andrea

To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	150.00 X
To Replace, Refix And Top Up Coolant For Radiator	\$	150.00 50%
Towing Fees.	\$	100.00 50%
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	350.00 100%
To Dismantle And Refit Front Undercarriage Parts, Final Checking And Testing.	\$	350.00 200%
Labour Charge To Mount And Dismount Vehicle On Jig Bench, To Facilitate Repair.	\$	350.00 250%
To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	150.00 120%
To Reseal Sealant On Gap	\$	100.00 50%
To Pull And Jack Out Chassis Frame And Correct It To Symmetrical position With The Aid Of Hydraulic Pneumatic Jack.	\$	350.00 X

TOTAL \$ 8,600.00

Over All Total \$ 21,569.13

Total Repair Days 14 Days
9 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP18021126/Ktbn2

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 04-12-2018



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHC 5807X
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	26/03/2013

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CROWN	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	LXS120026134	Colour	WHITE / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FALKEN	6 mm
L/H Front Tyre	185/60 R15	FALKEN	6 mm
R/H Rear Tyre	185/60 R15	FALKEN	6 mm
L/H Rear Tyre	185/60 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/03/2013	Inspection Date	26/03/2013
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5807X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSEMBLY	BENT	417.40	417.40
1	FRONT BUMPER REINFORCEMENT/BEAM	BENT	269.35	269.35
1	FRONT BUMPER CENTRE ABSORBER FOAM	TORN	125.00	125.00
1	FRONT BUMPER CENTRE BRACKET	BENT	15.50	15.50
1	FRONT BUMPER SPOT LAMP GARNISH RH	SERVICEABLE	50.49	-
1	FRONT BUMPER SPOT LAMP GARNISH LH	MISSING	50.49	50.49
1	FRONT TOW HOOK BRACKET	TO REPAIR SEE LABOUR	88.00	-
1	BONNET	BUCKLED	849.31	849.31
1	BONNET UNDER WEATHERSTRIP SEAL	TORN	59.99	59.99
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	44.63	-
1	BONNET HINGE LH	DISTORTED	44.63	44.63
1	BONNET MOULDING	CRACKED	161.97	161.97
1	BONNET LOCK	BENT	75.02	75.02
1	FRONT HEADLAMP RH	BROKEN	411.54	411.54
1	FRONT HEADLAMP LH	BROKEN	411.54	411.54
1	FRONT SIDE LAMP RH	BROKEN	170.60	170.60
1	FRONT SIDE LAMP LH	BROKEN	170.60	170.60
1	FRONT SUPPORT PANEL ASSY	BENT	626.30	626.30
1	FRONT BRACE PANEL	BENT	79.57	79.57
1	FRONT FENDER RH	BUCKLED	732.83	732.83
1	FRONT FENDER INNER COWLING RH	CRACKED	112.20	112.20
1	FRONT FENDER INDICATOR LAMP RH	SERVICEABLE	42.06	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	595.72	-
1	FRONT FENDER LH	BENT	732.83	732.83
1	FRONT FENDER INNER COWLING LH	TORN	112.20	112.20
1	FRONT FENDER INDICATOR LAMP LH	SERVICEABLE	42.06	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	BENT	595.72	595.72
1	RADIATOR ASSEMBLY	BENT / PUNCTURE	1,890.20	1,890.20
1	RADIATOR FAN BLADE	BROKEN	186.62	186.62
1	FAN CLUTCH	JAMMED	642.98	642.98
1	RADIATOR COWLING	CRACKED	184.77	184.77
1	RADIATOR GRILLE	MISSING	392.16	392.16

Report Ref No. CS/TP18021126/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON CONDENSER	BENT / PUNCTURE	1,098.16	1,098.16
1	AIRCON RECEIVER DRIER	DENTED	143.00	143.00
1	AIR CLEANER ASSEMBLY	BENT	548.92	548.92
1	AIR FILTER	SERVICEABLE	30.00	-
1	AIR-CLEANER INTAKE DUCT	DENTED	84.64	84.64
1	AIR-CLEANER INTAKE DUCT HOSE (TOP)	DENTED	61.83	61.83
1	AIR-CLEANER INTAKE HOSE	SERVICEABLE	166.18	-
1	AIR INTAKE RESONATOR TOP (SQUARE)	CRACKED	132.63	132.63
1	AIR RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	28.00	-
1	WINDSCREEN WASHER TANK-FILLER NECK	DENTED	80.42	80.42
1	WINDSCREEN WASHER TANK	CRACKED	48.06	48.06
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	204.62	-
1	FRONT FUSE BOX-TOP COVER	SERVICEABLE	93.01	-
1	FRONT FUSE BOX LOWER COVER	CRACKED	191.37	191.37
1	FRONT FUSE BOX CENTRE JUNCTION	CRACKED	367.17	367.17
1	FRONT FUSE BOX CENTRE COVER	DENTED	22.68	22.68
1	FRONT WINDSCREEN GLASS	CRACKED	996.40	996.40
1	FRONT WINDSCREEN MOULDING	NECESSARY	113.98	113.98
1	FRONT LOWER ARM RH	NOT NECESSARY	517.14	-
1	FRONT LOWER ARM LH	NOT NECESSARY	517.14	-
	LESS 25% DISCOUNT		-3,957.41	-3,352.65
			11,872.22	10,057.93
1	BONNET INSULATOR (50%)(SN)	CRACKED	436.72	218.36
	LESS 25% DISCOUNT		-109.18	-
			327.54	218.36
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	12.00	12.00
1	FRONT LICENCE PLATE (SN)	BENT	35.00	20.00
2	BONNET STOPPER (SN)	MISSING	10.00	10.00
1	SET BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	10.00	10.00
6	BONNET INSULATOR CLIP (SN)	NECESSARY	12.00	12.00
1	SET FRONT FENDER INNER COWLING CLIP RH (SN)	NECESSARY	40.00	40.00
1	SET FRONT FENDER INNER COWLING CLIP LH (SN)	NECESSARY	40.00	40.00
2	CAN RADIATOR COOLANT (SN)	NECESSARY	40.00	20.00

Report Ref No. CS/TP18021126/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RADIATOR GRILLE CLIPS (SN)	NECESSARY	10.00	10.00
2	RADIATOR TOP MOUNTING BRACKET (SN)	DISTORTED	15.00	15.00
2	RADIATOR LOWER MOUNTING BUSHING (SN)	NECESSARY	18.00	18.00
2	AIRCON CONDENSER BRACKET (SN)	TO REPAIR SEE LABOUR	30.00	-
2	AIRCON CONDENSER TOP MOUNTING (SN)	SERVICEABLE	15.80	-
1	BATTERY (50%)(SN)	DENTED	200.00	100.00
1	BATTERY TRAY (SN)	TO REPAIR SEE LABOUR	91.23	-
1	BATTERY FASTENER BRACKET (SN)	BENT	27.55	27.55
1	BATTERY FASTENER BOLT (SN)	TO REPAIR SEE LABOUR	12.79	-
2	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	30.00
1	ERP STICKER (SN)	NECESSARY	10.00	10.00
			769.37	414.55
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT TOW HOOK BRACKET,BONNET HINGE RH,FRONT FENDER INNER WHEEL HOUSE PANEL RH,AIR RESONATOR TANK TOP BRACKET,AIRCON CONDENSER BRACKET,BATTERY TRAY AND BATTERY FASTENER BOLT.		3,500.00	1,200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		200.00	180.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	40.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	1,080.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	250.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	300.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	150.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.		150.00	50.00
	TOWING FEES.		100.00	50.00
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.		350.00	100.00

Report Ref No. CS/TP18021126/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		350.00	200.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		350.00	250.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		150.00	120.00
	TO RESEAL SEALANT ON GAP.		100.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	REPEATED	350.00	-
			8,600.00	3,320.00
	GRAND TOTAL		21,569.13	14,010.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/TP18021126/Ktbn2


KONG SENG CHEONG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.