

ASS. REC. BY:

REF: CS/LPC18021132/KSD3

n2

Special Instruction:

Surveyor:

Kemmukh

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

22/11/18 @ 12:24pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 3315Y

Insured:

SJX 55455

at Workshop m/s

Massive Trading

Tel:

9108 2728

of

BLK 5038 AMK Ind. Park 2 # 01-405

Policy No:

Claim No:

18/18/18 / VC05 / 02 / 1133

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:28pm @ 22/11/18

Person Contacted:

Anthony

Vehicle IN

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLK 3315Y - X

SJX 55455 - CC6/AXA 14020872 / M/re 3q2

DOA: 4/9/14

9/1/18

6/1/18

4300

3250

email

4650

ASS. REC. BY:

REF:

LPC /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 33154 Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic c.c. 1597

Colour:

M. Red A/C: Insured / Std / NI / NA

Sp. Reading

32447 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR14PC 5650GT000841

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: MIC 215/55R16
R: HankookBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

5

mm

L/Bal.

4

mm

L/Bal.

5

mm

D.O.A.

11/18

D.O.A.

26/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/18

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 11 DEC 2018

Date / Time

Action / Instruction

11/11 File pass to Goshen Nanti

11/12 11/12 8 4700 Carbur

11/12/18 Confirmed HS \$ 4,700/- @ 6 days with Kenneth.
(\$ 7,243.36 Rd - 63%)

Date/Time, File Pass to?

11/12/18



: Prell. Report

1)

Type



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$

Fixings

Others

TOTAL

350

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

4,700/- 1/5

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 22 November 2018 12:24 PM
To: Admin-D (LKKAuto)
Subject: RE: TP CLAIMS- SKB2025A & SLD1091S DOA 18/11/2018 Our Ref: 18/18/18/VP05/021134
Attachments: 22112018121927.pdf; 22112018122314.pdf

Our Ref : 18/18/18/VC05/021133

Dear Catherine,

Please see attached and proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

GERALD POH WEE BIN

From: GERALD POH WEE BIN
Sent: Thursday, 22 November, 2018 12:19 PM
To: 'admin-d@lkkauto.com'
Cc: 'mt_claim@lonpac.com'; 'Janice Kee'
Subject: FW: Pre Repair Survey for SLK 3315 Y Our Ref: TKSF/M492-ACC-41187.18/sf

Dear Catherine,

Kindly proceed accordingly.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Janice Kee [<mailto:janice.kee@ksteoptr.com>]
Sent: Thursday, 22 November, 2018 12:08 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Anthony Cheong
Subject: Re: Pre Repair Survey for SLK 3315 Y Our Ref: TKSF/M492-ACC-41187.18/sf

Dear Sir

Our client has agree to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

张景祥大律師樓
(律師公會及宣誓處)

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTEOCO@singnet.com.sg

(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)



Our Ref : TKSF/M492-ACC-41187.18/sf (mc)
Your Ref : SJX 5545 S
Date : 22 November 2018

Secretary in charge: Janice

Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteoptr.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Motor Claims Dept

WITHOUT PREJUDICE

BY PDX #8192 & BY FAX 6296 2706

cc: CT Elevator Pte Ltd (Owner)
Chen Hong (Driver)
C/o 9 Tagore Lane
#03-22 9@Tagore
Singapore 787472

BY POST ONLY

PDX Intercompany Exchange Pte Ltd



010809571771

FROM TEO KENG SIANG LLC
PDX Box No. 8902

Dear Sirs

RE: ACCIDENT INVOLVING SLK 3315 Y / SJX 5545 S / (SJF 3261 T) ON 16/11/18 ALONG CTE TOWARDS CITY BEFORE EXIT 6

We are instructed by Yap Eng Boo to notify you of a road traffic accident 16/11/18 at about 19:15 hours at ALONG CTE TOWARDS CITY BEFORE EXIT 6 involving our client's vehicle registration number SLK 3315 Y and vehicle registration number SJX 5545 S driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle SLK 3315 Y is now at the following workshop:-

Massive Trading & Auto
Blk 5038 Ang Mo Kio Industrial Park 2
#01-405
Singapore 569541
Contact: 9108 2728 Anthony

Yours faithfully,

M/s Teo Keng Siang LLC
encs

Teo Keng Siang
LL.M(Singapore).
LL.B (Hons) (Singapore)

**Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225

Tel : 91082728

Fax : 64816131

Yap Eng Boo
Blk 221 Ang Mo Kio Ave 1
#08-759
Singapore 560221

Vehicle No : SLK 3315 Y
Make/Model : Honda Civic
Year : 2016

Not Authorised

Resumes B & paint

6 days

1/1 Sy @ 4650/pc
4700

Qty	Unit Price	Amount
-----	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet	R	\$658.80	X
1 pc	Front bonnet lock	R	\$185.60	X
1 pc	Front o/s fender	R	\$286.90	X
1 pc	Front o/s fender lamp	R	\$76.20	X
2 pcs	Front headlamp assy	CR	\$725.70	\$1,451.40 X
1 pc	Front support panel	R	\$575.90	X
1 pc	Front support panel top garnish	R	\$175.20	X
1 pc	Front grille	CR	\$188.80	X
1 pc	Front grille chrome	CR	\$150.40	X
1 pc	Front grille emblem	CR	\$45.60	X
1 pc	Front bumper	R	\$597.90	X
1 pc	Front bumper reinforcement	R	\$396.70	X
1 pc	Front bumper lower grille	CR	\$106.60	X
2 pcs	Front bumper fog lamp	R	\$375.50	\$751.00 X
2 pcs	Front bumper fog lamp garnish	R	\$65.80	\$131.60 X
1 pc	Air con condenser	R	\$755.40	X
1 pc	Rear boot lid	R	\$788.10	X
1 pc	Rear boot rubber	R	\$155.60	X
1 pc	Rear boot lid emblem " H "	R	\$35.60	X
1 pc	Rear boot lid emblem " Civic "	R	\$46.20	X
1 pc	Rear boot lid emblem " Vtech "	R	\$45.10	X
2 pcs	Rear tail-lamp assy	CR	\$287.40	\$574.80 X
1 pc	Rear end panel	R	\$355.50	X
1 pc	Rear end panel inner garnish	R	\$155.70	X
1 pc	Rear bumper	R	\$668.20	X
1 pc	Rear bumper lower garnish	CR	\$275.30	X
1 pc	Rear bumper reinforcement	R	\$395.10	X
2 pcs	Rear bumper side retainer	R	\$67.30	\$134.60 X
2 pcs	Rear bumper bracket	R	\$72.30	\$144.60 X
		balance c/f	\$10,308.40	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 14:56
Date Of Accident	16/11/2018 19:15
Exact Location Of Accident	CTE TOWARDS CITY BEFORE EXIT 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK3315Y
Insured/Policyholder	
Name Of Registered Owner	YAP ENG BOO
NRIC No	S1575552J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98502913
Alternative Phone No	OTHERS-98220925

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 VTI CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MU000230
Cover Note Number	12/01/2017 - 11/01/2019

Driver

Name of Driver	YAP YI YANG
NRIC No	S9536269I
Date Of Birth	26/09/1995
Occupation	INDOOR
Date Of Driving Pass	02/12/2017
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98220925
Fax Number	
Contact Number	OTHERS-98502913
Email Address	NOEMAIL

Address	BLK 221 ANG MO KIO AVE 1 #08-759
Postcode	560221
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KALYNN GIH ZHI XUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4519999 - FAX NO: 65535679
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX5545S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN HONG
NRIC/Passport Number	S8787366H
Contact Number	96460589
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJF3261T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANDY
NRIC/Passport Number	
Contact Number	82181274
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	YAP YI YANG
Approximate Age	
Injuries Sustain	WHIPLASH
Injured person in which vehicle?	SLK3315Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	KALYNN GOH ZHI XUAN
Approximate Age	
Injuries Sustain	WHIPLASH
Injured person in which vehicle?	SLK3315Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 16.11.2018 Time: 7.15 pm Location: CTE towards city before exit 6
 My Vehicle A: SLK 3315 Y Vehicle B: SIF 3216 T Vehicle C: SLX 5545 S
 SKETCH PLAN U B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16.11.2018 at 7.15pm, I was driving along lane 1 CTE towards city before exit 6 the vehicle (C) slow down and likewise I do slow down my vehicle. At this juncture vehicle (B) could not stopped in time and collided onto the rear of my vehicle. The strong impact pushes my vehicle forward to collide onto the front vehicle

Car B - Chen Hong
 S 97973604

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop : Massive Trading & Auto
 Email address : cheonganthony@yahoo.com.sg
 & myself
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 21/11/18 at 1400 hrs

Reporting Centre Personnel Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY

SLK 3315 Y

2 pcs	Rear bumper reflector
2 pcs	Rear bumper reflector garnish
2 pcs	Rear sensor
1 pc	Rear exhaust silencer

balance b/f	\$10,308.40
<i>n/s</i>	
<i>n/s</i> \$95.10	\$190.20 <i>2x</i>
<i>n/s</i> \$55.10	\$110.20 <i>4x</i>
<i>short</i> \$258.10	\$516.20 <i>2x</i>
	<i>n</i> \$866.70 <i>X</i>
	\$11,991.70
Less 20 %	\$2,398.34
	\$9,593.36

S Nett Item

1 pc	Front no plate
20 pcs	Front & rear bumper clip

\$2.00	<i>n</i> \$40.00 <i>✓</i>
	<i>n</i> \$40.00 <i>✓</i>
	\$80.00

Labour Charges

To remove/renew the above accident parts including knocking, welding & cutting.

\$1,200.00 *700*

To putty and spray paint

\$1,200.00 *880*

To check and reconnect wiring.

\$40.00 *✓*

To spray anti rust proofing treatment on accident affected portion.

nn \$100.00 *X*

Remove/refit rear boot upholstery to facilitate repair.

\$150.00 *60*

Remove/renew air con condenser & to top up gas element

nn \$180.00 *X*

Total \$12,543.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18021132/Ksd3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-12-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 5545S	Veh. Inspected	SLK 3315Y
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VC05/021133	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	22/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MRHFC5650GT000841	Colour	METALLIC RED
Odometer	32447	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	MICHELIN	4 mm
L/H Front Tyre	215/55 R16	MICHELIN	4 mm
R/H Rear Tyre	215/55 R16	HANKOOK	5 mm
L/H Rear Tyre	215/55 R16	HANKOOK	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/11/2018	Inspection Date	26/11/2018
Survey held at	BLK 5038 AMK IND.PARK 2# 01-405		
Repairer	MASSIVE TRADING & AUTO		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3315Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	TO REPAIR SEE LABOUR	658.80	-
1	FRONT BONNET LOCK	TO REPAIR SEE LABOUR	185.60	-
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	286.90	-
1	FRONT O/S FENDER LAMP	SERVICEABLE	76.20	-
2	FRONT HEADLAMP ASSY @\$725.70	CRACKED	1,451.40	1,451.40
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	575.90	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	175.20	-
1	FRONT GRILLE	CRACKED	188.80	188.80
1	FRONT GRILLE CHROME	MTG CRACKED	150.40	150.40
1	FRONT GRILLE EMBLEM	NECESSARY	45.60	45.60
1	FRONT BUMPER	BUCKLED	597.90	597.90
1	FRONT BUMPER REINFORCEMENT	BUCKLED	396.70	396.70
1	FRONT BUMPER LOWER GRILLE	CRACKED	106.60	106.60
2	FRONT BUMPER FOG LAMP @\$375.50	SERVICEABLE	751.00	-
2	FRONT BUMPER FOG LAMP GARNISH @\$65.80	SERVICEABLE	131.60	-
1	AIR CON CONDENSER	SERVICEABLE	755.40	-
1	REAR BOOT LID	TO REPAIR SEE LABOUR	788.10	-
1	REAR BOOT RUBBER	SERVICEABLE	155.60	-
1	REAR BOOT LID EMBLEM "H"	NECESSARY	35.60	35.60
1	REAR BOOT LID EMBLEM "CIVIC"	NECESSARY	46.20	46.20
1	REAR BOOT LID EMBLEM "VTECH"	NECESSARY	45.10	45.10
2	REAR TAIL-LAMP ASSY @\$287.40	N/S MTG CRACKED / O/S SERVICEABLE	574.80	287.40
1	REAR END PANEL	TO REPAIR SEE LABOUR	355.50	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	155.70	-
1	REAR BUMPER	BUCKLED	668.20	668.20
1	REAR BUMPER LOWER GARNISH	CRACKED	275.30	275.30
1	REAR BUMPER REINFORCEMENT	BENT	395.10	395.10
2	REAR BUMPER SIDE RETAINER @\$67.30	N/S DISTORTED	134.60	67.30

Report Ref No. CS/LPC18021132/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER BRACKET @\$72.30	TO REPAIR SEE LABOUR	144.60	-
2	REAR BUMPER REFLECTOR @\$95.10	N/S CRACKED	190.20	95.10
2	REAR BUMPER REFLECTOR GARNISH @\$55.10	N/S DENTED	110.20	55.10
2	REAR SENSOR @\$258.10	SHORTED (1 PC ONLY)	516.20	258.10
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	866.70	-
	LESS 20% DISCOUNT		-2,398.34	-1,033.18
			9,593.36	4,132.72
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE (SN)	BENT	40.00	40.00
20	FRONT & REAR BUMPER CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
			80.00	80.00
	<u>LABOUR</u>			
	TO REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING.INCLUSIVE OF THE REPAIR OF FRONT BONNET,FRONT BONNET LOCK,FRONT O/S FENDER,FRONT SUPPORT PANEL,REAR BOOT LID,REAR END PANEL,REAR BUMPER BRACKET AND REAR EXHAUST SILENCER.		1,200.00	700.00
	TO PUTTY AND SPRAY PAINT.		1,200.00	880.00
	TO CHECK AND RECONNECT WIRING.		40.00	40.00
	TO SPRAY ANTI RUST PROOFING TREATMENT ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	100.00	-
	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.		150.00	60.00
	REMOVE/RENEW AIR CON CONDENSER & TO TOP UP GAS ELEMENT.	NOT NECESSARY	180.00	-
			2,870.00	1,680.00
	GRAND TOTAL		12,543.36	5,892.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00

Report Ref No. CS/LPC18021132/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.