



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088854-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)

0

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/11/2018
Vehicle Reg. No.:	SKF3645H	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	GOH DUO YUN SHAUN		
Make/Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Vehicle Reg. Date:	24/05/2012
Vehicle Colour:	WHITE		
Engine No:	CAV400192	Chassis No:	WWWZZZ13ZCV031791
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	2,039.40
Miscellaneous Items	10.00
Labour	1,210.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,259.40
+ GST 7.00% (\$\$)	228.16
Nett Amount (\$\$)	3,487.56

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 974495749
wp
28/11/18 R 130pm
Resurvey after repair
Lumpsum
sur@lkkauto.com
4 days.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Nov 2018)

Parts: M1-COUPE VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKF3645H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH	10.00	0.00	2,043.00 FL <i>bt</i>
2	1		*FRONT DOOR LOWER PROTECTIVE MOULDING RH	10.00	0.00	145.00 FL <i>ut</i>
3	1		*FRONT DOOR RUBBER RH	10.00	0.00	48.00 FL <i>?</i>
4	10		*FRONT DOOR RIVET	10.00	0.00	30.00 FL <i>ru</i>
5	1		*FRONT FENDER RH - REPAIR	10.00	0.00	-
6	1		*FRONT WHEEL RIM RH - REPAIR	10.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 2,266.00

- List Item Discount on L Items (S\$) 226.60

Total Parts (S\$) 2,039.40

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING & LIGHTING MECHANISM	New	20 60.00
2	TO KNOCK & STRAIGHTEN ON FRONT FENDER RH. TO REPLACE DAMAGED ITEMS. RE-ALIGN CONNECTION.	New	300 400.00
3	TO RUST PROOF ON REPAIRED AREAS	New	30 50.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	400 500.00
5	TO CHECK WHEEL ALIGNMENT	New	60 80.00
6	TO REPAIR ON FRONT WHEEL RIM RH	New	80 120.00
Gross Labour Cost (S\$)			1,210.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**
< END OF ESTIMATES >