

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5712K**

AAD1811-175

*Not Authored  
L1 Sing @ 2450h*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHC 5712K**

VF1ABL15AUC280313

RENAULT

LATITUDE

19.11.2018

**CHINA TAIPING**

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Buclad</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Del/wr</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 } X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70
19	1 BOOT REAR	\$	<i>R</i> 2,872.68
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
24	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36 —
25	1 BOOT BADGE	\$	<i>na</i> 225.36 —
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08 X
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08 X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84 X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84 X

**Trans-cab Auto Services Pte Ltd**

AAD1811-175

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5712K**

30	1 BOOT INNER TRIM	\$	Sn	586.45	X
31	1 BOOT SWITCH	\$	Sn	168.13	X
32	1 BOOT LOCK	\$	n	202.67	X
33	1 BOOT LOCK CATCH	\$	n	74.40	X
		\$		<b>16,046.87</b>	
		10% \$		<b>7.44</b>	
		\$		<b>16,039.43</b>	

**Special Nett**

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	—
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	na	80.00	X
12	1 WINDSCREEN MOULDING	\$	na	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X

**TOTAL \$ 1,244.82****TOTAL PARTS \$ 17,284.25****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *4401*Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 3,000.00 *3001*

**Trans-cab Auto Services Pte Ltd**

AAD1811-175

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5712K**

To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i>	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X

**TOTAL \$ 7,410.00****Over All Total \$ 40,733.69****(LUMP SUM)****Repair Days**~~10 DAYS~~*2 days*