

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Owner : Muhammad Firdaus Bin Salim

Accident Date : 5-Nov-18

Vehicle No : FBF 1119 E

Vehicle Model : Yamaha T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 75.00
1	Front cowling inner bracket	\$ 55.00
2	Front fork tubes assy	\$ 640.00
1	Front wheel rim	\$ 280.00
1	Fork under bracket	\$ 185.00
1	Front rim shaft	\$ 45.00
1	Front rim bearing	\$ 38.00
1	Front brake disc	\$ 155.00
1	Front brake caliper	\$ 238.00
1	Handle bar	\$ 75.00
2	Handle bar ends	\$ 64.00
1	Hand grip (1 set)	\$ 55.00
1	Handle bar inner bracket	\$ 68.00
2	Side mirrors	\$ 110.00
1	Brake lever	\$ 32.00
2	Front signals	\$ 140.00
1	Headlamp	\$ 185.00
1	Fairing assy (1 set)	\$ 475.00
1	Centre inner panel	\$ 145.00
1	Radiator	\$ 458.00
1	Radiator fan assy	\$ 125.00
1	Front footrest bracket	\$ 65.00
2	Front footrest rubbers	\$ 70.00
1	Gear pedal	\$ 42.00
1	Brake pedal	\$ 42.00
1	Clutch cover	\$ 180.00
2	Rear footrests	\$ 80.00
2	Rear footrest brackets	\$ 156.00
1	Rear taillamp	\$ 135.00
1	Rear wheel rim	\$ 280.00
1	Rear fender	\$ 120.00
1	Basket	\$ 50.00
		\$ 4,863.00
	Less 10%	\$ 486.30
		\$ 4,376.70

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Muhammad Firdaus Bin Salim

Accident Date : 5-Nov-18

Vehicle No : FBF 1119 E

Vehicle Model : Yamaha T135

Estimated Repair Costs

c/f: \$ 4,376.70

Special Nett Items

1	Number plate (1 set)	\$	28.00	10
2	Fork oils	\$	30.00	X
2	Fork oil seals	\$	56.00	X
1	Steering cone (1 set)	\$	90.00	X
1	Rear box	\$	250.00	200
1	Rear box bracket	\$	100.00	/
1	Coolant	\$	18.00	10
1	ERP IU	\$	175.00	160
1	"YOSHIMURA" exhaust pipe	\$	1,250.00	X
		\$	1,997.00	

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	80.00	X
3	To provide labour.	\$	380.00	300
4	To repair body frame.	\$	350.00	250
		\$	860.00	

Grand Total

\$ 7,233.70

Dollars: Seven Thousand Two Hundred Thirty-Three And Seventy Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: