



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLJ 1053 X**  
Make & Model : **TOYOTA WISH**  
Chassis No. : **JTDGG20W30J006279**

Submit By : **Carmen Lim**  
Year Manufacture : **2016**  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$70.20	S.N	✓
2	Rear windscreen sealant	1	\$50.00	S.N	✓
3	Reverse sensor	2	\$370.20	S.N	2005n
4	Rear number plate	1	\$45.00	S.N	✓
6	Rear No.plate lamp LH	1	\$70.50		X
7	Rear No.plate lamp RH	1	\$70.50		X
8	Rear bumper	1	\$579.23		✓
9	Rear bumper clip	10	\$38.90		✓
10	Rear bumper side retainer LH	1	\$93.10		✓
11	Rear bumper side retainer RH	1	\$93.10		X
12	Rear bumper bracket LH	1	\$97.87		Z
13	Rear bumper bracket RH	1	\$97.87		X
14	Rear bumper sponge	2	N/A		
14	Rear Bumper reinforcement	1	N/A		
15	Rear bumper reflector LH	1	\$57.56		X
16	Rear bumper reflector RH	1	\$57.56		X
17	Rear bumper reflector garnish LH	1	N/A		
18	Rear bumper reflector garnish RH	1	N/A		
19	Tail door	1	\$1,500.70		✓
20	Tail door lock	1	\$375.60		✓
21	Tail door emblem	1	\$59.70		✓
22	"GREEN" Sticker	1	\$35.00	S.N	✓
23	Tail door chrome	1	\$278.50		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : **SLJ 1053 X**

Make & Model : **TOYOTA WISH**

Chassis No : **JTDGG20W30J006279**

Submit By : **Carmen Lim**

Year Manufacture : **2016**

Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim <i>Sn</i>	1	\$365.20		X
25	Tail door trim clip <i>Nn</i>	10	\$42.10		X
26	Taildoor reflector LH <i>Sn</i>	1	\$319.70		X
27	Taildoor reflector RH <i>Sn</i>	1	\$319.70		X
28	Tail end panel <i>B</i>	1	\$560.24		✓
29	Tail end panel garnish <i>Sn</i>	1	\$279.86		✓
30	Tail end panel garnish clip <i>nn</i>	10	\$32.10		✓
31	Boot weatherstrip <i>Dis/In</i>	1	\$341.12		✓
32	Tail lamp LH <i>Sn</i>	1	\$339.76		X
33	Tail lamp RH <i>Sn</i>	1	\$339.76		X
34	Spare tyre well panel <i>R</i>	1	\$750.90		X
35	Spare tyre board <i>Sn</i>	1	\$566.73		X
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.





## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLJ 1053 X** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA WISH** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,400.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LH REAR FENDER)	\$1,200.00	1000
3	To check Wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$250.00	60
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a Supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

hence notify  
following:  
after spray painting  
during resurvey  
confirmation  
"out Prejudice" basis  
• the conditions allowed  
• all repair estimations must be resurveyed and  
is subject to approval from insurance Company

Acknowledged by receiver  
Signature:  
Date:

**ESTEEM PERFORMANCE PTE LTD**

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

**Spare Parts**

Vehicle No. :

**SLJ 1053 X**

Submit By :

**CARMEN LIM**

Make &amp; Model :

TOYOTA WISH

Year Manufacture :

2016

Chassis No. :

JTDGG20W30J006279

Engine No. :

**Cost / List****Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Anttena <i>CMA</i>	1	\$171.19		<input checked="" type="checkbox"/>
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

171.19.