

RE: <TP - Mandate IA> - S8M013TV [ACCIDENT INVOLVING SKD 3107E(OI) & SLU 1207L(TP) ON 16/11/2018]

Type

Q Question

Message

Hi, For LOR, we have offered up to 9days, however third party insisted for 10days(8 repair days + 1Saturday + 1Sunday). The total amount counter proposed by third party is \$12,037.79(all-in). Kindly advise if we may proceed to settle at \$12,037.79(all-in) or elase advise further. Thank you, Hsiao Tong - 08 Oct 2019.

Reply



<TP - Mandate IA> - S8M013TV [ACCIDENT INVOLVING SKD 3107E(OI) & SLU 1207L(TP) ON 16/11/2018]

Type

Q Question

Message

Hi Hsiao Tong, pls inform TP, offer maintain. Tks

8/10/16@11.wom Called TP, # subaim. And maintan.
9days. He area for 9.5days. 11 Call, Ivan Palled Wome in mountain

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 9 October 2019 9:26 AM

To: Hsiao Tong (LKKAuto)

Subject: RE: New message for service request 83483, vehicle number SLU1207L

	revised to 9 days max (full & final). Tks		
J	Revised offer at \$11,930.79	СНТ	2/9/2019 10:31:01 AM
]	Message AXA: Hi, For LOR, we have offered up to 9days, however third party insisted for 10days(8 repair days + 1Saturday + 1Sunday). The total amount counter proposed by third party is \$12,037.79(all-in). Kindly advise if we may proceed to settle at \$12,037.79(all-in) or elase advise further. Thank you. Hsiao Tong - 08 Oct 2019.	СНТ	8/10/2019 10:14:13 AM
	WINNIE(AXA) CALLED IN. SHE SAID TELL TP WKSP (SUHAIMI) MAINTAIN OFFER AT 9DAYS	СНТ	8/10/2019 10:23:05 AM
	10/8/19 10:34 AM HO WinnieHi Hsiao Tong, pls inform TP, offer maintain. Tks	LSP	9/10/2019 9:12:10 AM

Best Regards, Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Tuesday, 8 October 2019 10:39 AM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 83483, vehicle number SLU1207L

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

----Original Message----

From: winnie.ho@axa.com.sg <winnie.ho@axa.com.sg>

Sent: Tuesday, 8 October, 2019 10:35 AM

To: admin-d@lkkauto.com

Subject: New message for service request 83483, vehicle number SLU1207L

AXA Insurance has sent you a message for claim number S8M013TV.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal.

Hsiao Tong (LKKAuto)

From: Sent:	Suhaimi Saidi <suha Tuesday, 15 Octobe</suha 	aimisaidi8069@gmail.com>
To:	Hsiao Tong (LKKAut	
Subject:		03107E DOA LKK REF CC4/ASM18021148/R1pb3
Dear Hsiao Tong,		
We refer to your email o	f 14.10.19.	
We confirmed acceptance	e of your offer there	in.
Please let us have the D	V soonest.	
Thanks,		
Suhaimi		
On Mon, 14 Oct 2019 at 08:1	6, Hsiao Tong (LKKAuto)	<chewht@lkkauto.com> wrote:</chewht@lkkauto.com>
Without Prejudice		
Dear Sirs/Mdm,		
We refer to your below ema	ail	
We have our principal instru	uction to maintain our of	ffer as follows: -
V <u>ec </u>		
1. Cost of Repair (w/GST)		\$10,967.79
2. Loss of Rental (9days x \$		\$ 963.00
	Total	\$11,930.79
Please re-consider.		

[&]quot;Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: <u>chewht@lkkauto.com</u> fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > Sent: Thursday, 10 October 2019 12:53 PM
To: Hsiao Tong (LKKAuto) < <u>chewht@lkkauto.com</u> >
Subject: Re: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3
Dear Hsiao Tong,
We refer to our emails of 02.09.19, 14.09.19 and 27.09.19.
We have yet to hear from you.
As matter as been protracted, please revert within the next 7 days failing which we shall proceed accordingly.
Regards,
Suhaimi
For Wearnes Automotive Pte Ltd

On Fri, 27 Sep 2019 at 14:57, Suhaimi Saidi <<u>suhaimisaidi8069@gmail.com</u>> wrote:

Dear Hsiao Tong,

Hp: 93865752

As spoken a moment ago, please revert soonest with your revised offer.
Regards,
Evelyn
On Sat, 14 Sep 2019 at 15:57, Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > wrote:
Dear Hsiao Tong,
We refer to our email of 02.09.19.
Please revert soonest.
Regards,
Suhaimi
On Mon, 2 Sep 2019 at 12:45, Suhaimi Saidi < suhaimisaidi8069@gmail.com > wrote:
Dear Hsiao Tong,
Refer to your offer dated 02.09.2019
We maintained our counter propose loss of rental in full as per our letter of demand dated 07.02.2019
LOR 10 days = \$1070.00 and the rest remain same.
Please review and revert.
Regards

Suhaimi Saidi	
Hp:93865752	
For Wearnes Automotive Pte Ltd	
For Wearnes Automotive Pte Ltu	
On Mon, 2 Sep 2019 at 10:42, Hsiao Tong (LK	KAuto) < chewht@lkkauto.com > wrote:
Without Prejudice	
Dear Sirs/Mdm,	
We refer to the above matter.	
we refer to the above matter.	
We have our principal instruction to revise of	our offer as follows: -
1. Cost of Repair (w/GST)	\$10,967.79
2. Loss of Rental (9days x \$100.00)(w/GST)	
	Total \$11,930.79
Please confirm acceptance.	
"Please note that our proposal and correspondence	with you is strictly on a without prejudice basis and should not be construed as
engagement should not be disclosed in any other related claims."	ur policyholder and/or the authorised driver. The terms of our without prejudic lated matter(s) in respect of this accident nor should it be binding in any other
related Claims.	
Best Regards,	
Hsiao Tong, Chew Case Handler	
LKK Auto Consultants Pte Ltd	

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108

From: Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > Sent: Tuesday, 27 August 2019 2:41 PM
To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com > Subject: Re: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3
Hi Hsiao Tong,
We refer to our emails of 30.07.19 and 06.08.19.
Please revert soonest.
Regards,
Suhaimi
On Tue, 6 Aug 2019 at 13:12, Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > wrote:
Dear Hsiao Tong,
Any updates?
Regards
Suhaimi Saidi
Hp:93865752
For Wearnes Automotive Pte Ltd

HI HSIAO TONG,	
We refer to your email of 28.07.19.	
We would like to counter propose in full for L	OR, 8 days repair + weekend.
Please review and revert.	
Regards,	
Suhaimi	
On Sun, 28 Jul 2019 at 10:15, Hsiao Tong (LKKAuto) < <u>c</u>	chewht@lkkauto.com> wrote:
Without Prejudice	
Dear Sirs/Mdm,	
We refer to the above matter.	
We have our principal instruction to offer as follows:	ws: -
1. Cost of Repair (w/GST)	\$10,967.79
2. Loss of Rental (8days x \$100.00) (w/GST)	\$ 856.00
I me we indicate to see I do it de it	\$11,823.79
Total	1 311.023.77

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 6 July 2019 11:18 AM

To: Suhaimi Saidi <suhaimisaidi8069@gmail.com>

Cc: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <<u>Rasul@lkkauto.com</u>> Subject: RE: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3

Without Prejudice

Hi Suhaimi,

We refer to the above matter.

As per our surveyor, kindly let us have the following damage photos for our necessary action: -

- Tyre Pressure Sensor
- Harness Bumper Frt

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 15 June 2019 11:00 AM

To: Suhaimi Saidi <suhaimisaidi8069@gmail.com>

Cc: Admin A <admin-a@lkkauto.com>; Rasul (LKKAuto) <<u>Rasul@lkkauto.com</u>> Subject: RE: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3

Without Prejudice

Hi Suhaimi,

We refer to the above matter.

As per our surveyor, kindly let us have the following damage photos for our necessary action: -

- Tyre Pressure Sensor
- Harness Bumper Frt

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement. In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement." Best Regards, Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Vic (LKKAuto) Sent: Thursday, 13 June 2019 4:38 PM To: Suhaimi Saidi <suhaimisaidi8069@gmail.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com> Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com> Subject: RE: SLU1207L / SKD3107E DOA LKK REF CC4/ASM18021148/R1pb3 Without Prejudice Dear Suhaimi, We refer to your below email and the contents were noted. Please be informed that this matter is now handled by my colleague Ms Hsiao Tong and she will get back to you for an update/offer.

Thank you.

Hi Hsiao Tong,
Kindly do the necessary.
Thank you.
Best Regards,
Vic Alpeh Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6841-2096 email: <u>vicalpeh@lkkauto.com</u> fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
Save the Earth. Print only when necessary.
This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.
From: Suhaimi Saidi [mailto:suhaimisaidi8069@gmail.com]
Sent: Wednesday, 12 June, 2019 10:07 AM To: Vic (LKKAuto) Subject: Re: SLU1207L / SKD3107E DOA
Dear Vic,
Please revert.

Regards

Suhaimi Saidi
Hp:93865752
For Wearnes Automotive Pte Ltd
On Wed, 29 May 2019 at 11:30, Suhaimi Saidi < suhaimisaidi8069@gmail.com > wrote:
Hi Vic,
We refer to our email below.
Any update?
Regards,
Suhaimi
Forwarded message
From: Suhaimi Saidi <suhaimisaidi8069@gmail.com> Date: Wed, 15 May 2019 at 08:05</suhaimisaidi8069@gmail.com>
Subject: Re: SLU1207L / SKD3107E DOA To: Vic (LKKAuto) < vicalpeh@lkkauto.com >
Dear Vic,
We refer to our emails below.
We refer to our citians select.
Please let us have your offer of settlement soonest as matter has been protracted.
Regards,
Suhaimi

(On Mon, 29 Apr 2019 at 09:26, Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > wrote:
	Dear Vic,
	Any update?
	Regards,
	Suhaimi
	On Tue, 16 Apr 2019 at 11:45, Suhaimi Saidi < <u>suhaimisaidi8069@gmail.com</u> > wrote:
	Yr ref: CC4/ASM18021148/hb3
	Dear Vic,
	Refer to the above, please revert with your settlement.
	Regards
	Suhaimi Saidi
	Hp:93865752
	For Wearnes Automotive Pte Ltd



Our Reference: SLU1207L/7015297

Your Reference: SKD3107E

By Email / Mail

07 February 2019

AXA INSURANCE PTE LTD C/O LKK AUTO CONSULTANTS

Attn: Third Party Claim Department -

ACCIDENT INVOLVING SLU1207L & SKD3107E ON 16 Nov 2018.

Dear Officer,

We wish to inform you that the repairs to our client vehicle have been completed.

We hereby submit the claims as follows:

Details	Remarks	Amount (SGD)
Cost of Repairs		10,967.79
Loss Of Rental	1,070.00 x 10 days	10,700.00
Others		
TOTAL		21,667.79

Kindly let us have your offer to Christine.yow@wearnes.com

Your soonest reply is much appreciated. Thank you.



Yours faithfully Christine Yow D (65) 6430 4899 Wearnes Automotive Pte Ltd Bodyshop and Paint Division 249 Alexandra Road Singapore 159935

This is a computer generated printout, no signature is required.

Wearnes Automotive Pte. Ltd. 45 Leng Kee Road, Singapore 159103 T 65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R



SERVICE TAX INVOICE

	TAX THANTCE	
0 - A00005 SL: AXA INSURANCE P	E LTD	
AXA INSURANCE PTE LTD	GST Reg.No:M28920	628X
		e 1
#27-01 AXA TOWER,	Inv.No: B&P 7015297 Page Inv.date.: 29/01/2019	500 65
SINGAPORE 068811	WIP No : 39237	
SIMANFORE COODEL	Veh.In/Out: 05/12/2018 14/01/2	2019
		2017
	*Tel.No : 6338 7288	
	Reg.No. : SLU1207L	
Closed by : Derek Oh Siong Wee		
Svc Consultant : ACC Remarks : Mr Goh Koon Wee	Mileage: 20,868	
Remarks : Mr Goh Koon Wee	Chassis No: VF1RFA00158580930	
Parts/Op.No Description	Mech Qty Price Disc% Pkg Am	ount G
802 TO REPLACE FRONT BONNET, FRT	0 1575 00 0 1 57	E 00 6
BUMPER, FRT BRACKET, FRT LH	0 1575.00 0 1,575	5.00 5
HEADLAMP, FRT LH FENDER, FRT		
WHEEL ARCH, ETC		
800 TO PUTTY SPRAY PAINT ON FRT	0 1200.00 0 1.20	0.00 8
BONNET, FRT BUMPER, FRT LH	(T)	\$454580 ST
FENDER, ETC		
0031 TO REPLACE FRONT LH RIM	0 50 00 0 50	0.00 8
419 COMPUTERISED WHEEL ALIGMENT		
280 TO EDOUS HEAD! AMD	0 110 00 0 110	
280 TO FOCUS HEADLAMP 280 TO CHECK WIRING INCLUDE	0 110.00 0 110 0 330.00 0 33	0.00 8
RESETTING OF ALL ELECTRICAL	0 350.00 0 35	0.00 0
MODULES	1 0 50 11/5 50 10 1 0/	0.05.0
620223972R BUMPER FRT GS4 620358403R BUMPER BRACKET FRT L	1.0 EA 1165.50 10 1,040	8.70 0
SZUSSBAUSK BUMPEK BRACKET FRI L	1.0 EA 104.50 10 9 1.0 EA 191.30 10 17	9.05 5
261A24871R FOG LAMP COVER CHORM	1.0 EA 191.30 10 17	2.17 3
622907255R BUMPER FRT SUPPORT B	1.0 EA 91.80 10 8	2.62 3



SERVICE TAX INVOICE

0 - A00005 SL: AXA INSURANCE PTE LTD

AXA INSURANCE PTE LTD

GST Reg.No:M28920628X 8 SHENTON WAY. Inv.No. . : B&P 7015297 Page 2

#27-01 AXA TOWER. Inv.date. : 29/01/2019

SINGAPORE 068811 WIP No. . : 39237

Veh.In/Out: 05/12/2018 14/01/2019

*Tel.No. . : 6338 7288 Reg.No. . : SLU1207L

Closed by : Derek Oh Siong Wee Reg.date. : 23/11/2017 Svc Consultant : ACC Mileage . : 20,868

Remarks : Mr Goh Koon Wee Chassis No: VF1RFA00158580930

Mech Qty Price Disc% Pkg Amount G Parts/Op.No Description 269257264R SUPPORT BRACKET, HEA 1.0 EA 66.60 10 59.94 S 631012967R FENDER FRT LH GS4 1.0 EA 512.70 10 461.43 S 625132283R BRACKET, FENDER FRT 1.0 EA 98.10 10 88.29 S 620424559R FENDER BRACKET FRT L 1.0 EA 89.90 10 80.91 S 7703077435 WHEEL ARCH CLIP J5AL 10.0 EA 5.30 10 47.70 S 625132283R BRACKET, FENDER FRT 1.0 EA 98.10 10 88.29 S 620424559R FENDER BRACKET FRT L 1.0 EA 89.90 10 80.91 S 7703077435 WHEEL ARCH CLIP J5AL 10.0 EA 5.30 10 47.70 S 260606234R HEADLAMP LH R9A3 GS4 1.0 EA 677.30 10 609.57 S 403007153R ALLOY RIM 20" R9A3 S 1.0 EA 986.40 10 887.76 S 407004CB0B TYRE PRESSURE SENSOR 1.0 EA 119.10 10 107.19 S 622540901R BUMPER LOWER GS4 1.0 EA 356.20 10 320.58 S 269257264R SUPPORT BRACKET, HEA 1.0 EA 66.60 10 59.94 S 257-257-254R SUPPORT BRHCKET, HEH 1.0 EA 204.60 10 37.74 S
638457730R WHEEL ARCH - FRT LH 1.0 EA 204.60 10 184.14 S
253A49995R PARK SENSOR BOTH CTR 1.0 EA 429.90 10 386.91 S
240704528R HARNESS- BUMPER FRT 1.0 EA 152.20 10 136.98 S
256685474R AIR INTAKE HOSE, BUM 1.0 EA 105.80 10 95.22 S
620901789R BUMPER FRT CENTER IN 1.0 EA 122.10 10 109.89 S
7703101446 FENDER SCREW 10.0 EA 5.60 10 50.40 S 620347326R BUMPER BRACKET FRT R 1.0 EA 104.50 10 94.05 8



SERVICE TAX INVOICE

0 - A00005 SL: AXA INSURANCE PTE LTD AXA INSURANCE PTE LTD GST Reg.No:M28920628X Inv.No. . : B&P 7015297 Page 3 8 SHENTON WAY. Inv.date. : 29/01/2019 #27-01 AXA TOWER. SINGAPORE 068811 WIP No. . : 39237 Veh.In/Out: 05/12/2018 14/01/2019 *Tel.No. . : 6338 7288 Reg.No. . : SLU1207L Reg.date. : 23/11/2017 Closed by : Derek Oh Siong Wee Mileage . : 20,868 Svc Consultant : ACC Chassis No: VF1RFA00158580930 Remarks : Mr Goh Koon Wee Parts/Op.No Description Mech Qty Price Disc% Pkg Amount G 172.17 S 738.54 S 191.30 10 261520089R FOG LAMP MOULDING OU 1.0 EA 625005785R GRILLA PANEL INNER A 1.0 EA 820.60 10 1.0 EA 59.80 10 53.82 S 1.0 EA 75.40 10 67.86 S 1.0 EA 622359016R EQUERRE G F 622349675R EQUERRE D F 620100101R ADHESIVE SEALER FL2 1.0 EA 549.10 10 494.19 S

			Gross Total.	10,250.27
Labour Parts Package	Total	3,545.00 6,705.27 0.00	Net GST @ 7.0% Total Paid Please Pay	10,250.27 717.52 10,967.79 0.00 10,967.79

GST: S=StdRated; O=OutOfScope; Z=ZeroRated Enquiries must be lodged within 14 days from the invoice date This is a computer generated invoice. No signature is required.



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Auton	nobile
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM1802	1148/R1pb3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE HO		Date: 24-10-2019 Code: ASM		
1.		Policy Particula	ars :- THIRD PARTY CLAI	IM
	Insured Veh.	SKD 3107E	Veh. Inspected	SLU 1207L
	Policy No.	P1929461	Coverage (\$)	0.00
	Claim No.	S8M013TV	Excess (\$)	0.00
	Assign From	WINNIE HO	Assign Date	22/11/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	RENAULT GRAND SCENIC	1.5 c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VF1RFA00158580930	Colour	WHITE
	Odometer	20833	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
i.	General	FAIR		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/55 R20	CONTINENTAL	6 mm
	L/H Front Tyre	195/55 R20	CONTINENTAL	6 mm
	R/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm
	L/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm
4.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	N/S FRONT PORTION.	
	DAMAGES SEE D			
5.			eral Information	
	Accident Date	16/11/2018	Inspection Date	05/12/2018
	Survey held at			
		249 ALEXANDRA ROAD SINGAPORE 159935		
5a.	ALCO DE LA COMPANION DE LA COM		Remarks	

Estimate Days of Repair

8 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1207L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER LOWER GS4 (SN) (CONSISTENT)	SCRATCHED	356.20	320.58
1	BUMPER FRT GS4 (SN) (CONSISTENT)	DEFORMED	1,165.50	1,048.95
1	BUMPER FRT CENTER IN (SN) (CONSISTENT)	BENT	122.10	109.89
1	BUMPER BRACKET FRT R (SN) (CONSISTENT)	BENT	104.50	94.05
1	BUMPER BRACKET FRT L (SN) (CONSISTENT)	NECESSARY	104.50	94.05
1	COVERGENT AIR KIT S (SN) (CONSISTENT)	SERVICEABLE	114.90	,
1	FOG LAMP MOULDING OU (SN) (CONSISTENT)	CRACKED	191.30	172.17
1	FOG LAMP COVER CHROM (SN) (CONSISTENT)	CRACKED	191.30	172.17
1	BUMPER FRT SUPPORT B (SN) (CONSISTENT)	NECESSARY	91.80	82.62
1	BUMPER FRT TOP INNER (SN) (CONSISTENT)	SERVICEABLE	560.90	
1	SUPPORT BRACKET, HEA (SN) (CONSISTENT)	NECESSARY	59.94	59.94
1	SUPPORT BRACKET, HEA (SN) (CONSISTENT)	NECESSARY	59.94	59.94
1	BUMPER FRT REINFORCE (SN) (CONSISTENT)	SERVICEABLE	510.00	22000
1	FENDER FRT LH GS4 (SN) (CONSISTENT)	DEFORMED	512.70	461.43
1	BRACKET, FENDER FRT (SN) (CONSISTENT)	NECESSARY	88.29	88.29
1	FENDER BRACKET FRT L (SN) (CONSISTENT)	NECESSARY	80.91	80.91
1	WHEEL ARCH - FRT LH (SN) (CONSISTENT)	DEFORMED	204.60	184.14
10	WHEEL ARCH CLIP J5AL (SN) (CONSISTENT)	NECESSARY	53.00	47.70
1	HEADLAMP LH R9A3 GS4 (SN) (CONSISTENT)	CRACKED	677.30	609.57
1	ALLOY RIM 20" R9A3 S (SN) (CONSISTENT)	SCRATCHED	887.76	887.76
1	TYRE PRESSURE SENSOR (SN) (CONSISTENT)	NECESSARY	119.10	107.19
1	ADHESIVE SEALER FL2 (SN) (CONSISTENT)	NECESSARY	549.10	494.19
1	FOG LAMP LH/RH S3/ M (SN) (CONSISTENT)	SERVICEABLE	185.50	
4	PARK SENSOR BOTH CTR (SN) (CONSISTENT)	NECESSARY 1PC ONLY	1,719.00	386.91
1	HARNESS - BUMPER FRT (SN) (CONSISTENT) (ADDITIONAL)	SHORTED	136.98	136.98
1	AIR INTAKE HOUSE, BUM (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	95.22	95.22
1	FENDER SCREW (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	50.40	50.40
1	GRILLA PANEL INNER A (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	738.54	738.54

Report Ref No. CC4/ASM18021148/R1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BUMPER FRT CENTRE IN (SN) (CONSISTENT) (ADDITIONAL)	REPEATED	109.89	
1	EQUERRE G F (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	53.82	53.82
1	EQUERRE D F (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	67.86	67.86
	2d 40.00 5000 5000 5000 5000 5000 5000 500	- Section Control	9,962.85	6,705.27
	LABOUR			
	TO REPLACE FRONT BONNET, FRT BUMPER, FRT BRACKET, FRT LH HEADLAMP, FRT LH FENDER, FRT WHEEL ARCH, ETC.		2,250.00	1,575.00
	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, ETC.		1,600.00	1,200.00
	TO REPLACE FRONT LH RIM.		50.00	50.00
	COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO FOCUS HEADLAMP.		110.00	110.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		330.00	330.00
			4,620.00	3,545.00
7	GRAND TOTAL		14,582.85	10,250.27

RECOMMENDED COST OF REPAIRS	10,250.27
-----------------------------	-----------

Report Ref No. CC4/ASM18021148/R1pb3s2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.