

in 05/12/18

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4

#35-183

Singapore 122312

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 20/11/2018

WIP No. : 39237

Veh.In/Out: 20/11/2018

*Tel.No. : Mobile: 86688082

Reg.No. : SLU1207L

Reg.date : 23/11/2017

Mileage : 0

Chassis No: VF1RFA00158580930

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Goh Koon Wee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BONNET, FRT BUMPER, FRT BRACKET, FRT LH HEADLAMP, FRT LH FENDER, FRT WHEEL ARCH, ETC	0	2250.00	0		2,250.00 S	1575
800	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, ETC	0	1600.00	0		1,600.00 S	1200
0031	TO REPLACE FRONT LH RIM	0	50.00	0		50.00 S	
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00 S	
280	TO FOCUS HEADLAMP	0	110.00	0		110.00 S	
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00 S	
RESETTING OF ALL ELECTRICAL MODULES							
	BUMPER LOWER GS4	1.0 EA	356.20			356.20 S	320.58
	BUMPER FRT GS4	1.0 EA	1165.50			1,165.50 S	1048.95
	BUMPER FRT CENTER IN	1.0 EA	122.10			122.10 S	109.89
	BUMPER BRACKET FRT R	1.0 EA	104.50			104.50 S	94.05

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4

#35-183

Singapore 122312

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Goh Koon Wee

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 20/11/2018

WIP No. : 39237

Veh.In/Out: 20/11/2018

*Tel.No. : Mobile: 86688082

Reg.No. : SLU1207L

Reg.date. : 23/11/2017

Mileage : 0

Chassis No: VF1RFA00158580930

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BUMPER BRACKET FRT L	1.0 EA	104.50	104.50	S	94.05	
CONVERGENT AIR KIT S	1.0 EA	114.90	114.90	S	X	
FOG LAMP MOULDING OU	1.0 EA	191.30	191.30	S	172.17	
FOG LAMP COVER CHORM	1.0 EA	191.30	191.30	S	172.17	
BUMPER FRT SUPPORT B	1.0 EA	91.80	91.80	S	82.62	
BUMPER FRT TOP INNER	1.0 EA	560.90	560.90	S	X	
SUPPORT BRACKET, HEA	1.0 EA	38.90	38.90	S	59.94	
SUPPORT BRACKET, HEA	1.0 EA	38.90	38.90	S	59.94	
BUMPER FRT REINFORCE	1.0 EA	510.00	510.00	S	X	
FENDER FRT LH GS4	1.0 EA	512.70	512.70	S	461.43	
BRACKET, FENDER FRT	1.0 EA	85.30	85.30	S	88.29	
FENDER BRACKET FRT L	1.0 EA	78.20	78.20	S	80.91	
WHEEL ARCH - FRT LH	1.0 EA	204.60	204.60	S	184.14	
WHEEL ARCH CLIP J5AL	10.0 EA	5.30	53.00	S	47.70	
HEADLAMP LH R9A3 GS4	1.0 EA	677.30	677.30	S	609.57	
ALLOY RIM 20" R9A3 S	1.0 EA	558.00	558.00	S	887.76	
TYRE PRESSURE SENSOR	1.0 EA	119.10	119.10	S	107.19	

SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC
 Mr Goh Koon Wee
 Blk 312B Clementi Avenue 4
 #35-183

Singapore 122312

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Goh Koon Wee

GST Reg.No:M28920628X
 Inv.No. . : B&P . 0 Page 3
 Inv.date. : 20/11/2018
 WIP No. . : 39237
 Veh.In/Out: 20/11/2018
 *Tel.No. . : Mobile: 86688082
 Reg.No. . : SLU1207L
 Reg.date. : 23/11/2017
 Mileage . : 0
 Chassis No: VF1RFA00158580930

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

ADHESIVE SEALER FL2	1.0 EA	549.10				549.10 S	494.19 ✓
FOG LAMP LH/RH S3/ M	1.0 EA	185.50				185.50 S	X
PARK SENSOR BOTH CTR	4.0 EA	429.90				1,719.60 S	386.91 ✓

Resul

Hp 90010068

8 days

05/12/18 @ 1430

Recovery by paint

Gross Total.	12,953.20
Net.....	12,953.20
GST @ 7.0%	906.72
Total.....	13,859.90
Paid.....	0.00
Please Pay..	13,859.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Labour Total	4,620.00
Parts Total	8,333.20
Package Total	0.00

- = Supp.
- ① Harness-Bumper Fit \$136.98 ✓ Shunted
 - ② Air Intake Hose, Bum \$ 95.22 ✓ CRA
 - ③ Tender Screw \$ 50.40 ✓ nee
 - ④ Gonna Panel Inner A \$ 738.54 ✓ CRA
 - ⑤ Equerre G F \$ 53.82 ✓ CRA
 - ⑥ " D F \$ 67.86 ✓ CRA