

✓  
in 051218

### SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4

#35-183

Singapore 122312

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 20/11/2018

WIP No. . : 39237

Veh.In/Out: 20/11/2018

\*Tel.No. . : Mobile: 86688082

Reg.No. . : SLU1207L

Reg.date .: 23/11/2017

Mileage .: 0

Chassis No: VF1RFA00158580930

Closed by .... : Derek Oh Siong Wee

Svc Consultant :

Remarks ..... : Mr Goh Koon Wee

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

802 TO REPLACE FRONT BONNET, FRT  
BUMPER, FRT BRACKET, FRT LH  
HEADLAMP, FRT LH FENDER, FRT  
WHEEL ARCH, ETC

0

2250.00 0

2,250.00 S

1575

800 TO PUTTY SPRAY PAINT ON FRT  
BONNET, FRT BUMPER, FRT LH  
FENDER, ETC

0

1600.00 0

1,600.00 S

1200

0031 TO REPLACE FRONT LH RIM

0

50.00 0

50.00 S

419 COMPUTERISED WHEEL ALIGNMENT

0

280.00 0

280.00 S

280 TO FOCUS HEADLAMP

0

110.00 0

110.00 S

280 TO CHECK WIRING INCLUDE

0

330.00 0

330.00 S

RESETTING OF ALL ELECTRICAL  
MODULES

BUMPER LOWER GS4

1.0 EA

356.20

356.20 S

BUMPER FRT GS4

1.0 EA

1165.50

1,165.50 S

BUMPER FRT CENTER IN

1.0 EA

122.10

122.10 S

BUMPER BRACKET FRT R

1.0 EA

104.50

104.50 S

### SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4

#35-183

Singapore 122312

Closed by .... : Derek Oh Siong Wee

Svc Consultant :

Remarks ..... : Mr Goh Koon Wee

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 20/11/2018

WIP No. . : 39237

Veh.In/Out: 20/11/2018

\*Tel.No. . : Mobile: 86688082

Reg.No. . : SLU1207L

Reg.date. : 23/11/2017

Mileage . : 0

Chassis No: VF1RFA00158580930

| Op.No | Description                     | Mech Qty | Price  | Disc% | Pkg | Amount | G |
|-------|---------------------------------|----------|--------|-------|-----|--------|---|
|       | BUMPER BRACKET FRT L <i>Ne</i>  | 1.0 EA   | 104.50 |       |     | 104.50 | S |
|       | CONVERGENT AIR KIT S <i>?</i>   | 1.0 EA   | 114.90 |       |     | 114.90 | S |
|       | FOG LAMP MOULDING OU <i>?</i>   | 1.0 EA   | 191.30 |       |     | 191.30 | S |
|       | FOG LAMP COVER CHORM <i>Ch</i>  | 1.0 EA   | 191.30 |       |     | 191.30 | S |
|       | BUMPER FRT SUPPORT B <i>Ne</i>  | 1.0 EA   | 91.80  |       |     | 91.80  | S |
|       | BUMPER FRT TOP INNER <i>?</i>   | 1.0 EA   | 560.90 |       |     | 560.90 | S |
|       | SUPPORT BRACKET, HEA <i>Ne</i>  | 1.0 EA   | 38.90  |       |     | 38.90  | S |
|       | SUPPORT BRACKET, HEA <i>Ne</i>  | 1.0 EA   | 38.90  |       |     | 38.90  | S |
|       | BUMPER FRT REINFORCE <i>?</i>   | 1.0 EA   | 510.00 |       |     | 510.00 | S |
|       | FENDER FRT LH GS4 <i>De</i>     | 1.0 EA   | 512.70 |       |     | 512.70 | S |
|       | BRACKET, FENDER FRT <i>Ne</i>   | 1.0 EA   | 85.30  |       |     | 85.30  | S |
|       | FENDER BRACKET FRT L <i>Ne</i>  | 1.0 EA   | 78.20  |       |     | 78.20  | S |
|       | WHEEL ARCH - FRT LH <i>De</i>   | 1.0 EA   | 204.60 |       |     | 204.60 | S |
|       | WHEEL ARCH CLIP J5AL <i>Ne</i>  | 10.0 EA  | 5.30   |       |     | 53.00  | S |
|       | HEADLAMP LH R9A3 GS4 <i>Ch</i>  | 1.0 EA   | 677.30 |       |     | 677.30 | S |
|       | ALLOY RIM 20" R9A3 S <i>XSC</i> | 1.0 EA   | 558.00 |       |     | 558.00 | S |
|       | TYRE PRESSURE SENSOR <i>X</i>   | 1.0 EA   | 119.10 |       |     | 119.10 | S |

### SERVICE ESTIMATE

93167 - C00001 SL: SERVICE SALES - PC

Mr Goh Koon Wee

Blk 312B Clementi Avenue 4  
#35-183

Singapore 122312

Closed by .... : Derek Oh Siong Wee

Svc Consultant :

Remarks ..... : Mr Goh Koon Wee

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 20/11/2018

WIP No. . : 39237

Veh.In/Out: 20/11/2018

\*Tel.No. . : Mobile: 86688082

Reg.No. . : SLU1207L

Reg.date. : 23/11/2017

Mileage . : 0

Chassis No: VF1RFA00158580930

| Op.No | Description                   | Mech Qty | Price  | Disc% | Pkg | Amount   | G |
|-------|-------------------------------|----------|--------|-------|-----|----------|---|
|       | ADHESIVE SEALER FL2 <i>m</i>  | 1.0 EA   | 549.10 |       |     | 549.10   | S |
|       | FOG LAMP LH/RH S3/ M <i>?</i> | 1.0 EA   | 185.50 |       |     | 185.50   | S |
|       | PARK SENSOR BOTH CTR <i>?</i> | 4.0 EA   | 429.90 |       |     | 1,719.60 | S |

*Resul*  
*Hp 90010068*  
*8 days*  
*05/12/18 @ 1430*  
*Reswing by paint*

|               |          |  |              |           |
|---------------|----------|--|--------------|-----------|
|               |          |  | Gross Total. | 12,953.20 |
| Labour Total  | 4,620.00 |  | Net.....     | 12,953.20 |
| Parts Total   | 8,333.20 |  | GST @ 7.0%   | 906.72    |
| Package Total | 0.00     |  | Total.....   | 13,859.90 |
|               |          |  | Paid.....    | 0.00      |
|               |          |  | Please Pay.. | 13,859.90 |

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated