



STUTTGART AUTO PTE LTD  
27A TANJONG PENJURU, SINGAPORE 609042  
ESTIMATE COST OF REPAIRS



PORSCHE

<b>LONPAC INSURANCE BHD</b>		<b>NAME :</b> Ms Namrata Singh	<b>WIP :</b> 39859
101 THOMSON ROAD		<b>ADDRESS :</b> 16 Balmoral Park	<b>EXCESS :</b>
#19-00 SHAW TOWER		#01-12	<b>DATE:</b> 22.11.2018
SINGAPORE 189702		Singapore 259847	
<b>ATTN. :</b>	MOTOR CLAIMS	<b>TEL :</b>	
<b>FAX :</b>			

<b>VEH NO :</b>	SKB2025A	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	EVA	63310683
<b>CHASSIS NO :</b>	WP0ZZZ97ZJL108061	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	TP	
<b>MODEL :</b>	Porsche Panamera PDK	<b>DATE REG.:</b>	29.12.2017	<b>POLICY NO. :</b>		

**NATURE OF WORKS**

S/NO	Parts Description	QTY	REVISED	PRICES
1	HEAT SHIELD RH <i>BT B/</i>	1		\$ 147.10
2	REAR BUMER <i>at</i>	1		\$ 2,371.40
3	BUMPER SOUND ABSORBER LH <i>X</i>	1		\$ 289.30
4	BUMPER SOUND ABSORBER RH <i>?</i>	1		\$ 289.30
5	BUMPER SPOILER <i>DE</i>	1		\$ 1,024.60
6	TAIL PIPE COVER LH <i>X</i>	1		\$ 160.10
7	TAIL PIPE COVER RH <i>CR/</i>	1		\$ 160.10
8	SENSOR OUTER <i>?</i>	1		\$ 227.60
9	SENSOR INNER <i>?</i>	1		\$ 227.60
10	SENSOR GASKET <i>na</i>	2		\$ 5.00
11	BLIND RIVET <i>na</i>	6		\$ 10.20
12	REAR BUMPER SUPPORT LOWER <i>X</i>	1		\$ 52.60
13	REINFORCEMENT <i>?</i>	1		\$ 941.10
14	TAILGATE <i>X</i>	1		\$ 4,303.30
15	WATER DRAIN STRIP <i>X</i>	1		\$ 54.10
16	STOPPER <i>X</i>	7		\$ 23.10
20	CAVITY PRESERVATION <i>X</i>	1		\$ 80.30
21	SEALANT (W736) <i>X</i>	1		\$ 58.40
24	DECORATIVE FILM BLACK <i>X</i>	1		\$ 38.40
25	FASTENING SCREW <i>X</i>	2		\$ 1.40
27	EXPANSION RIVET <i>X</i>	10		\$ 85.00
28	REAR WINDSCREEN <i>X</i>	1		\$ 1,831.40
29	(AH04) ADHESIVE SET <i>X</i>	1		\$ 346.90
30	GROMMET <i>X</i>	1		\$ 10.80
31	LOGO - "PANAMERA" <i>X</i>	1		\$ 156.70
32	BUMPER REFLECTOR RH <i>CR/</i>	1		\$ 73.90
33	SENSOR, LINE CONTROL UNIT REAR LID OPEN <i>X</i>	1		\$ 195.10
34	REAR MUFFLER RH <i>BT</i>	1		\$ 2,850.80
35	REAR MUFFLER LH <i>? photo</i>	1		\$ 2,850.80
36	HEXAGON-HEAD BOLT <i>u</i>	4		\$ 7.20
37	SUPPORT <i>na</i>	2		\$ 112.20
38	TAIL PIPE RH <i>PA</i>	1		\$ 729.20
39	HEXAGON-HEAD BOLT <i>na</i>	4		\$ 7.20
40	CLAMPING SLEEVE EXHAUST SYSTEM (WB43) <i>na</i>	2		\$ 171.20

		TOTAL PARTS		\$ 19,893.40
		LESS 10%		\$ 1,989.34
		TOTAL PARTS COST		\$ 17,904.06
		<b>Labour Description</b>		
1	TO REMOVE / REPLACE TAILGATE, REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560		\$ <del>6,240.00</del>
2	TO RESPRAY TAILGATE & REAR BUMPER.	1300		\$ <del>2,500.00</del>
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ <del>X</del> 250.00
4	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT		\$ 1,560.00
5	TO TRANSFER THE TAILGATE MECHANISM.	NETT		\$ <del>X</del> 780.00
6	TO REMOVE & REPLACE REAR WINDSCREEN GLASS.	NETT		\$ <del>X</del> 560.00
7	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	NETT		\$ <del>X</del> 195.00
8	TO SUPPLY SOLAR FLIM ON THE REAR WINDSCREEN GLASS.	NETT		\$ <del>X</del> 300.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ <del>100</del> 250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT		\$ <del>480</del> 600.00
11	SUNDRIES.	NETT		\$ <del>30</del> 50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$ -	\$ 13,285.00
TOTAL PARTS	\$ -	\$ 17,904.06
TOTAL	\$ -	\$ 31,189.06
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

Rasul  
Hp 90010068  
4 days  
23/11/18 @ 1050  
Resurvey & paint