

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

FINAL REPAIR BILL : SKC 2071 K

Vehicle & Document Information

Date: 06/12/2018
 Vehicle No: SKC 2071 K
 Make/Model: TOYOTA CAMRY

S/N	Description	Qty	Repairer's Est	Revised Est
1	RH SIDE MIRROR SET	1	\$ 1,053.20	\$ 1,053.20
2	RHF DOOR	1	\$ 1,348.00	\$ 1,348.00
3	RHF DOOR PROTECTOR STRIP	1	\$ 136.00	\$ 136.00
4	RHF DOOR PROTECTOR CHROME	1	\$ 53.00	\$ 53.00
5	RHF FENDER	1	\$ 890.00	\$ 890.00
6	RHF FENDER EMBLEM (VVT-I)	1	\$ 68.00	\$ 68.00
7	RHF FENDER BRACKET	1	\$ 70.00	\$ 70.00
8	RHF HEADLAMP	1	\$ 1,150.00	\$ 1,150.00
9	RHF FOG LAMP CHROME	1	\$ 90.00	\$ 90.00
10	FRONT BONNET	1	\$ 1,637.00	\$ 1,637.00
11	RHF WHEEL ARCH PROTECTOR	1	\$ 170.00	\$ 170.00
12	RHF WHEEL ARCH PROTECTOR CLIPS	15	\$ 120.00	\$ 120.00
13	RHF RIM	1	\$ 150.00	\$ 150.00

Parts Total : \$ 6,935.20
 -25% \$ 1,733.80
Total : \$ 5,201.40

1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	\$ 60.00
1	TO CHECK LIGHTING, WIRING & FUSES	\$ 20.00
1	LABOUR TO DISMANTLE FRONT PARTS, REPLACE & RE-ALIGN	\$ 550.00
1	4 WHEEL COMPUTERIZED ALIGNMENT AND WHEEL BALANCING	\$ 60.00
1	TO PUTTY, PRIMER, RE-SPRAY, RHF DOOR INNER, OUTER, FRONT BUMPER, RHF FENDER INNER, OUTER, BONNET INNER, OUTER AND SIDE MIRROR	\$ 1,200.00
1	ALIGNMENT	\$ 60.00

Labour Total : \$ 1,950.00

TOTAL :	\$ 7,151.40
-20%	\$ 1,430.28
GRAND TOTAL :	\$ 5,721.12
LUMP SUM :	\$ 5,750.00

CHUAN HO AUTO SERVICE

