

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1327/2018/GW
Date : 22-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ong Choon Teck
Address : 100 Springside Avenue
Singapore 786494
Telephone : HP +65 96713972
Type of Claim : Own Damage Claim
Policy No. : 2100334516-05
Vehicle No : **SKJ 6958 P**
Model Code : Audi Q3 2.0 TFSI QU
Model / Year : Apr-13
Engine No : CCZ 264221
Chassis No : WAUZZZ8U1CR055501
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Nov-18
Place of Accident : Junct of Tagore Lane & Tagore Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKJ 6958 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To suspend engine . To dismantle front suspension assy . To inspect any further damages and renew accordingly .	S/N \$ 2,800.00 ? x
3	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1000.
4	To respray front bumper, lhs front fender and LHS front door .	\$ 2,400.00 1650.
5	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
5	To carry out diagnostic checks.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>8,674.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 6958 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,754.00	✓
2	FRONT BUMPER SPOILER <i>Deland</i>	\$ 333.00	✓
3	FRONT BUMPER TRIM-LH <i>new</i>	\$ 21.00	✓
4	FRONT BUMPER CLOSING ELEMENT-LOWER <i>new</i>	\$ 151.00	✓
5	FRONT BUMPER AIR GUIDE GRILLE-LH <i>Missing</i>	\$ 103.00	✓
6	FRONT BUMPER BRACE-LH LOWER ?	\$ 48.00	?
7	FRONT BUMPER BRACE-LH UPPER ?	\$ 58.00	?
8	FRONT BUMPER SUPPORT ?	\$ 22.00	?
9	FRONT FENDER-LH <i>Distorted</i>	\$ 796.00	✓
10	FRONT FEDNER ATTACHMENT PARTS-LH <i>new</i>	\$ 60.00	✓
11	FRONT FENDER BRACKET-LH ? <i>Best</i>	\$ 72.00	✓
12	FRONT FENDER BRACE-LH	\$ 92.00	✓
13	FRONT WHEEL HOUSING LINER-LH <i>Deland</i>	\$ 215.00	✓
14	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 132.00	?
15	FRONT WHEEL SPOILER-LH ?	\$ 96.00	?
16	HEADLIGHT MOUNTING-LH ?	\$ 103.00	?
17	HEADLIGHT -LH ?	\$ 1,819.00	?
18	HEADLIGHT RETAINING PLATE-LH ?	\$ 76.00	?
19	HOLOGEN FOG LAMP-LH <i>new</i>	\$ 224.00	✓
20	FRONT WHEEL COVER-LH <i>new</i>	\$ 227.00	✓
SUB - TOTAL SPARE PARTS :		<u>\$ 6,402.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 6958 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
21	WHEEL COVER SOUL(BLACK) <i>new</i>	\$ 227.00	✓
22	FRONT ALUMINIUM RIM-LH <i>cut</i>	\$ 687.00	✓
23	RUBBER VALVE <i>Not new</i>	4 \$ 12.00	x.
24	FRONT HEADLIGHT LIFT CYLINDER-LH <i>new new</i>	\$ 184.00	✓
25	FRONT WISHBONE ?	\$ 445.00	?
26	HEX COLLARED BOLT ?	\$ 13.00	?
27	WHEEL BEARING HOUSING - LH ?	\$ 519.00	?
28	BALL SCREW ?	4 \$ 40.00	?
29	BOLT ?	\$ 13.00	?
30	GUIDE JOINT - LH ?	\$ 111.00	?
31	GAS SHOCK ABSORBER ?	\$ 275.00	?
32	DEEP GROVE BALL THRUST BEARING ?	\$ 41.00	?
33	RUBBER STOPPER FOR ABSORBER ?	\$ 32.00	?
34	COUPLIG ROAD ?	\$ 85.00	?
35	WHEEL BEARING WITH ASSEMBLY ?	\$ 397.00	?
36	FRONT DRIVESHAFT - LH <i>Not new</i>	\$ 2,192.00	x
37	WHEEL BEARING CENTRE SHAFT BOLT ?	\$ 13.00	?
38	DRIVESHAFT PROTECTIVE CAP ?	\$ 16.00	?
39	DEEP GROVE BALL THRUST BEARING ?	\$ 41.00	?
40	SUSPENSION TOP MOUNTING ?	\$ 85.00	?
SUB TOTAL PARTS CHARGES		\$ 5,428.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKJ 6958 P

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	DEEP GROVE BALL THRUST BEARING ?	\$ 41.00	?
42	TRACK ROD ?	\$ 82.00	?
43	TIE ROD END - LH ?	\$ 113.00	?
44	SUNDRIES ?	\$ 300.00	?
TOTAL LABOUR CHARGES		: \$ 12,366.00	
TOTAL LABOUR CHARGES		: \$ 8,674.00	
GRAND TOTAL		: \$ 21,040.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Li
Surveyed Date : 22/11/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 06 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant