

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1231/2018/GW
Date : 27-Oct-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ho Shu-Min
Address : 1 Youngberg Terrace
#12-07
Singapore 357741
Telephone : HP +6593633048
Type of Claim : Own Damage Claims
Policy No. : 1800076240
Vehicle No : **SLJ 1784 U**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 938231
Chassis No : WAUZZZ8V4J1066061
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Oct-18
Place of Accident : Park Green Condo

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 1784 U

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To renew lhs 1/4 galss and rear windscreen to facillitate fender renewal.	S/N 600.00 ✓
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓
4	To dislodge and reinstall rear wire harness for lighs, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓
5	To remove and reinstall rear seat, back rest, hat tray, acbd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓
6	To dismantle lhs rear door, rear bumper and rear lid. Cut out and weld lhs rear fender. Repair outer wheel house. Renew lhs rear door and align to position. Reinstall all parts removed.	S/N \$ 5,400.00 3500
SUB- TOTAL LABOUR CHARGES		: \$ 9,360.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 1784 U.

S/n	Nature of Jobs	Estimated Charges
8	To respray lhs rear door, lhs rear fender, lhs sill panel, door entrances, drain channel and end panelling. To carry out join sealant work and stone chip treatment.	\$ 4,100.00 2200 ✓
9	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓
10	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 13,932.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 1784 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR DOOR-LH <i>Dented</i>	TBC	✓
2	REAR DOOR OUTER SEAL-LH <i>Neu</i>	\$ 139.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	REAR DOOR CATCH-LH <i>Neu</i>	\$ 82.00	✗
6	REAR DOOR ATTACHEMENT PARTS-LH <i>?</i>	\$ 110.00	?
7	REAR DOOR HANDLE-LH <i>Reps</i>	\$ 207.00	✗
8	REAR DOOR CATCH COVER-LH <i>Neu</i>	\$ 14.00	✗
9	REAR DOOR UPPER HINGE HALF-LH <i>?</i>	\$ 72.00	✗
10	REAR DOOR MOUNTING BAR-LH <i>Neu</i>	\$ 143.00	✗
11	REAR DOOR GUIDE RAIL-LH <i>Neu</i>	\$ 45.00	✗
12	REAR FENDER-LH <i>Distorted</i>	\$ 2,006.00	✓
13	REAR WHEEL HOUSING LINER-LH <i>Neu</i>	\$ 215.00	✗
14	REAR SIDE WINDOW-LH <i>Neu</i>	\$ 502.00	✓
15	REAR WINDOW <i>Neu</i>	\$ 704.00	✓
16	PRIMER <i>Neu</i>	\$ 37.00	✓
17	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>Neu</i>	2 \$ 28.00	✗
18	REAR BUMPER LOCKING MECHANISM	2 \$ 50.00	✗
19	REAR ALUMINIUM RIM-LH <i>Cut</i>	\$ 659.00	✓
20	SOUND ABSROBER <i>Neu</i>	2 \$ 216.00	✗
SUB- TOTAL SPARE PARTS CHARGES		\$ 5,336.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 1784 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	ACRYLIC SEALANT	S/N \$ 180.00 ✓	
22	CAVITY WAX	S/N \$ 140.00 ✓	
23	STONE CHIPS	S/N \$ 180.00 ✓	
24	METAL FILLER POWDER	S/N \$ 280.00 ✓	
25	1/4GLASS SEALANT	S/N \$ 100.00 ✓	
26	REAR WINDSCREEN SEALANT	S/N \$ 200.00 ✓	
27	SUNDRIES	\$ 800.00	
TOTAL SPARE PARTS CHARGES		: \$ 7,216.00	
TOTAL LABOUR CHARGES		: \$ 13,932.00	
GRAND TOTAL		: \$ 21,148.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *22/11/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 13 days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant