

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1353/2018/PH
Date : 22-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Siew Hwa
Address : 80 Jollicoe Road
#11-12
Singapore 208766
Telephone : (HP) 91158554
Type of Claim : Own Damage Claims
Policy No. : 2100443165-02
Vehicle No : **SKX 5508 M**
Model Code : Audi A3 SB 1.4 TFSI
Model / Year : Dec-15
Engine No : CZC 501632
Chassis No : WAUZZZ8V7GA067472
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Nov-18
Place of Accident : Jalan Besar Road Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5508 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper assy. Repair bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray front bumper and bonnet.	\$ 1,400.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES - FRONT		: \$ <u>3,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5508 M.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>Repis</i>	\$ 1,613.00	X
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 161.00	X
4	PULL STRAP <i>3 new</i>	4 \$ 175.00	X
5	AIR GUIDE GRILLE - LH	\$ 95.00	✓
6	AIR GUIDE GRILLE SATIN BLACK/CHROME - RH <i>new</i>	\$ 95.00	✓
7	RADIATOR GRILLE <i>could</i>	\$ 573.00	✓
8	COVER FOR RADIATOR GRILLE ?	\$ 86.00	?
9	COVER FOR FOAM FILLER PIECE <i>new ?</i>	\$ 48.00	?
10	FOAM FILLER PIECE <i>new ?</i>	\$ 71.00	?
11	REINFORCEMENT BEAM <i>new ?</i>	\$ 633.00	?
12	CAUTION' STICKER <i>new</i>	\$ 12.00	✓
13	FRONT NO. PLATE <i>3rd</i>	S/N \$ 25.00	✓
14	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 3,887.00	
TOTAL LABOUR CHARGES		: \$ 3,152.00	
GRAND TOTAL		: <u>\$ 7,039.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Lij
22/11/18

Authorised Repairs, 03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant