



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

22/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPM
VIC

NRCS 711-610434737

Accident date: 21/11/2018

Estimated repair cost for vehicle no: SLC1627C TOYOTA ALTIS 1.6 A '16

S/n	Qty	Items	U/price	Amount
1	2	Front Head Lamp LHud	\$1976.50	\$ 3953
2	2	Front Head Lamp Chrome LH rhr	\$196.20	\$392.40
3	1	Front Grille Assy Lrt		\$564.20
4	1	Front Grille Emblem Logo Key		\$43.10
5	1	Front Bumper Rep. Deformed.		\$581.10
6	10	Front Bumper Clip Nec	\$6.50	\$65.00
7	2	Front Bumper Side Retainer rhr.	\$65.50	\$131.00
8	1	Front Bumper Number Plate		\$50.00
9	1	Front Bumper Reinforcement		\$379.20
10	1	Front Bumper Inner Sponge		\$172.45
11	1	Front Support Panel		\$977.60
12	1	Front Support Panel Top Cover		\$125.10
13	10	Front Support Panel Top Cover Clip	\$6.50	\$65.00

Subtotal :- \$6,246.95

3457.40

2593.05

Labour charges

To remove & refit air-con condenser, radiator, fan motor
& top up gas

\$380.00 +

To check wiring

~~\$60.00~~ 40

Tuff Kote

640

\$100.00 +

Panel beating

~~\$850.00~~ 350.

Spray painting

~~\$750.00~~ 250

Subtotal :- \$2,140.00

Total:- \$7,157.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
L/S 22/11/18
03 Aug

total: 8133.05
L/S 2-6K

26K 030