

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 28 Nov 2018

Preliminary Advice

Insured Vehicle No	: YM2734M		
TP Vehicle No	: SKK5725X	Accident Date	: 22/11/2018
Make	: VOLKSWAGEN GOLF	Assignment Date	: 22/11/2018
Date of Inspection	: 23/11/2018	Est. Duration of Repair	: 5 days
Inspection At	: Carz Auto Services Pte Ltd - Woodlands (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047 Singapore 757047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,397.56
Revised Amount	:S\$	5,613.93
Check Items (Estimated)	:S\$	11,122.03
Total	:S\$	16,735.96

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP