



Your Ref: 5578402597SG-005

Date: 03rd December 2018

Our Ref: CS1/AIG18021197/Bvbs2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16

Chartis Building

Singapore 079120

(The Motor Claims Department)

Attn: Bennie Tan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO.:
SBS 7597A INSURED VEHICLE NO: EY 300T ACCIDENT ON 14/09/2017**

We thank you for your instruction on 22/11/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SBS 7597A from M/s Vicom Ltd.
- b) Final Repair Bill of SBS 7597A from M/s Autoteam Engineering Pte Ltd.
- c) Colour damaged vehicle photographs of SBS 7597A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SBS 7597A
Make & Mode	: Volvo B9TL
Year of Registration	: 2011
Chassis Number	: YV3S4P921BA143676
Engine Capacity	: 9364 cc



2. Our finding is that the repair cost of \$12,088.22 (before GST) quoted by M/s SBS Transit Ltd is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.

Vehicle Inspection By:

L T G

LIM TEOW GUAN
Asst. Automotive Assessor

HO LEONG CHUAN
Automotive Assessor