

ASS. REC. BY:

REF: CS/FCU8021008 / Ntbn2

Special Instruction:

SUNVAPOR: N62

ASSIGNMENT (Office)

From (Person): CWB Karen Tan of FCL Date/Time: 23.11.2018 10:17am

Estimated Cost: Bill to:

OD / ~~FW~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 7381B Insured: SHC 79367

at Workshop m/s World Auto Tel: 6362 1776

of No. 1 Kranji Loop

Policy No: Claim No: D18008302MFSH

Sum Insured: Excess:

Make of Vch: D.O.A. 21.11.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 23.11.2018 10:51am Person Contacted: Anne Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLU 7381B - X
	SHC 79367 - NS / INC17007734 / Hlibn7
31.12 - @ 8:35pm -	Revised preli advise via email.

DOT: 12042017

REF:

REF:

FCI

Surveyor: NA 2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

26/3/19

FINALIZED PART BY PART REPAIR \$ 8,536.75 / 6 days
(Red: 12529.27: 50%)

RECEIVED 27 MAR 2019

Date/Time, File Pass to?

1) 27/3 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.Y. (\$ 8536.75)

☐ : Prelim Report

☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Veh No:

SU 73813

Yr Regn: 13 DEC 2017

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA Prius Hybrid 1.8 c.c. 1498

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

86,025

T/Radi: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU003564759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65 R15

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

WORLD AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR 0/S, 0/S

The U/C / Chassis frame / Body Structure affected due to collision

11x15=165

170+165

30

50+50

41

526



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008302MFSH

Date: 3/12/2018

Our Ref: CS/FCI18021236/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 7381L

Please be informed that we had conducted the inspection of the abovementioned vehicle
23/11/2018 at the premises of M/s World Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>21,066.02</u>
Revised Estimate Amount	: S\$ <u>9,664.25</u>
"Check" Items Amount	: S\$ <u>2,490.17</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front o/s and o/s



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Taufik
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-11-2018	Our Ref No. D18008302MFSH
Accident Date	22-11-2018	Claim Type. Third Party
Insured Vehicle	SHC7936T	Third Party Vehicle. SLU7381B
Survey Location	NO.1, KRANJI LOOP	
Contact Person.	AINEE	
Contact No.	63621776/ 0	Fax No. 63631250
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 3 December 2018 3:35 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008302MFSH/1
Attachments: PRELI ADVISED SLU 7381B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLU 7381B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 23 November 2018 10:32 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008302MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 November, 2018 10:07 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008302MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

WORLD AUTO PTE LTD

47 Jalan Pernimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000407

Date : 22/11/2018

Vehicle Num. : SLU 7381B(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 22/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	FRONT BUMPER
2.	1	FRONT HEADLAMP - RH
3.	1	FRONT FOG LAMP - RH
4.	1	FRONT BUMPER RETAINER RH
5.	1	FRONT FENDER RH
6.	1	FRONT FENDER HYBRID EMBLEM RH
7.	1	FRONT KNUCKLE - RH
8.	1	FRONT WHEEL HUB RH
9.	1/RH	FRONT STABILIZER LINK
10.	1/RH	FRONT STABILIZER BAR
11.	1/RH	DRIVE SHAFT
12.	1	FRONT SHOCK ABSORBER - RH
13.	1	FRONT LINKAGE - RH
14.	1	TIE ROD END RH
15.	1/RH	FRONT LOWER ARM
16.	1	SIDE SKIRT RH
17.	1	FRONT DOOR - RH
18.	1	FRONT DOOR GLASS REGULATOR MOTOR RH
19.	1	REAR DOOR SUB RUBBER SEAL
20.	1	REAR DOOR - RH
21.	1	REAR DOOR GLASS REGULATOR MOTOR LH
22.	1	REAR DOOR HINGE UPPER RH
23.	1	REAR DOOR HINGE LOWER RH
24.	1	REAR DOOR CHECKER RH
25.	1	REAR FENDER RH

List TotalS\$:

25.00% Discount S\$:

400	550.00	✓ CEX
	2,550.00	✓ SCR
500	950.00	✓ SCR
	110.00	✓ CEX
700	880.00	✓ DEF
	89.00	✓ NEC
	550.00	✓ XSVL
	560.00	✓ XSVL
	210.00	✓ XSVL
	360.00	✓ XSVL
	1,185.70	✓ XSVL
	420.00	✓ XSVL
	150.00	✓ XSVL
	160.00	✓ XSVL
	650.00	✓ XSVL
	430.00	✓ X R
1,300	1,450.00	✓ DEF
	450.00	✓ XSVL
	180.00	✓ DEF
1,300	1,450.00	✓ DEF
	450.00	✓ XSVL
	120.00	✓ XSVL
	120.00	✓ XSVL
	180.00	✓ XSVL
	950.00	✓ X R

15,154.70

3,788.68

11,366.02

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000407

Date : 22/11/2018

Vehicle Num. : SLU 7381B(LCR)

Make/Model : TOYOTA PRIUS HYBRID

Chassis/Eng# :

Accident Date : 22/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1	FRONT BUMPER CLIP	40.00	NFC
2.	1/RH	FRONT TYRE	280.00	XVC
3.	1/RH	FRONT WHEEL RIM	1,550.00	XSVL
4.	1	FRONT WHEEL CAP - RH	180.00	MIS
5.	1	SIDE SKIRT CLIPS	40.00	XNN
6.	1/RH	REAR TYRE	280.00	XVC
7.	1/RH	REAR WHEEL CAP	180.00	SCR
8.	1/RH	REAR WHEEL RIM	1,550.00	XSVL
Special Nett Total S\$:			4,100.00	400
LABOUR :				
FRT & BACKCOMPUTERISED ALIGNMENT			360.00	160 80
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.			180.00	80
TRANSFER DOOR MECHANISM (X2 DOORS)			360.00	100
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE BODY PARTS			1,600.00	1,200
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)			1,600.00	1,000
DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME. (HV HYBRID SYSTEM SAFETY PROCEDURES)			450.00	200
				80
				2,540

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED
 80 ROBINSON RD #09-02/03
 068898

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000407

Date : 22/11/2018
 Vehicle Num. : SLU 7381B(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 22/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING
 FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST
 REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 200

REMOVE INTERIOR UPHOLSTERY INCLUDING INNER ROOF LINING,
 REAR SEATS, FLOOR PANEL LINING, ETC, IN ORDER TO
 FACILITATE REPAIRS TO REAR PANELS AND CHASSIS AND REFIT
 BACK SAME.

480.00 XNN

TO REMOVE, REARRANGE ALL ELECTRICAL WIRING, CHECK
 LIGHTINGS & RESET HEADLAMP FOCUSING

120.00 50

Labour Total S\$:

5,600.00 250

NAZ LKK

23/11/18

PIR

6 DAYS


 3/12/18

CHECK ITEMS PHOTOS

BEFORE PAINT PHOTOS

E. & O.E.

Total S\$:

21,066.02

=====

for WORLD AUTO PTE LTD

PARTS \$7,129
 LESS 25% \$5,346.75

S/NET \$ 400

LABOUR \$ 3,790

TOTAL \$8,536.75 / 6 DAYS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021208/Ntbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7936T	Veh. Inspected	SLU 7381B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008302MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	23/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003564759	Colour	WHITE	
Odometer	86025	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	5 mm	
L/H Front Tyre	195/65 R15	PIRELLI	5 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	5 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/11/2018	Inspection Date	23/11/2018	
Survey held at	NO 1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 7381B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CRACKED	550.00	400.00
1	FRONT HEADLAMP-RH	SCRATCHED	2,550.00	2,550.00
1	FRONT FOG LAMP-RH	SCRATCHED	950.00	500.00
1	FRONT BUMPER RETAINER RH	CRACKED	110.00	110.00
1	FRONT FENDER RH	DEFORMED	880.00	700.00
1	FRONT FENDER HYBRID EMBLEM RH	NECESSARY	89.00	89.00
1	FRONT KNUCKLE-RH	SERVICEABLE	550.00	-
1	FRONT WHEEL HUB RH	SERVICEABLE	560.00	-
1	FRONT STABILIZER LINK RH	SERVICEABLE	210.00	-
1	FRONT STABILIZER BAR RH	SERVICEABLE	360.00	-
1	DRIVE SHAFT RH	SERVICEABLE	1,185.70	-
1	FRONT SHOCK ABSORBER-RH	SERVICEABLE	420.00	-
1	FRONT LINKAGE-RH	SERVICEABLE	150.00	-
1	TIE ROD END RH	SERVICEABLE	160.00	-
1	FRONT LOWER ARM RH	SERVICEABLE	650.00	-
1	SIDE SKIRT RH	TO REPAIR SEE LABOUR	430.00	-
1	FRONT DOOR-RH	DEFORMED	1,450.00	1,300.00
1	FRONT DOOR GLASS REGULATOR MOTOR RH	SERVICEABLE	450.00	-
1	REAR DOOR SUB RUBBER SEAL	DEFORMED	180.00	180.00
1	REAR DOOR-RH	DEFORMED	1,450.00	1,300.00
1	REAR DOOR GLASS REGULATOR MOTOR LH	SERVICEABLE	450.00	-
1	REAR DOOR HINGE UPPER RH	SERVICEABLE	120.00	-
1	REAR DOOR HINGE LOWER RH	SERVICEABLE	120.00	-
1	REAR DOOR CHECKER RH	SERVICEABLE	180.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	950.00	-
	LESS 25% DISCOUNT		-3,788.68	-1,782.25
			11,366.02	5,346.75
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00

Report Ref No. CS/FC118021208/Ntbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE RH (SN)	SERVICEABLE	280.00	-
1	FRONT WHEEL RIM RH (SN)	SERVICEABLE	1,550.00	-
1	FRONT WHEEL CAP-RH (SN)	MISSING	180.00	180.00
1	SIDE SKIRT CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR TYRE RH (SN)	NOT NECESSARY	280.00	-
1	REAR WHEEL CAP RH (SN)	SCRATCHED	180.00	180.00
1	REAR WHEEL RIM RH (SN)	SERVICEABLE	1,550.00	-
			4,100.00	400.00
	LABOUR			
	FRT & BACK COMPUTERISED ALIGNMENT.		360.00	80.00
	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	80.00
	TRANSFER DOOR MECHANISM (X2 DOORS).		360.00	100.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE BODY PARTS.INCLUSIVE OF THE REPAIR OF SIDE SKIRT RH AND REAR FENDER RH.		1,600.00	1,200.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		1,600.00	1,000.00
	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME.(HV HYBRID SYSTEM SAFETY PROCEDURES).		450.00	80.00
	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES).		450.00	200.00
	REMOVE INTERIOR UPHOLSTERY INCLUDING INNER ROOF LINING,REAR SEATS,FLOOR PANEL LINING,ETC,IN ORDER TO FACILITATE REPAIRS TO REAR PANELS AND CHASSIS AND REFIT BACK SAME.	NOT NECESSARY	480.00	-
	TO REMOVE,REAR RANGE ALL ELECTRICAL WIRING,CHECK LIGHTINGS & RESET HEADLAMP FOCUSING.		120.00	50.00
			5,600.00	2,790.00
	GRAND TOTAL		21,066.02	8,536.75

Report Ref No. CS/FCI18021208/Ntbn2



RECOMMENDED COST OF REPAIRS			8,536.75
-----------------------------	--	--	----------

Report Ref No. CS/FCI18021208/Ntbn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.