

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 22/11/2018

TP Veh Reg No: SLM2198P

Estimate No: ES1891320/AMK

Date: 22 Nov 2018

Policy No: 5078851569-02

Veh Reg No: SGF2741S

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204177295

Engine No: 1NZX386484

Reg. Date: 05/04/2006

Estimate Repair Cost to Vehicle No :SGF2741S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	245.90	1 PC	245.90	—
2 REAR BUMPER SIDE RETAINER	12.50	2 PC	25.00	—
3 REAR BUMPER CLIP	3.50	4 PC	14.00	—
4 REAR BOOT	445.80	1 PC	445.80	—
5 REAR BOOT INNER LOCK	22.90	1 PC	22.90	—
6 REAR BOOT INNER RUBBER	44.10	1 PC	44.10	50.00
7 REAR BOOT LOGO	18.90	1 PC	18.90	—
8 REAR BOOT EMBLEM '1.5'	7.10	1 PC	7.10	—
9 REAR BOOT EMBLEM 'E'	30.94	1 PC	30.94	—
10 REAR BOOT EMBLEM 'VVT'	38.43	1 PC	38.43	—
11 REAR BOOT EMBLEM 'VIOS'	13.70	1 PC	13.70	—
12 TAILLAMP	189.00	2 PC	378.00	—
13 TAILLAMP INNER GASKET	19.20	2 PC	38.40	—
14 REAR END PANEL	720.10	1 PC	720.10	—
15 REAR END PANEL INNER TOP GARNISH	57.96	1 PC	57.96	—
			2,101.23	
		Less 25%	525.31	1,575.92
Special Net				
16 REVERSE SENSOR	200.00	1 SET	200.00	—
			200.00	200.00
Labour				
17 REMOVE & REFIX REAR BUMPER,REAR BOOT & ATTACHMENTS,TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR BOTH FENDERS,REAR SPARE TYRE PANEL & REALIGN THE SAME	850.00	1 LA	850.00	750.00
18 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,REAR END PANEL,REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	950.00	1 LA	950.00	850.00
19 RUSTPROOFING	60.00	1 LA	60.00	—
			1,860.00	
		Less 25%	465.00	1,395.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 22/11/2018
TP Veh Reg No: SLM2198P

Estimate No: ES1891320/AMK
Date: 22 Nov 2018
Policy No: 5078851569-02
Veh Reg No: SGF2741S
Make/Model: TOYOTA VIOS 1.5E A
Chassis No: MR053HY4204177295
Engine No: 1NZX386484
Reg. Date: 05/04/2006

Estimate Repair Cost to Vehicle No :SGF2741S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 3,170.92
			Add GST @ 7%	221.96
			Total Amount Payable	<u>S\$ 3,392.88</u>

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE