

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

23 NOV 2018

## ESTIMATE

Estimate No. : b1 49215	Page No. : 1 of 5
Date Estimated : 23/11/2018	
Prepared By : Gary Poh Chai Hoon	

- ESTIMATE REPAIR FOR - Christophe Jean Simon Marciano 114 Hillcrest Road  Singapore Singapore 288982	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX5882U	EG21101	29/03/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
Replace rear bumper panel and attachments, etc to knock out dents caused by the accident.	850 1,700.00
Spray rear bumper panel, tail panel	934 1,781.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
Sundries	? 80.00
<b>Total Labour 1:</b>	<b>3,915.00</b>

PART NUMBER	DESCRIPTION	QTY	PRIC	VALUE
51127332317	REAR LH BUMPER MOUNT ?	1	160.55	160.55
51127332318	REAR RH BUMPER MOUNT ?	1	160.55	160.55
51127332320	RR BUMPER CARRIER ?	1	468.30	468.30
51127378532	MOUNTING SMART OPENER ?	1	45.30	45.30
51127379982	REAR TRIM UNDERRIDE PROTECTION (X L) DE -	1	102.30	102.30
51127381119	RR BUMPER LH CORNER MOUNTING ?	1	141.90	141.90
51127381120	RR BUMPER RH CORNER MOUNTING ?	1	141.90	141.90
51127403391	REAR BUMPER PANEL PRIMED ?	1	741.55	741.55
51127403397	REAR BUMPER TRIM BOTTOM (LINES) DE -	1	222.45	222.45
51317361233	REAR BUMPER TOWING EYE COVER X	1	36.60	36.60
66209274428	ULTRASONIC SENSOR BLACK ?	4	248.70	994.80
66209283203	DECOUPLING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
<b>Total Parts :</b>				<b>3,236.40</b>

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No.	: b1 49215	Page No. : 2 of 5
Date Estimated	: 23/11/2018	
Prepared By	: Gary Poh Chai Hoon	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX5882U	EG21101	29/03/2018	X1 sDrive18i	0

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>09/01/19 @ 14:55</u>	Excess \$ _____
Surveyor's Name <u>Rasmi</u>	Sign _____
Surveyor's Tel <u>96010568</u>	Authorised <input type="checkbox"/> Yes / <input type="checkbox"/> No
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR <input type="checkbox"/> Yes / <input type="checkbox"/> No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	3,915.00
Parts	:	3,236.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	500.60
Grand Total	:	<u>7,652.00</u>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*