


SMRT Vehicle Repair Estimate

| | | |
|--------------------------------------|--|---|
| Group : | Buses / Taxis / Private Car | |
| Reg. No. : | PC 3663 L | Ref. No. _____ |
| Make / Model : | MERCEDES-BENZ BUS | Reg. Date : _____ |
| Chassis No. : | _____ | Mileage : _____ |
| Name of Driver : | BUS PLUS SERVICES PTE LTD | Rental/Replacement Vehicle : Yes / No |
| Date/Time of Accident : | 17/8/18 10:15A.M. | <div style="border: 1px solid black; padding: 5px;"> <p>The damages on the vehicle are as indicated in the following diagram :</p>  </div> |
| Surveyer is Required ? | YES / NO | |
| If Yes, VICOM / LKK / AIS / Others | MSIG : _____ | |
| Vehicle is Towed Back ? | YES / NO Date / Time : _____ | |
| Accident reporting date : | 17/8/2018 14:25P.M. | |
| Type of Accident : | Skid / Head-Rear / Head-On / Side Swipe / Others | |
| Special Instruction to ARC, if any : | <div style="border: 1px solid black; padding: 2px; display: inline-block;">LUMP SAM TP</div> | |
| Signed : | Date : | |

| | | | |
|--------------------------------|---------------------------|--------------------|-------------------------------------|
| Accident Repair Job Card No. : | _____ | Date Prepared : | _____ |
| Summary of Repair Estimates | | Repair Completed : | _____ |
| | Quotation from ARC | | Adjusted by Surveyor, if applicable |
| Total Labour Charges : | \$ 1,200.00 | | \$ - |
| Total Spray Painting Charges : | \$ 1,000.00 | | \$ - |
| Total Material Charges : | \$ 3,943.41 | | \$ - |
| Other Charges : | \$ 560.00 | | \$ - |
| TOTAL : | \$ 6,703.41 | | \$ - |
| | Lump Sum Repair, if any : | | _____ |
| No. of Repair Days : | [_____] days | | [_____] days |
| Signature : | Prepared by: _____ | | Adjusted by: _____ |

| | |
|----------------|-------------------|
| QN No. _____ | Invoice No. _____ |
| Signed : _____ | Date : _____ |

To be completed by Service Advisor, ARC

| Part Number | Parts Description | Qty | Cost Price (\$) | less 10% | Final Price (\$) | Repair (R) Replace (/) | Not given (X) Repair (R) Replace (/) |
|-------------|---|-----|-----------------|----------|------------------|-----------------------------|--|
| | Rear Bumper <i>OT</i> | 1 | \$ 1,588.59 | 10% | \$ 1,429.73 | / | |
| | Rear Bumper Reinforcement | 1 | \$ 581.32 | 10% | \$ 523.19 | ? | |
| | Rear Bumper Side Bracket RH | 1 | \$ 205.15 | 10% | \$ 184.64 | ? | |
| | Rear Bumper Reflector RH | 1 | \$ 198.45 | 10% | \$ 178.61 | ? | |
| | Rear Tail Lamp (Red) RH | 1 | \$ 355.35 | 10% | \$ 319.82 | ? | |
| | Rear Tail Lamp Panel RH <i>Repair</i> | 1 | \$ 1,231.62 | 10% | \$ 1,108.46 | R | |
| | Rear Side Panel Signal Lamp RH <i>CRA</i> | 1 | \$ 221.09 | 10% | \$ 198.98 | / | |

| Special Nett Items | Parts Description | Qty | Cost Price (\$) | Discount | Final Price (\$) | Repair (R) Replace (/) | Not given (X) Repair (R) Replace (/) |
|--------------------|-------------------|-----|-----------------|----------|------------------|-----------------------------|--|
| | | | | | | | |

TOTAL MATERIALS

\$ 4,381.57

-

\$ 3,943.41

Surveyor Remark:

Part 1 - Labour Works

| Job Scope | Quotation from ARC | |
|--------------------------|------------------------|----------|
| To repair LH side door | \$ 1,200.00 | |
| Total Labour Cost | \$ 1,200.00 | \$ 600 - |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | |
|---------------------------|------------------------|-----|
| To respray affected areas | \$ 1,000.00 | |
| Spray Painting | \$ 1,000.00 | 500 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

| Job Scope | Quotation from ARC | |
|--|----------------------|-----|
| Towing | | |
| To remove & refix side glass | | |
| To tuffcoat affected areas | \$ 250.00 | 100 |
| To remove & refix front windscreen | | |
| To renew engine mountings | | |
| To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas | | |
| To remove/refit replace dashboard | | |
| To remove and refit interior upholstery and seat | \$ 250.00 | 80 |
| To remove and replace steering column | | |
| To remove /refit wiring check | \$ 60.00 | 30 |
| To remove/refit adjust brake 4 wheel | | |
| To remove/replace exhaust silencer box and straighten centre pipe | | |
| To remove/ replace door mechanism | | |
| To remove & replace advertisement sticker | | |
| To remove & renew Fuel Tank | | |
| To remove and replace floor carpet | | |
| Total Other Costs | \$ 560.00 | |

I, the undersigned, hereby acknowledge and agree to the following:
 • To be resurveyed before/after spray painting
 • To be resurveyed damaged part(s) during resurvey
 • Parts to be replaced are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No item(s) of damage is allowed
 • Supply of any item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Hwee Jie - LKK (91803151)
 18/12/18
 L/s 5 days
 [Signature]

Part 4 - Spare Parts / Material Usage