



SMRT Accident Vehicle Repair Estimates

Poh Kin

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/11/2018

User ID : PehEngHock

Section A - Accident Details


Registration Number	PC3663L
Case Reference Number	BPS/10/16/3001
Registration Date	1/1/1900
Company Type	Bus-Plus Services Pte Ltd
Make	MITSUBISHI
Model	MITSUBISHI ROSA BE637
Name of Driver	Toh Suay Hwa
Type of Accident	SIDE SWIPE
Accident Date and Time	10/10/2016 8:30 AM
Accident Reported Date and Time	10/11/2016 1:56 PM
Is Surveyor Required?	Yes
Survey by	FCI
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	REAR RIGHT PORTION. TP: SHD3997M
Prepared Date and Time	12/10/2016 6:08 PM
Chassis Number	BE641JJ10175
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$606.00	\$0.00
Total Spare Part Cost	\$108.00	\$0.00
Total Other Cost	\$1,440.00	\$0.00
TC COST	\$4,274.00	\$0.00
Lump Sum Total	\$4,250.00	\$0.00
Number of Repair Days	6.0	0.0
Prepared / Adjusted By	Bus Plus Estimator Team	
ARC / Surveyor Sign Off Date	05/06/2017 1:42 PM	01/01/1900 12:00 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Finalized - Huse Je

	Rear Bumper	1	\$ 1,588.59	10%	\$ 1,429.73	/	DD
	Rear Bumper Reinforcement	1	\$ 581.32	10%	\$ 523.19	X	NN
	Rear Bumper Side Bracket RH	1	\$ 205.15	10%	\$ 184.64	X	NN
	Rear Bumper Reflector RH	1	\$ 198.45	10%	\$ 178.61	X	NN
	Rear Tail Lamp (Red) RH	1	\$ 355.35	10%	\$ 319.82	X	NN
	Rear Tail Lamp Panel RH	1	\$ 1,231.62	10%	\$ 1,108.46	R	
	Rear Side Panel Signal Lamp RH	1	\$ 221.09	10%	\$ 198.98	/	CRA

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R)	Not given (X)
						Replace (/)	Repair (R) Replace (/)
TOTAL MATERIALS			\$ 4,381.57	-	\$ 3,943.41		

Surveyor Remark:

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To repair RH side door	\$ 1,200.00	
Total Labour Cost	\$ 1,200.00	\$ 600 -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,000.00	
Spray Painting	\$ 1,000.00	500

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
Towing		
To remove & refix side glass		
To tuffcoat affected areas	\$ 250.00	100
To remove & refix front windscreen		
To renew engine mountings		
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas		
To remove/refit replace dashboard		
To remove and refit interior upholstery and seat	\$ 250.00	80
To remove and replace steering column		
To remove /refit wiring check	\$ 60.00	30
To remove/refit adjust brake 4 wheel		
To remove/replace exhaust silencer box and straighten centre pipe		
To remove/ replace door mechanism		
To remove & replace advertisement sticker		
To remove & renew Fuel Tank		
To remove and replace floor carpet		
Total Other Costs	\$ 560.00	

Hwa Jie - LKK (91803151)
 18/12/18
 L/s 5 days

Part 4 - Spare Parts / Material Usage

FR-AS-ARC-02 Rev 7

10/1/19 - Finalized L/s repair \$2,350/- 5 days.