

22/03/2002

ASS. REC. BY:

REF:

CS3/FWD1802/218/Gcd30p

Special Instruction:

Surveyor:

Mumen

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

FWD

Date/Time:

22/11/18 @ 4:48pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PCGG89T

Insured:

SJK 8509 X

at Workshop m/s

AS Auto

Tel:

9738 8183

of

1 Kaki Bkt Ave 6 #01-106

Policy No:

PNPV2018-00013785/LP

Claim No:

1201800016044

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/11/18

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

23/11/18 @ 9:30am

Person Contacted:

Ah Soon

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate	Insp: 01-08
	vehicle will be In December &	
	PCGG89T-X	
	SJK 8509 X-X	
	Dismantle: 5/12/2018	

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Thursday, 22 November 2018 4:48 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Subject: FW: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT
Attachments: 20181122163319.pdf

Please attend to attached TPRS notice.

Regards,
Lionel

From: Prestina Moh [mailto:prestinamoh@visionlawllc.com]
Sent: Thursday, November 22, 2018 4:36 PM
To: Lionel Tan Tian Pei - SGUser
Cc: Motor Claims SG - SG Common
Subject: RE: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT

WITHOUT PREJUDICE
Our ref: PC 6689 T

Dear Sir/Mdm

Please refer to our letter of even date for your attention.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

From: lionel.tan@fwd.com [mailto:lionel.tan@fwd.com]
Sent: Thursday, 22 November, 2018 4:11 PM
To: prestinamoh@visionlawllc.com
Cc: motorclaims.sg@fwd.com
Subject: RE: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT

WITHOUT PREJUDICE

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Regards,
Lionel

From: Prestina Moh [<mailto:prestinamoh@visionlawllc.com>]
Sent: Thursday, November 22, 2018 4:02 PM
To: Lionel Tan Tian Pei - SGUser
Cc: Motor Claims SG - SG Common
Subject: RE: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT

WITHOUT PREJUDICE
Our ref: PC 6689 T

Dear Sir/Mdm

Please refer to our reply of even date for your attention.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

From: lionel.tan@fwd.com [<mailto:lionel.tan@fwd.com>]
Sent: Thursday, 22 November, 2018 2:51 PM
To: prestinamoh@visionlawllc.com
Cc: motorclaims.sg@fwd.com
Subject: RE: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT

Without Prejudice

Dear Sir/ Madam

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. VICOM LTD
5. APPRAISALS ASSOCIATES PTE LTD

Regards,
Lionel

From: Prestina Moh [<mailto:prestinamoh@visionlawllc.com>]
Sent: Thursday, 22 November, 2018 2:15 PM
To: Motor Claims SG - SG Common
Subject: **PRE-REPAIR SURVEY** Our Ref: PNPV2018-00013785/LT

WITHOUT PREJUDICE
Our ref: PC 6689 T

Dear Sir/Mdm

Please see our PRS request as attached.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments:

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓ HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: PC 6689 T (PM)
Your Ref: SJK 8509 X

22 November 2018

BY EMAIL ONLY

FWD Insurance
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attention: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE PC 6689 T(#2) & SJK 8509 X(#3) & SKH 3943 C(#1) ON
21 NOVEMBER 2018 ALONG WOODLANDS ROAD TOWARDS TOWN NEAR YEW TEE FLYVOER
AT ABOUT 1620 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Venue: A S AUTO SERVICE
1 Kaki Bukit Avenue 6
#01-106 Autobay@Kaki Bukit
Singapore 417883
Contact: Ah Soon @ 9738 8183 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully


DIANE ANG
(HEAD OFFICE)

cc: PC 6689 T – By email only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2068Z
Vehicle Details	
Vehicle No.:	PC6689T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	MAXUS
Vehicle Model:	V80 WINDOW VAN SWB 6MT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	R9164010766
Chassis No.:	LSKG4GL14GA228212
Maximum Power Output:	-
Open Market Value:	\$28,845.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,443.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$46,890.00
COE Rebate Amount:	\$42,276.00
Total Rebate Amount:	\$42,276.00

The information contained herein is correct as at 05 Dec 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Nov 2018 Edit Reg		22 Nov 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **Jayeinthiran**, ID: S7326414F

Main Claimant: -

Vehicle Reg. No.: **PC6689T**

Claim Type: **TP / 1201800016044**

Vehicle Reg. No. (Insured): **SJK8509X**

Repairer: **As Auto Service (HQ)** Blk 1 Kaki Bukit Avenue 6 #01-106 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel:

Handling Insurer: **FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Lionel Tan**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... **[Final Rpt due 04/12/2018]**

Date of Loss: 21/11/2018 16:00 - :59
[**11 Months and 9 Days** From LTA Reg Date (Man Yr)]

Policy/Cover Note No.: PNPV2018-00013785 (Comprehensive)
Coverage: 05/11/2018 - 04/11/2019

Policy No. (Claimant):

Excess: S\$600.00

[Created by adjuster]

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
















































Claim Documents

































***PC6689T (1201800016044)**
[SJK8509X]

TP

-
Nov 21 2018 4:00PM
[Jayeinthiran]
As Auto Service

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
2	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
3	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
4	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
5	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
6	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
7	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
8	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
9	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
10	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
11	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
12	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
13	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
14	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
15	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
16	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
17	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
18	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
19	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
20	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
21	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
22	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
23	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
24	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
25	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
26	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
27	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
28	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
29	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
30	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
31	07/12/18 10:19	General View							Load JPG	<input checked="" type="checkbox"/>
32	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>
33	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>
34	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>
35	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>
36	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>
37	07/12/18 10:20	General View							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/12/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	07/12/18 10:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/18 16:41	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18021218/GCD3E2

Date: 17/12/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013785
Claimant Vehicle No : PC6689T **Insured Vehicle No :** SJK8509X
 Date of Loss: 21/11/2018 Nature of Claim: TP Claim No: 1201800016044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC6689T**
 Make & Model: MAXUS V80, 2.5 (A) Engine No: R9164010766
 Reg. Date: 12/12/2017 (Man. Year: 2016) Chassis No: LSKG4GL14GA228212
 Colour: White Odometer: 23625 km
 Engine Capacity: 2499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R16 Rear Tyre Size: 195/75 R16
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/11/2018
 Date Inspected: 04/12/2018 Inspected At: As Auto Service (HQ)
 Blk 1 Kaki Bukit Avenue 6 #01-106
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts:	143	MAXUS V80 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6689T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >