

CC 4, lpc 180 2124, 181454

Surveyor:

KSL

ASSIGNMENT
DOI: 23-11-18

Date / Time:

23-11-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMC 5900A

Name of Insured:

CHEN CHUAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 21-11-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

1818181805/02142

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

JNK 3232



INSRS:

WSP:

Tel:

Liability:

RMKS:

S&M



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

5/12/19
ing

JNK 3232 - X; SMC 5900A - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☐	☐
Authorisation To Act:	☒	☐
Release Voucher: (ODG W/LR)	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☐	☐
Towing Invoice:	☐	☐
LTA / GIA:	☐	☐
Medical Bill:	☒	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others: V&P	☒	☐

01/07/19

- REPORT DONE
- 900K MANDATE APPROVAL TO LPC

10/07/19

- LPC APPROVED MANDATE
- SEND 1ST OFFER TO TP.
- TP REQUESTED OFFER. CLAIM FOR MEDICAL
BILLS. ALLEGED LOD.

08/08/19

10/08/19

- 18-900K MANDATE APPROVAL
- SEND 2ND OFFER
LOD RECEIVED BY LONPAC.

17-6-19

FOR MANDATE.
- TP ACCEPTED OFFER.
- ALL DONE IN OFFICE.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: US \$5 10,000.00 (9 days) Reduction: 11 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☒ Call ☐

Final Liability: % 100 (A tick / Assessed) BOLA S/N No.: 8

If NO or B 28, Ass. Lia:

Repair Cost: (w/acc) \$5 10,700.00

Loss of Rental (LOR): \$5 (days)

Loss of Use (LOU): \$5 960.00 x 20 (12 days) FOREIGN-5190CC

Loss of Income (LOI): \$5 (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5

Medical: BLUE \$5 180.81

Disbursement: V&P P&E \$5 455.00 (e.g. Tow/ Independent)

Legal Cost \$5

Total: \$5 12,295.51 Global Sum \$5: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$5 12,295.51

Name 1:

S & H MOTOR P&E V&P

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: 4450.00

COPY SENT
4/12/19

ASS. REC. BY:

REF: 6PC /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s P&H

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 09 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: JNK 3232 Yr Regn: 1 12Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or AMake: M. E350 c.c. 3498Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 177178 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDB 211 0362B 132955Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 245/40R18R: 285/35R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 21/11/18 D.O.I. 23/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ols body

The U/C / Chassis / frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/11 File pass to Catherine, await log card28-01-19 \$10K
(200.01255.95 / 11%)

Data/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Data/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

\$ + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

Kij
Not withark
11 Day 810,000k
Resony After Paint
9 days

File No : SH/2018/150/11/011/TP
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity	List Price
RH front door	1	\$ <i>B1</i> 980.00 ✓
RH rear door	1	\$ <i>B1</i> 985.00 ✓
RH front door protector	1	\$ <i>B1</i> 135.00 ✓
RH rear door protector	1	\$ <i>B1</i> 95.00 ✓
RH rear fender	1	\$ <i>B1</i> 1,280.00 ✓
RH running board garnish	1	\$ <i>CM</i> 390.00 ✓
RH rear bumper bottom cover	1	\$ <i>mi</i> 115.00 ✓
Rear windscreen moulding	1	\$ <i>me</i> 288.00 ✓
RH rear alloy road wheel	1	\$ <i>nd</i> 450.00 ✓
RH rear lower arm	1	\$ <i>B1</i> 350.00 ✓
RH rear knuckle	1	\$ <i>B1</i> 220.00 ✓
RH rear knuckle wheel bearing	1	\$ <i>me</i> 165.00 ✓
RH rear door glass gear	1	\$ <i>B1/01</i> 260.00 ✓
RH rear door top hinge	1	\$ <i>R</i> 85.00 X
RH rear door bottom hinge	1	\$ <i>R</i> 85.00 X
RH rear door outer lock handler	1	\$ <i>nd</i> 325.00 ✓
RH front door weather strip	1	\$ <i>me</i> 190.00 ✓
RH rear door weather strip	1	\$ <i>me</i> 245.00 ✓
Front RH door inner lock	1	\$ <i>ed</i> 190.00 ✓
		\$ 6,833.00
	Add 15%	\$ 1,024.95
		\$ 7,857.95
Rear windscreen sealant	1	SN \$ <i>me</i> 80.00 ✓
Rear windscreen inner sealant rubber	1	SN \$ <i>me</i> 38.00 ✓
RH front door insulator	1	SN \$ <i>me</i> 80.00 ✓
RH rear door insulator	1	SN \$ <i>me</i> 80.00 ✓
RH rear tyre Firelli Pzero 265/35/R18	1 <i>17/18</i>	SN \$ <i>CM</i> 285.00 ✓
To remove and reinstall rear windscreen glass.	1	\$ 150.00/2 ✓
To spray painting the accident and repair areas.	1	\$ 1,200.00 ✓
Labour to check RH rear suspension under carriage, remove and repair, renew damaged parts.	1	\$ 320.00 ✓
To check and reset 4 wheel steering alignment.	1	\$ 65.00 ✓

CHEE CHERN KITT
 NO. 28 #05-02/03
 AYER RAJAH CRESCENT
 SINGAPORE 139959

File No : SH/2018/150/11/011/TP
 Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
 Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity		List Price
Labour to removed damaged parts, cut out RH rear fender, jack out door center pillar, body RH rear wheel housing panel, rewelding, repair , panel beating, renew and install , adjust body door alignment.	1	\$	1,100.00 <i>1000</i>
		\$	<u>11,255.95</u>

T/Party: LONPAC INSURANCE BHD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

File No :
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity	List Price
		<u>S 2,953.00</u>

T/Party: LONPAC INSURANCE BHD

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 23 November, 2018 10:51 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Doris (doris@sh-motor.com)
Subject: Our Ref: 18/18/18/VP05/021142 FW: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018
Attachments: CCF_20181123_093855_007415.tif; CCF_20181123_093855_007416.tif; CCF_20181123_093855_007417.tif; CCF_20181123_093855_007418.tif; CCF_20181123_093855_007419.tif; CCF_20181123_093855_007420.tif

Dear Catherine/Nivitha

Please arrange TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

23.11.2018 @ 11:15am
Gynthia veh in.
Kenneth.

From: GERALD POH WEE BIN
Sent: Friday, 23 November, 2018 10:21 AM
To: ONG LI LI
Subject: FW: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018

Hi Li Li,

FYA

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Doris [mailto:doris@sh-motor.com]
Sent: Friday, 23 November, 2018 9:54 AM
To: GERALD POH WEE BIN
Subject: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018

Dear Gerald

Forward vehicle no : JNK 3232 estimated for arrange survey

Thank

Doris

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 28 November, 2018 9:37 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/18/18/VP05/021142 FW: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018
Attachments: 28112018093314.pdf
Categories: HMK

Dear Mei Kwan,

Attached copy of insured 's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 27 November, 2018 7:37 PM
To: ONG LI LI
Cc: Admin A; MT_Claim_SG; Joy Irene (LKKAUTO); CS A Team
Subject: RE: Our Ref: 18/18/18/VP05/021142 FW: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/18/18/VP05/02114
LKK REF: CC4/LPC18021224/Kja3

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your perusal is:

- Estimated cost of repair (parts price incomplete)
- Photographs of TP vehicle in its damaged condition

We will revert to you on preliminary advice in due course.

Kindly let us have a copy of insured's accident report for our necessary action.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Doris [<mailto:doris@sh-motor.com>]

Sent: Friday, 23 November, 2018 9:54 AM

To: GERALD POH WEE BIN

Subject: arrange survey for third parts vehicle no : JNK 3232 /SMC 5900 A DOA : 21.11.2018

Dear Gerald

Forward vehicle no : JNK 3232 estimated for arrange survey

Thank

Doris

Chee Chern Kitt
No : 28, #05-02/03
Ayer Rajah Crescent
Singapore 139959

File No : SH/2018/150/11/011/TP
Date : 04-December-2018

Supplementary estimated cost of repair for vehicle no: JNK 3232 Mo Mercedes
Accident involving vehicle no: JNK 3232 & SMC 5900 A on 21.11.2018

Description	Quantity	Cost Price
Rear right upper arm	\$ B ₁	190.00 ✓
Rear right wheel anti roll bar link	\$ 011	160.00 ✓
Rear right upper trust arm	\$ B ₁	230.00 ✓
Rear right wheel lower control arm	\$ R ₁	340.00 ✓
Rear anti roll bar	\$ 011	280.00 ✓
Rear cross member	\$ R ₁	650.00 ✓
Rear differential (Second Hand)	\$ Sm	300.00 X
	\$	2,150.00
	Add 15%	\$ 322.50
		\$ 2,472.50
Towing (King Dolly)	\$	120.00 ✓
Labour charge for remove exhaust, cross member for replace wheel undercarriage	\$	250.00 760/
	\$	2,842.50

T/Party: Lonpac



Mercedes-Benz : 211 (E Class 2002-09) : Rear Wheel Drive : Sedan Steel Spring Suspension Europe version/USA : Standard Suspension
(Code 954/954+485)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°19'	-2°33'	-1°07' -0°27'
11°00'	11°00'	
-0°51'	-0°10'	0°02' 0°08'
6°05'	6°19'	
3°46'	3°46'	
		-2°19' -1°19'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°51'	-1°38'	-1°07' -0°27'
11°45'	11°45'	
0°40'	-0°02'	0°02' 0°08'
5°34'	5°21'	
3°43'	3°43'	
		-2°19' -1°19'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°28'	-0°55'	-0°20' 0°20'
-0°45'	-0°45'	-0°30' 0°30'
0°31'	0°58'	
-0°12'	-0°12'	0°04' 0°16'

Rear : Left

Actual	Before	Specified Range
-2°57'	-3°06'	-1°32' -0°32'
0°16'	0°16'	0°03' 0°17'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-6°15'	-6°12'	-1°32' -0°32'
-1°29'	-1°29'	0°03' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
3°18'	3°06'	-0°30' 0°30'
-1°14'	-1°12'	0°13' 0°27'
0°52'	0°52'	-0°15' 0°15'



PRIVATE CAR - INDIVIDUAL

Form MX1

Certificate of Insurance

ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE MOTOR
VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).
MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 90), NEGARA BRUNEI DARUSSALAM.

Certificate No. **JB-87397034-MPC**

1. Index Mark and Registration

Number of Vehicle : **JNK3232**
Make of Vehicle : **MERCEDES BENZ E350 CGI (A)**

2. Name of Policy Holder : **CHEE CHERN KITT**

3. Effective date of the Commencement of Insurance for the purpose of the Regulations, Ordinance
or Enactment: **17/05/2018**

4. Date of Expiry of Insurance: **16/05/2019**

5. Persons or Classes of Persons entitled to drive *

(a) The Policyholder. (b) Any other person who is driving on the Policyholder's order or with his
permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations
to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by
reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward, racing, pacemaking, reliability trial speed-testing, the
carriage of goods other than samples in connection with any trade or business or use for any purpose in
connection with the Motor Trade.

Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of
the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7
of the Motor Vehicles Insurance (Third Party Risks) Act (Cap. 90) Negara Brunei Darussalam are not
included under this heading.

"I/We certify that the Policy to which this Certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act,
1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance
(Third Party Risks) Act (Cap 90) Negara Brunei Darussalam."

Approved Insurers:

RTD - 32

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18021224/Kha3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 19-02-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 5900A	Veh. Inspected	JNK 3232
Policy No.		Coverage (\$)	0.00
Claim No.	18/18/18/VP05/02114	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	23/11/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES E350 (A)	c.c	3498
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDB2110562B132955	Colour	METALLIC BLACK
Odometer	177178	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	7 mm
L/H Front Tyre	245/40 R18	PIRELLI	7 mm
R/H Rear Tyre	265/35 R18	PIRELLI	7 mm
L/H Rear Tyre	265/35 R18	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/11/2018	Inspection Date	23/11/2018
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JNK 3232

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH FRONT DOOR (WCP)	BENT	980.00	980.00
1	RH REAR DOOR (WCP)	BENT	985.00	985.00
1	RH FRONT DOOR PROTECTOR (WCP)	BENT	135.00	135.00
1	RH REAR DOOR PROTECTOR (WCP)	BENT	95.00	95.00
1	RH REAR FENDER SFA (WCP)	BENT	1,280.00	1,280.00
1	RH RUNNING BOARD GARNISH (WCP)	CRACKED	390.00	390.00
1	RH REAR BUMPER BOTTOM COVER (WCP)	MISSING	115.00	115.00
1	REAR WINDSCREEN MOULDING (WCP)	NECESSARY	288.00	288.00
1	RH REAR ALLOY ROAD WHEEL (WCP)	DENTED	450.00	450.00
1	RH REAR LOWER ARM (WCP)	BENT	350.00	350.00
1	RH REAR KNUCKLE (WCP)	BENT	220.00	220.00
1	RH REAR KNUCKLE WHEEL BEARING (WCP)	NECESSARY	165.00	165.00
1	RH REAR DOOR GLASS GEAR (WCP)	BENT / DISTORTED	260.00	260.00
1	RH REAR DOOR TOP HINGE (WCP)	TO REPAIR SEE LABOUR	85.00	-
1	RH REAR DOOR BOTTOM HINGE (WCP)	TO REPAIR SEE LABOUR	85.00	-
1	RH REAR DOOR OUTER LOCK HANDLER (WCP)	DENTED	325.00	325.00
1	RH FRONT DOOR WEATHER STRIP (WCP)	NECESSARY	190.00	190.00
1	RH REAR DOOR WEATHER STRIP (WCP)	NECESSARY	245.00	245.00
1	FRONT RH DOOR INNER LOCK (WCP)	DENTED	190.00	190.00
	COST PLUS 15%		1,024.95	999.45
			7,857.95	7,662.45
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SEALANT RUBBER (SN)	NECESSARY	38.00	38.00
1	RH FRONT DOOR INSULATOR (SN)	NECESSARY	80.00	80.00
1	RH REAR DOOR INSULATOR (SN)	NECESSARY	80.00	80.00
1	RH REAR TYRE FIRELLI PZERO 265/35R18 (SN) (60%)	CUT	285.00	171.00
			563.00	409.00

Report Ref No. CC4/LPC18021224/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS.		150.00	120.00
	TO SPRAY PAINTING THE ACCIDENT AND REPAIR AREAS.		1,200.00	1,000.00
	LABOUR TO CHECK RH REAR SUSPENSION UNDER CARRIAGE ,REMOVE AND REPAIR ,RENEW DAMAGED PARTS.		320.00	160.00
	TO CHECK AND RESET 4 WHEEL STEERING ALIGNMENT.		65.00	60.00
	LABOUR TO REMOVED DAMAGED PARTS ,CUT OUT RH REAR FENDER ,JACK OUT DOOR CENTER PILLAR ,BODY RH REAR WHEEL HOUSING PANEL ,REWELDING REPAIR,PANEL BEATING ,RENEW AND INSTALL ,ADJUST BODY DOOR ALIGNMENT.INCLUSIVE OF THE REPAIR OF RH REAR DOOR TOP HINGE AND RH REAR DOOR BOTTOM HINGE .		1,100.00	1,000.00
			2,835.00	2,340.00
	GRAND TOTAL		11,255.95	10,411.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,000.00

Report Ref No. CC4/LPC18021224/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.