

Kj



CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

Not withstanding
11 Day @ 10,000
Recovery After Paint 9 days

File No : SH/2018/150/11/011/TP
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity	List Price
RH front door	1	\$ B1 980.00 ✓
RH rear door	1	\$ B1 985.00 ✓
RH front door protector	1	\$ B1 135.00 ✓
RH rear door protector	1	\$ B1 95.00 ✓
RH rear fender	1	\$ B1 1,280.00 ✓
RH running board garnish	1	\$ CM 390.00 ✓
RH rear bumper bottom cover	1	\$ M1 115.00 ✓
Rear windscreen moulding	1	\$ M 288.00 ✓
RH rear alloy road wheel	1	\$ Dd 450.00 ✓
RH rear lower arm	1	\$ B1 350.00 ✓
RH rear knuckle	1	\$ B1 220.00 ✓
RH rear knuckle wheel bearing	1	\$ M 165.00 ✓
RH rear door glass gear	1	\$ R101 260.00 ✓
RH rear door top hinge	1	\$ R 85.00 X
RH rear door bottom hinge	1	\$ R 85.00 X
RH rear door outer lock handler	1	\$ Dd 325.00 ✓
RH front door weather strip	1	\$ M 190.00 ✓
RH rear door weather strip	1	\$ M 245.00 ✓
Front RH door inner lock	1	\$ Rd 190.00 ✓
		\$ 6,833.00
	Add 15%	\$ 1,024.95
		\$ 7,857.95
Rear windscreen sealant	1	SN \$ M 80.00 ✓
Rear windscreen inner sealant rubber	1	SN \$ M 38.00 ✓
RH front door insulator	1	SN \$ M 80.00 ✓
RH rear door insulator	1	SN \$ M 80.00 ✓
RH rear tyre Firelli Pzero 265/35/R18	1	SN \$ M 285.00 ✓
To remove and reinstall rear windscreen glass.	1	\$ 150.00/2
To spray painting the accident and repair areas.	1	\$ 1,200.00 ✓
Labour to check RH rear suspension under carriage, remove and repair, renew damaged parts.	1	\$ 320.00 ✓
To check and reset 4 wheel steering alignment.	1	\$ 65.00 ✓

CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

File No : SH/2018/150/11/011/TP
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity		List Price
Labour to removed damaged parts, cut out RH rear fender, jack out door center pillar, body RH rear wheel housing panel, rewelding, repair , panel beating, renew and install , adjust body door alignment.	1	\$	1,100.00 <i>1000</i>
		\$	<u>11,255.95</u>

T/Party: LONPAC INSURANCE BHD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: