

Not Notmark

11 Sep 07

Resurvey After Paint

8 days



CHEE CHERN KITT  
NO. 28 #05-02/03  
AYER RAJAH CRESCENT  
SINGAPORE 139959

File No :  
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES  
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

| Description                                           | Quantity | List Price |
|-------------------------------------------------------|----------|------------|
| RH front door <i>BT ✓</i>                             | 1        | \$ -       |
| RH rear door <i>BT ✓</i>                              | 1        | \$ -       |
| RH front door protector <i>BT ✓</i>                   | 1        | \$ -       |
| RH rear door protector <i>BT ✓</i>                    | 1        | \$ -       |
| RH rear fender <i>BT ✓</i>                            | 1        | \$ -       |
| RH running board garnish <i>CM ✓</i>                  | 1        | \$ -       |
| RH rear bumper bottom cover <i>7</i>                  | 1        | \$ -       |
| Rear windscreen moulding <i>me ✓</i>                  | 1        | \$ -       |
| RH rear alloy road wheel <i>Del ✓</i>                 | 1        | \$ -       |
| RH rear lower arm <i>7</i>                            | 1        | \$ -       |
| RH rear knuckle <i>BT ✓</i>                           | 1        | \$ -       |
| RH rear knuckle wheel bearing <i>me ✓</i>             | 1        | \$ -       |
| RH rear tyre Firelli Pzero 265/35/R18 <i>me 708 ✓</i> | 1        | \$ -       |
| RH rear door glass gear <i>7</i>                      | 1        | \$ -       |
| RH rear door top hinge <i>Rx</i>                      | 1        | \$ -       |
| RH rear door bottom hinge <i>Rx</i>                   | 1        | \$ -       |
| RH rear door outer lock handler <i>Del ✓</i>          | 1        | \$ -       |
|                                                       |          | \$ 0.00    |
|                                                       |          | \$ 0.00    |
|                                                       |          | \$ 0.00    |

Add 15%

Rear windscreen sealant  
Rear windscreen inner sealant rubber  
RH front door weather strip  
RH rear door weather strip  
To remove and reinstall rear windscreen glass.  
To spray painting the accident and repair areas.  
Labour to check RH rear suspension under carriage, remove and repair, renew damaged parts.  
To check and reset 4 wheel steering alignment.  
Labour to removed damaged parts, cut out RH rear fender, jack out door center pillar, body RH rear wheel housing panel, rewelding, repair, panel beating, renew and install, adjust body door alignment.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal implication(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SN \$ *me* 80.00 *4000*  
SN \$ *me* 38.00 *—*  
SN \$ - *7*  
SN \$ - *7*  
\$ 150.00 *1200*  
\$ 1,200.00 *10000*  
\$ 320.00 *?*  
\$ 65.00 *600*  
\$ 1,100.00 *10000*



**CHEE CHERN KITT**  
NO. 28 #05-02/03  
AYER RAJAH CRESCENT  
SINGAPORE 139959

File No :  
Date : 22-November-2018

**Estimated cost of repair for vehicle no: JNK3232 MERCEDES**  
**Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018**

| Description | Quantity | List Price         |
|-------------|----------|--------------------|
|             |          | <u>\$ 2,953.00</u> |

T/Party: LONPAC INSURANCE BHD