




CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

File No :
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity	List Price
RH front door	1	\$ -
RH rear door	1	\$ -
RH front door protector	1	\$ -
RH rear door protector	1	\$ -
RH rear fender	1	\$ -
RH running board garnish	1	\$ -
RH rear bumper bottom cover	1	\$ -
Rear windscreen moulding	1	\$ -
RH rear alloy road wheel	1	\$ -
RH rear lower arm	1	\$ -
RH rear knuckle	1	\$ -
RH rear knuckle wheel bearing	1	\$ -
RH rear tyre Firelli Pzero 265/35/R18	1	\$ -
RH rear door glass gear	1	\$ -
RH rear door top hinge	1	\$ -
RH rear door bottom hinge	1	\$ -
RH rear door outer lock handler	1	\$ -
		\$ 0.00
	Add 15%	\$ 0.00
		\$ 0.00
Rear windscreen sealant	1	SN \$ 80.00
Rear windscreen inner sealant rubber	1	SN \$ 38.00
RH front door weather strip	1	SN \$ -
RH rear door weather strip	1	SN \$ -
To remove and reinstall rear windscreen glass.	1	\$ 150.00
To spray painting the accident and repair areas.	1	\$ 1,200.00
Labour to check RH rear suspension under carriage, remove and repair, renew damaged parts.	1	\$ 320.00
To check and reset 4 wheel steering alignment.	1	\$ 65.00
Labour to removed damaged parts, cut out RH rear fender, jack out door center pillar, body RH rear wheel housing panel, rewelding, repair , panel beating, renew and install , adjust body door alignment.	1	\$ 1,100.00



CHEE CHERN KITT
NO. 28 #05-02/03
AYER RAJAH CRESCENT
SINGAPORE 139959

File No :
Date : 22-November-2018

Estimated cost of repair for vehicle no: JNK3232 MERCEDES
Accident involving vehicle no: JNK3232 & SMC5900A on 21-November-2018

Description	Quantity	List Price
		\$ 2,953.00

T/Party: LONPAC INSURANCE BHD