

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793] . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBG4350C181116

Estimate

Customer

Name: QBE Insurance (International) Limited

Date: 23-11-18

Address Motor Claims Department

Vehicle No: GBG4350C

1 Raffles Quay #29-10

Model/Make: Toyota Hiace

South Tower

Singapore 048583

DX 3.0 Auto

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 2,051.60	
2	Tailgate Lock	\$ 359.00	
3	Tailgate Weatherstrip	\$ 391.20	
4	Tailgate "Toyota Logo" Motif	\$ 167.00	
5	Tailgate "Hiace" Sticker	\$ 60.35	
6	Tailgate "70 KM/H" Sticker	\$ 12.00	SN
7	Tailgate "8 PAX" Sticker	\$ 12.00	SN
8	Number Plate Lamp Outer Garnish	\$ 346.50	
9	Number Plate & Base	\$ 48.00	SN
10	Tailgate Windscreen Glass	\$ 1,311.30	
11	Tailgate Windscreen Glass Moulding	\$ 219.00	
12	Tailgate Windscreen Glass Sealant	\$ 50.00	SN
13	Tail Lamp 02 pcs (@ \$5365.10)	\$ 730.20	
14	Bumper	\$ 465.00	
15	Bumper Bracket 02 pcs (@ \$539.10)	\$ 78.20	
16	Bumper Clips 1 set	\$ 48.00	SN
17	Bumper Reverse Sensor	\$ 220.00	SN
18	Bumper Step Panel	\$ 262.30	
19	End Panel Outer	\$ 566.10	
20	End Panel Sealant	\$ 50.00	SN
21	Tailgate "Corporate" Advertisement Sticker	\$ 450.00	SN
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	
	To check all wiring & electrical component for proper function	\$ 80.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Et	\$ 800.00	
	To putty & spray painting & including touch up paint on accident	\$ 800.00	
	To apply Rust Proofing , reseal tuff-coating treatment on accident a	\$ 80.00	
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 140.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 9,877.75

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks