

Kp

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5304A**AAD1811-182***Not Authored**Referring B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5304A

JTDKB3FU503076732

RENAULT

LATITUDE

21.11.2018

AIG**PART****LIST**

1	1 FRONT BUMPER	\$	BH/cm	499.90	✓
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	DIY	101.20	✓
3	1 REINFORCEMENT, FRONT BUMPER	\$	R	696.40	X
4	1 ABSORBER, FRONT BUMPER, LOWER	\$	SL	130.20	X
5	1 ABSORBER, FRONT BUMPER ENERGY	\$	SL	78.10	X
6	1 FRONT BUMPER SIDE RETAINER RH	\$	CM	78.00	✓
7	1 FRONT BUMPER SUPPORT	\$	SL	81.70	X
8	1 EXTENSION, FRONT BUMPER, RH	\$	SL	117.80	X
9	1 FRONT LED LAMP (LOWER)	\$	CM	907.75	✓
10	1 FRONT HEADLAMP	\$	CM	2,909.04	✓
11	1 FRONT FENDER	\$	Bu	945.30	✓
12	1 EXTENSION, FRONT FENDER, RH	\$	R	48.80	X
13	1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	SL	98.30	X
14	1 LINER, FRONT FENDER, RH	\$	DIY	200.70	✓
15	1 FRONT FENDER EMBLEM	\$	SL	86.50	✓
16	1 SEAL, FENDER APRON MUDGUARD, RH	\$	SL	50.90	X
17	1 FRONT BONNET	\$	BH	950.50	✓
18	1 FRONT LOWER ARM	\$	DIY	631.90	✓
19	1 FRONT SHOCK ABSORBER	\$	BH	398.20	✓
20	1 SHAFT ASSY, FRONT DRIVE, RH	\$	R	1,186.20	X
21	1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	SL	637.50	X
22	1 KNUCKLE, STEERING, RH	\$	SL	562.30	X
23	1 LINK ASSY, FRONT STABILIZER, RH	\$	SL	199.00	X
24	1 BAR, STABILIZER, FRONT	\$	SL	360.30	X
25	1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	SL	200.60	X
26	1 ABSORBER ASSY, SHOCK, FRONT RH	\$	SL	401.80	X
27	1 COCK ASSY, RESERVE TANK	\$	Ref	117.80	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5304A**AAD1811-182**

	\$	12,676.69
25%	\$	3,169.17
	\$	<u>9,507.52</u>

Special Nett

1	1 FRONT WHEEL RIM	\$	<i>Net</i> 1,570.55 ✓
2	1 FRONT WHEEL RIM COVER	\$	<i>Sm</i> 175.80 X
3	1 CLIP, FRONT FENDER LINER	\$	<i>nn</i> 22.00 ✓

TOTAL \$ 1,768.35**TOTAL PARTS \$ 11,275.87****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00 <i>8801</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>5001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1811-182

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5304A

To replace, refix and top up coolant for radiator	\$	<i>nn</i>	170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i>	170.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>nn</i>	380.00 X

TOTAL \$ 10,400.00**Over All Total \$ 31,183.39****(PART-BY-PART) Repair Days***14 days**4 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**