

Adnan LLC - AXA



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

22/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA.

Joy.

Accident date: 21/11/2018

Estimated repair cost for vehicle no: PC8232P GOLDEN DRAGON XML6103J98

CHASSIS: LL3BGCDH7AA003374

6.7 M '10

S/n	Qty	Items	U/price	Amount	
1	1	Rear R/H Front Tailgate (Aluminium) <i>Dented</i>		\$2,800.00	14.00(SN)
2	1	Rear R/H Front Tailgate Outer Handle <i>lt</i>		\$350.00	180(SN)
3	1	Rear R/H Front Tailgate Signal Lamp <i>new</i>		\$160.00	+
4	1	Rear R/H Front Tailgate Inner Rubber <i>new</i>		\$280.00	+
5	1	Rear R/H Front Tailgate Battery Panel <i>new</i>		\$680.00	+
6	2	Rear R/H Front Tailgate Shock Absorber <i>new</i>	\$280.00	\$560.00	+
7	1	Rear R/H Rear Tailgate (Aluminium) <i>Dented</i>		\$3,500.00	1500(SN)
8	2	Rear R/H Rear Tailgate Shock Absorber <i>new</i>	\$280.00	\$560.00	+
9	1	Rear R/H Rear Tailgate Inner Rubber <i>new</i>		\$280.00	+
10	1	Rear R/H Rear Tailgate Signal Lamp <i>lt</i>		\$160.00	50(SN)
11	2	Rear R/H Rear Tailgate Outer Lock Assy <i>Dented</i>		\$350.00	50(SN)
12	1	Rear R/H Rear Tailgate Centre Cover Assy <i>new</i>		\$850.00	+
13	1	Rear R/H Rear Tailgate Inner Lower Member <i>2nd</i>		\$420.00	+
14	1	Rear R/H Rear Tailgate Lower Member Top Cover <i>1st</i>		\$400.00	+

Subtotal :- \$11,350.00

SN: 3280

Labour charges

To remove & refit rear radiator

\$380.00 +

To remove & refit battery & check wiring

\$280.00 +

Tuff Kote

\$150.00 +

Panel beating

1100

~~\$2,400.00~~ 500

Spray painting

~~\$2,000.00~~ 600

Subtotal :- \$5,210.00

Total:- \$16,560.00

total: 4380.

L/S: 3.5K.

04 Days.

3.5K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: