

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388

FAX: 62962706

ATTN: Motor Claim Department

Estimate No: EST1800365

Date: 22 Nov 2018

Veh Reg No: SLF5376J

Make/Model: CHEVROLET ORLANDO
1.4AT TURBO

Chasis No: KL1YA7589HK604496

Reg. Date: 30/08/2016

Your Ref No: SFV91A

Claim Type: Third Party

Accident Date: 20/11/2018

TP Veh Reg No: SFV91A

Estimate Repair Cost to Vehicle No :SLF5376J

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented.</i>	1,404.00	✓
2	1 PC BOOT LID LOGO <i>new</i>	70.00	✓
3	1 PC BOOTLID "CHEVROLET" EMBLEM	55.60	✓
4	1 PC BOOTLID "ORLANDO" EMBLEM	46.80	✓
5	1 PC BOOTLID "TURBO" EMBLEM	36.70	✓
6	1 PC BOOT LID TRIM <i>cracked.</i>	320.00	✓
7	1 PC BOOT LID LOCK <i>Damaged.</i>	185.00	✓
8	1 PC BOOT LID LOCK CHECKER <i>new new</i>	65.70	x.
9	1 PC BOOT LID RUBBER <i>at</i>	279.10	✓
10	1 PC TAIL LAMP - RH <i>new new</i>	478.00	x
11	1 PC REAR PANEL <i>Dented.</i>	866.70	✓
12	1 PC REAR PANEL TRIM <i>Rehanded.</i>	266.90	✓
13	1 PC BOOT COMPARTMENT TRAY <i>Rehanded.</i>	438.00	✓
14	1 PC REAR BUMPER <i>Distorted.</i>	1,467.00	✓
15	1 PC REAR BUMPER REINFORCEMENT <i>Best.</i>	783.60	✓
16	1 PC REAR BUMPER BEAM <i>cracked</i>	211.60	✓
17	1 PC REAR BUMPER TOP COVER <i>Deformed.</i>	310.70	✓
18	1 PC REAR BUMPER LOWER <i>Dehd</i>	547.30	✓
19	1 PC REAR LOWER BUMPER CENTRE GARNISH <i>Rehanded</i>	267.10	✓
20	1 PC REAR BUMPER REFLECTOR - RH <i>cracked</i>	79.60	✓
21	1 PC REAR BUMPER CENTRE LAMP <i>cracked</i>	178.60	✓
22	4 PCS REVERSE SENSORS <i>2 pieces damaged</i>	557.60	568.20
23	2 PCS REAR BUMPER SIDE RETAINER	99.20	✓
24	2 PCS REAR BUMPER RETAINER (SMALL)	66.20	✓
25	1 PC SPARE TYRE HOLDING BRACKET <i>new new</i>	230.70	x.
26	1 PC FRT TOP BUMPER <i>Dehanded.</i>	1,607.00	✓
27	1 PC FRT LOWER BUMPER <i>Dehanded.</i>	529.30	✓
28	1 PC FRT LOWER BUMPER CENTRE GARNISH <i>new new</i>	267.00	x
29	1 PC FRT BUMPER REINFORCEMENT <i>Best.</i>	927.00	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department

Estimate No: EST1800365

Date: 22 Nov 2018

Veh Reg No: SLF5376J
Make/Model: CHEVROLET ORLANDO
1.4AT TURBO

Chasis No: KL1YA7589HK604496

Reg. Date: 30/08/2016

Your Ref No: SFV91A

Claim Type: Third Party
Accident Date: 20/11/2018
TP Veh Reg No: SFV91A

Estimate Repair Cost to Vehicle No :SLF5376J

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	1 PC FRT BUMPER BEAM <i>Sponge cracked.</i>	244.10 ✓	
31	1 PC FRONT TOP GRILLE <i>not me</i>	580.00 ✗	
32	1 PC FRT BOTTOM GRILLE <i>cracked</i>	349.00 ✓	
33	1 PC HEADLAMP LH <i>cracked</i>	983.00 ✓	
34	1 PC AIRCON CONDENSER <i>3 not me</i>	700.00 ✗	
35	1 PC RADIATOR	915.00 ✗	
36	1 PC FRT GRILLE EMBLEM	99.70 ✗	
37	1 PC FRT NUMBER PLATE PANEL <i>delivered</i>	66.90 ✓	
		16,779.70	
	Less 10%	1,677.97	15,101.73
Special Net			
38	1 SET BOOT LID TRIM CLIPS <i>3 new</i>	48.00 30	
39	1 SET REAR PANEL TRIM CLIPS	60.00 10	
40	1 SET REAR LOWER BUMPER CLIPS <i>new</i>	60.00 20	
41	1 SET REAR LOWER BUMPER CENTRE GARNISH CLIPS <i>new</i>	48.00 20	
42	1 PC REAR WINDSCREEN SEAL <i>3 new</i>	60.00 30	
43	1 PC REAR WINDSCREEN SEALANT <i>3 new</i>	60.00 30	
44	1 SET FRT LOWER BUMPER CENTRE GARNISH CLIPS <i>not me</i>	40.00 ✗	
45	1 SET FRT TOP GRILLE CLIPS <i>3 not me</i>	48.00 ✗	
46	1 SET FRT BOTTOM GRILLE CLIPS <i>3 not me</i>	48.00 ✗	
47	1 PC FRT NUMBER PLATE <i>cracked</i>	50.00 ✓	
		522.00	522.00
Labour			
48	1 TO CHECK WIRING	50.00 30	
49	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
50	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00 50	
51	1 TO REMOVE AND REFIT INNER TRIM	180.00 60	
52	1 TO SPRAY UNDERSEAL	200.00 50	
53	1 (REAR) TO SPRAY PAINTING	1,300.00 900	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388

FAX: 62962706

ATTN: Motor Claim Department

Estimate No: EST1800365

Date: 22 Nov 2018

Veh Reg No: SLF5376J

Make/Model: CHEVROLET ORLANDO
1.4AT TURBO

Chasis No: KL1YA7589HK604496

Reg. Date: 30/08/2016

Your Ref No: SFV91A

Claim Type: Third Party

Accident Date: 20/11/2018

TP Veh Reg No: SFV91A

Estimate Repair Cost to Vehicle No :SLF5376J

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
54	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00	1,500.00
55	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	120.00
56	1 TO CHECK WIRING	50.00	50.00
57	1 TO REFILL AIRCON GAS	120.00	120.00
58	1 TO SPRAY UNDERSEAL	80.00	80.00
59	1 (FRONT) TO SPRAY PAINTING	800.00	800.00
60	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	1,000.00
		5,560.00	5,560.00
	Total		S\$ 21,183.73
	Add GST @ 7%		1,482.86
	Total Amount Payable		S\$ 22,666.59

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND SIX HUNDRED SIXTY SIX AND CENTS FIFTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Adrian Lim
H/S 23/11/18
09 Days.
Total: 14808.78
H/S: 11.8K.