

22/03/2002

ASS. REC. BY:

REF:

CS/AIG18021247/Ksd307

Special Instruction:

Surveyor:
Maimon

Kenneth

ASSIGNMENT (Office)

From (Person):

Azlan Syazaidin

AIG

Date/Time:

23/11/18 3:04pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 5615P

Insured:

SLM 4540X

at Workshop m/s

H.C. Auto

Tel:

9457 0678

of

160 Sin Ming Drive #05-09

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/11/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:20pm 23/11/18

Person Contacted:

Yan Fong

Vehicle ☒ IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
| | SKN 5615P - X |
| | SLM 4540 X - X |
| | |
| | |
| | |
| | |
| | |

ASS. REC. BY:

REF:

AG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKN 5615P

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c.

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

134061

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM 6BM 4 2ABE 0107463

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

3

mm

L/Bal.

d

mm

L/Bal.

3

mm

D.O.A.

21/11/18

D.O.I.

23/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/11 File pass to Catherine, E/R not ready

MV - \$ 531k

LTA - \$ 41,318.00

NEH - \$ 11,682.00

Submit L/S \$ 11,500/- @ 16 days (unconfirm)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair:

16

Resurvey No. of Trip:

3

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

TOTAL

261

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

11,500/- 45

- Pre repair inspection request - SKN5615P VS SLM4540X (OI) DOA 21/11/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul; Fan, Winnie-LW
Sent: 23/11/2018 3:04:24 PM
Attachments: 20181123114651.pdf 20181123100306.pdf

Hi,

Please refer to the enclosed request from **VISION LAW LLC**.

Claim no : 0192296936SG003
Case Owner : CHIT YAN FOO

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Prestina Moh [mailto:prestinamoh@visionlawllc.com]
Sent: Friday, November 23, 2018 11:49 AM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul; Fan, Winnie-LW
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM4540X AND SKN5615P ON 21/11/2018

WITHOUT PREJUDICE
Our ref: SKN 5615 P

Dear Sir/Mdm

Please see attached our letter of even date for your attention.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]
Sent: Friday, 23 November, 2018 10:41 AM
To: prestinamoh@visionlawllc.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Kaur, Baljit; Hor, Yinrul; Fan, Winnie-LW
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM4540X AND SKN5615P ON 21/11/2018

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-11-30 10:41 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com
To: prestinamoh@visionlawllc.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, yokeshi.chan@aig.com, NoorMariesa.AbuKassim@aig.com, Baljit.Kaur@aig.com, Yin.LW.Fan@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM4540X AND SKN5615P ON 21/11/2018
Date: Fri, 23 Nov 2018 02:41:20 +0000
Without Prejudice

Your Reference : SKN 5615 P
Our Reference : SLM4540X

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| AIG In House Surveyor | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Chan, Yoke Shi
Sent: Friday, November 23, 2018 10:16 AM
To: Azlan, Syazairdina
Subject: FW: PRE-REPAIR SURVEY

From: Prestina Moh [mailto:prestinamoh@visionlawllc.com]
Sent: Friday, November 23, 2018 10:09 AM
To: Supramaniam, Darshene; Abu Kassim, Noor Mariesa
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: PRE-REPAIR SURVEY

WITHOUT PREJUDICE
Our ref: SKN 5615 P

Dear Sir/Mdm

Please see attached our PRS request for your attention.

Regards,

Prestina Moh (Secretary)
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811 (Ext. 146)
Fax: 6535-6802

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

✓ HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6

#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SKN 5615 P (PM)
Your Ref: SLM 4540 X

23 November 2018

BY EMAIL ONLY

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING SKN 5615 P & SLM 4540 X ON 18 NOVEMBER 2018 ALONG JUNCTION OF KILLINEY ROAD AND EXETER ROAD AT ABOUT 1700 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **KENNETH KONG - LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Venue: H C Auto Pte Ltd
160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722
Contact: Mr. Joe @ 9457-0678

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



DIANE ANG
(HEAD OFFICE)

cc: SKN 5615 P - By fax: 64578287 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

- [Upcoming] 2019 Hyundai Elantra (facelift)
- Petrol price keeps increasing!
- 2014 / 2015 BMW 2 Series Active / Gran Tourer

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$638
GV Credit Pte Ltd [StarAd](#)

▪ Free VICOM evaluation
 ▪ Free grooming and 6 months maintenance
 ▪ In-house workshop ensures quality service
 ▪ Member of SYTA and hire purchase association
 ▪ 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

3 vehicles

Mazda 3

Advanced Search

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|---|---------|----------------------|----------|--------------|-------------|----------|-----------|----------|-----------|
| Search Selection | Mazda 3 | | Any | Any | 2014 | Any | Any | Any | Available |
|  | Mazda 3 | Mazda 3 1.5A Deluxe | \$52,833 | \$8,660 /yr | 30-Jun-2014 | 1,496 cc | - | Sedan | Available |
| 1 Owner Low Mileage Of 13K Per Year! Accident Free With Original Paintwork Yet Shine, Leather Seat Is Like New No Repairs Needed Under Carriage And Gearbox Are In Good Condition Still. For More Details ... | | | | | | | | | |
| Posted: 16-Nov-2018 Tags: 2014 Mazda 3, 2014 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda | | | | | | | | | |
|  | Mazda 3 | Mazda 3 1.5A Sunroof | \$51,888 | \$8,760 /yr | 27-Jun-2014 | 1,496 cc | 51,000 km | Sedan | Available |
| Down Payment \$5K Only! From \$880/Month. Genuine Mileage, Guaranteed Non Private-Hire Unit. Outstanding Stock Condition, Very Careful Lady Driver. Last Serviced In May 2018. Diligently Serviced And Mal... | | | | | | | | | |
| Audax Auto Pte Ltd | | | | | | | | | |
| Posted: 30-Oct-2018 Tags: 2014 Mazda 3, 2014 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda | | | | | | | | | |
|  | Mazda 3 | Mazda 3 1.5A Deluxe | \$55,000 | \$8,700 /yr | 01-Oct-2014 | 1,496 cc | - | Sedan | Available |
| Well Kept And Maintained By Previous Owner. Always Parked In Sheltered Area. Drive With A Peace Of Mind. Trade In And High Loans Available. Call/Whatsapp Now To Arrange An Appointment For Viewing. | | | | | | | | | |
| Monster Motors Pte Ltd | | | | | | | | | |
| Posted: 21-Sep-2018 Tags: 2014 Mazda 3, 2014 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda | | | | | | | | | |

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mazda 3, Mazda 3 Singapore, used Mazda 3 Singapore, used Mazda 3, used vehicles Singapore or even buy used Mazda 3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 1948K |
| Vehicle Details | |
| Vehicle No.: | SKN5615P |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 27 Nov 2018 |
| Vehicle Make: | MAZDA |
| Vehicle Model: | MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2014 |
| Engine No.: | P520201154 |
| Chassis No.: | JM6BM42A8E0107463 |
| Maximum Power Output: | 88.0 kW (118 bhp) |
| Open Market Value: | \$19,060.00 |
| Original Registration Date: | 25 Jun 2014 |
| First Registration Date: | 25 Jun 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$9,060.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 24 Jun 2024 |
| PARF Rebate Amount: | \$6,795.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 24 Jun 2024 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$61,899.00 |
| COE Rebate Amount: | \$34,523.00 |
| Total Rebate Amount: | \$41,318.00 |

The information contained herein is correct as at 26 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------|
| Date Of Report | 22/11/2018 17:38 |
| Date Of Accident | 21/11/2018 20:45 |
| Exact Location Of Accident | YIO CHU KANG ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|---------------------------|
| Vehicle Registration Number | SKN5615P |
| Insured/Policyholder | |
| Name Of Registered Owner | SWEE SENG LEASING PTE LTD |
| Co Reg No | 201111948K |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-64663808 |

Vehicle Particulars

| | |
|--|-----------------|
| Manufacturer | MAZDA |
| Model | 3-1.5 SEDAN (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMHCSN1422691804 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | CHONG YUNG CHIANG |
| NRIC No | S8015806H |
| Date Of Birth | 01/06/1980 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 17/04/2000 |
| Driving Experience | 18 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | +65-93833344 |
| Fax Number | |
| Contact Number | |
| EMail Address | NOEMAIL |

| | |
|---|---------------------------------|
| Address | BLK 262C COMPASSVALE ST #10-137 |
| Postcode | 643262 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - LESSEE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - CROSS JUNCTION |
| Weather Conditions | RAINING |
| Road Surface | WET |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|----------------|
| Vehicle Registration Number | SLM4540X |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | CHUA SENG HOCK |
| NRIC/Passport Number | S0655098C |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/11/18 at about 8:47pm, I was travelling on the extreme left lane along Yio Chu Kang Rd. The traffic light at Lenton Rd junction was green in my favour. Hence, I proceeded straight. Vehicle B which was turning right from the opposite direction did not wait for his turn and collided into my vehicle's front right portion. The impact resulted in both the airbags in my vehicle being activated. Both me and my wife felt unwell after the accident.

☐ Claim own policy
☐ Claim third party
☒ Claim OD (TP) at other works hop
☐ For record purpose
 Policy No. DMTCSN144781804
 Insurer CHINA Veh. No. SEN 915P

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Shawn
NRIC/FIN No.:

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 22 / 11 / 2018

ESTIMATE COSTS OF REPAIR

M/s Swee Seng Leasing Pte. Ltd.

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 57572

Dear Sir / Madam ,

Vehicle no. : SKN 5615 P - Mazda 3 1.5L Sedan

Accident date : 21 / 11 / 2018

*Not Withheld
C/Lng B?
Pursuing After Paint*

As informed BY repair max \$11,500/-

| Quantity | Descriptions | Amount (S\$) |
|----------|---|-----------------------------|
| 1 | 1 pc bonnet | \$ <i>BN</i> 1,067.30 ✓ |
| 2 | 2 pcs bonnet stopper rubber 1 @ 11.20 | \$ <i>BN</i> 22.40 X |
| 3 | 2 pcs bonnet hinge 1 @ 41.00 | <i>BN</i> \$ 82.00 ✓ |
| 4 | 1 pc bonnet lock | \$ <i>BN</i> 211.00 ✓ |
| 5 | 1 pc bonnet lock catch | \$ <i>BN</i> 52.80 X |
| 6 | 2 pcs bonnet rubber 1 @ 87.60 | \$ <i>BN</i> 175.20 ✓ |
| 7 | 2 pcs head lamp 1 @ 2245.00 <i>also m</i> | <i>also m</i> \$ 4,490.00 ✓ |
| 8 | 2 pcs head lamp lower bracket 1 @ 15.00 | \$ <i>CM</i> 30.00 ✓ |
| 9 | 2 pcs head lamp ECU 1 @ 895.50 | <i>also m</i> \$ 1,791.00 ✓ |
| 10 | 1 pc front bumper | <i>BN/CM</i> 1,031.70 ✓ |
| 11 | 10 pcs front bumper clip 1 @ 4.00 | \$ <i>BN</i> 40.00 ✓ |
| 12 | 1 pc front bumper top | \$ <i>BN</i> 837.90 X |
| 13 | 1 pc front bumper reinforcement | \$ <i>BN</i> 565.10 ✓ |
| 14 | 2 pcs front bumper side retainer 1 @ 27.10 | \$ <i>BN</i> 54.20 ✓ |
| 15 | 1 pc front bumper tow cover | \$ <i>BN</i> 28.60 ✓ |
| 16 | 2 pcs front bumper signal lamp 1 @ 157.30 | <i>also m</i> 314.60 ✓ |
| 17 | 2 pcs front bumper fog lamp 1 @ 351.40 | <i>also m</i> 351.40 ✓ |
| 18 | 2 pcs front bumper fog lamp cover 1 @ 46.40 | \$ <i>BN</i> 92.80 ✓ |
| 19 | 1 pc front bumper lower garnish | \$ <i>BN</i> 800.00 X |
| 20 | 2 pcs front bumper side grille 1 @ 121.00 | \$ <i>CM</i> 121.00 ✓ |
| 21 | 2 pcs front bumper bracket 1 @ 12.00 | \$ <i>BN</i> 24.00 ✓ |
| 22 | 1 pc front bumper number plate garnish | \$ <i>BN</i> 35.00 ✓ |
| 23 | 1 pc front bumper lower beam | \$ <i>BN</i> 444.50 ✓ |
| 24 | 2 pcs front bumper nozzle 1 @ 242.40 | \$ <i>BN</i> 484.80 ✓ |
| 25 | 2 pcs front bumper nozzle cover 1 @ 85.10 | \$ <i>BN</i> 170.20 ✓ |
| 26 | 1 pc front grille | \$ <i>CM</i> 581.10 ✓ |
| 27 | 2 pcs front grille bracket 1 @ 15.10 | \$ <i>BN</i> 30.20 ✓ |
| 28 | 10 pcs front grille clip 1 @ 5.00 | \$ <i>BN</i> 50.00 ✓ |
| 29 | 2 pcs front grille chrome 1 @ 176.70 | \$ <i>CM</i> 353.40 ✓ |
| | Balance C/FD | \$ 14,332.20 |

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

| | | | | |
|----|--------|--|---------------------------------|---|
| | | Balance B/FD (SKN 5615 P) | \$ 14,332.20 | |
| 30 | 1 pc | front grille "Mazda" logo | \$ <i>mi</i> 44.20 | ✓ |
| 31 | 2 pcs | front fender 1 @ 333.90 | \$ <i>Be</i> 667.80 | ✓ |
| 32 | 2 pcs | front fender top rubber 1 @ 94.16 | \$ <i>su</i> 188.32 | X |
| 33 | 2 pcs | front fender inner garnish 1 @ 141.00 | \$ <i>cm</i> 282.00 | — |
| 34 | 10 pcs | front fender inner garnish clip 1 @ 3.50 | \$ <i>wa</i> 35.00 | — |
| 35 | 1 pc | n/s front fender wiper garnish | \$ <i>su</i> 216.50 | X |
| 36 | 1 pc | n/s front fender wiper garnish side (triangle) | \$ <i>su</i> 17.30 | X |
| 37 | 1 pc | front support panel | \$ <i>cm</i> 469.70 | — |
| 38 | 1 pc | brace panel | \$ <i>Be</i> 38.80 | — |
| 39 | 1 pc | radiator | <i>Be</i> \$ <i>Pr</i> 1,064.90 | — |
| 40 | 1 pc | radiator top hose | \$ <i>su</i> 37.70 | X |
| 41 | 1 pc | radiator spare tank | \$ <i>nd</i> 65.80 | — |
| 42 | 1 pc | radiator fan cowling | \$ <i>cm</i> 421.00 | — |
| 43 | 2 pcs | radiator fan motor 1 @ 410.40 | \$ <i>Tu</i> 820.80 | — |
| 44 | 2 pcs | radiator fan blade 1 @ 277.70 | \$ <i>cm</i> 555.40 | — |
| 45 | 1 pc | radiator top panel | \$ <i>Be</i> 140.10 | — |
| 46 | 1 pc | radiator top garnish | \$ <i>cm</i> 92.20 | — |
| 47 | 1 pc | radiator side garnish | \$ <i>cm</i> 35.60 | — |
| 48 | 1 pc | air con condenser | <i>Be</i> \$ <i>Pr</i> 1,063.00 | ✓ |
| 49 | 1 pc | air con pipe (suction) | \$ <i>su</i> 345.70 | X |
| 50 | 1 pc | air con pipe (liquid) | \$ <i>Be</i> 463.80 | X |
| 51 | 1 pc | air con discharges hose | \$ <i>Pr</i> 248.80 | X |
| 52 | 1 pc | engine mounting rear | \$ <i>cm</i> 171.30 | — |
| 53 | 1 pc | engine mounting LH | \$ <i>cm</i> 298.90 | — |
| 54 | 1 pc | engine mounting RH | \$ <i>cm</i> 377.00 | — |
| 55 | 1 pc | front dashboard | \$ <i>Tu</i> 1,429.10 | — |
| 56 | 1 pc | steering air bag | <i>Be</i> \$ 1,082.50 | — |
| 57 | 1 pc | steering air bag clock spring | \$ <i>su</i> 484.40 | ✓ |
| 58 | 1 pc | steering wheel | \$ <i>su</i> 779.70 | X |
| 59 | 1 pc | air bag sensor | \$ <i>su</i> 145.90 | — |
| 60 | 1 pc | air bag ECU | \$ <i>su</i> 1,523.90 | — |
| 61 | 1 pc | passenger air bag | <i>Be</i> \$ 1,169.60 | — |
| 62 | 2 pcs | front seat belt 1 @ 1125.00 | \$ <i>Tu</i> 2,250.00 | ✓ |
| 63 | 1 pc | horn | \$ <i>nd</i> 60.40 | ✓ |
| 64 | 1 pc | air intake manifold | \$ <i>su</i> 809.90 | X |
| 65 | 1 pc | air cleaner box (top) | \$ <i>su</i> 75.40 | X |
| 66 | 1 pc | air cleaner box (bottom) | \$ <i>su</i> 79.70 | X |
| 67 | 1 pc | air cleaner box air duct | \$ <i>su</i> 92.70 | X |
| 68 | 1 pc | air cleaner air hose | \$ <i>su</i> 61.20 | X |
| 69 | 1 pc | engine ECU | \$ <i>su</i> 2,867.00 | X |
| 70 | 1 pc | n/s front chassis | \$ <i>R</i> 1,569.80 | X |
| 71 | 1 pc | steering rack & pinion | \$ <i>R</i> 915.40 | X |
| | | Balance C/FD | \$ 37,890.42 | |

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

| | | |
|----|------|--------------------------------------|
| | | Balance B/FD (SKN 5615 P) |
| 72 | 1 pc | n/s front drive shaft |
| 73 | 1 pc | n/s front lower arm |
| 74 | 1 pc | n/s front kunckle arm |
| 75 | 1 pc | n/s front kunckle arm bearing |
| 76 | 1 pc | n/s front shock absorber |
| 77 | 1 pc | n/s front anti-roll bar side linkage |
| 78 | 1 pc | front cross member |
| 79 | 1 pc | fuse box |
| 80 | 1 pc | front wire hardness |
| 81 | 1 pc | electrical capacitor |
| 82 | 1 pc | throttle body |
| 83 | 1 pc | wiper tank |
| 84 | 1 pc | wiper tank motor |
| 85 | 1 pc | wiper tank pipe |

Less 20%

| | | |
|----|-------|--|
| 86 | 1 pc | coolant |
| 87 | 1 pc | front no. plate |
| 88 | 2 pcs | center pillar inner garnish (top) |
| 89 | 2 pcs | center pillar inner garnish (bottom) |

Balance C/FD

Labour charges
 To putty and spray painting
 Re-seal anti rust
 To check chassis alignment
 Towing Charges (King Dolley)
 Remove and refix front undercarriage
 To check front wheel alignment
 Remove and refix cushion seat, garnish, car pet, etc.
 Refill air con gas
 To remove dashboard
 To remove and refix engine
 To remove and refix front windscreen glass
 To use computer to install air bag ECU and reset ABS
 To remove & refix upholstery, cushion seat, garnish carpet,
 To check, replace, repair wiring & re-set fault code

Plus : 7% GST

Grand total

\$ 37,890.42

\$ 1,712.00

\$ 484.70

\$ 383.40

\$ 541.70

\$ 343.60

\$ 86.40

\$ 1,791.00

\$ 478.20

\$ 333.33

\$ 3,926.10

\$ 1,021.00

\$ 104.00

\$ 476.00

\$ 17.50

\$ 49,589.35

\$ 9,917.87

\$ 39,671.48

\$ 120.00 sn 205n

\$ 50.00 sn 455n

\$ 1,000.00 sn X

\$ 1,000.00 sn X

\$ 41,841.48

\$ 2,500.00 1200

\$ 2,000.00 1200

\$ 200.00 150

\$ 250.00

\$ 180.00 120

\$ 350.00 200

\$ 120.00 60

\$ 360.00 120

\$ 160.00 100

\$ 280.00 250

\$ 350.00 280

\$ 160.00 120

\$ 450.00 250

\$ 350.00 X

\$ 240.00 120

\$ 49,791.48

\$ 3,485.40

\$ 53,276.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|---|---|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 23 Nov 2018 Edit Reg | | 23 Nov 2018 00:00 Edit Adj Rpt | S\$11,500.00 Edit Estimates | S\$11,500.00 View Rpt | | Pending for Survey Report Cancel Case |








































| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|-----------|--|------------|------------------------------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: PATRICK CHUA , ID: S8326103Z | | | | | | | | | |
| Main Claimant: - | | | | | | | | | |
| Vehicle Reg. No.: SKN5615P | | Date of Loss: 21/11/2018 00:00 - :59 [52 Months and 27 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: TP / 0192296936SG | | Policy/Cover Note No.: 2100507302 (Comprehensive) | | | | | | | |
| Vehicle Reg. No. (Insured): SLM4540X | | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City, 575722 Sin Ming - Tel: 64570678 | | | | | | | | | |
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com | | | | | | | | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/12/2018] | | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | View All Compose Case Mail | | | | | |
| <ul style="list-style-type: none"> AIG_SG (26/11/2018): Request to upload TP GIA Report | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

***SKN5615P (0192296936SG)**
[SLM4540X]

—

Nov 21 2018 12:00AM
[PATRICK CHUA]
H C Auto Pte Ltd

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp...> 27/11/2019

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 44 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 27/11/19 10:52 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 27/11/19 10:52 | SKN 5615P GIA.pdf |  Load PDF | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 26/11/18 11:00 | OI GIA REPORT |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

| |
|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18021247/KSD3E2

Date: 27/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507302
Claimant
Vehicle No : SKN5615P **Insured Vehicle No :** SLM4540X
Date of Loss: 21/11/2018 **Nature of Claim:** TP **Claim No:** 0192296936SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN5615P
Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) **Engine No:** P520201154
Reg. Date: 25/06/2014 (Man. Year: 2014) **Chassis No:** JM6BM42A8E0107463
Colour: Metallic Grey **Odometer:** 134061 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 **Rear Tyre Size:** 205/60 R16
Front Left Side: Bridgestone 8 mm **Rear Left Side:** Bridgestone 3 mm
Front Right Side: Bridgestone 8 mm **Rear Right Side:** Bridgestone 3 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|------------------|------------------|--------------|
| Parts | 41,841.48 | 23,025.80 | 18,815.68 | 44.97 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,950.00 | 4,420.00 | 3,530.00 | 44.40 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 49,791.48 | 27,445.80 | 22,345.68 | 44.88 |
| Approved Total (Overridden) (\$\$) | | 11,500.00 | | |
| (\$\$) | 49,791.48 | 11,500.00 | 38,291.48 | 76.90 |
| + GST 7.00/7.00% (\$\$) | 3,485.40 | 805.00 | 2,680.40 | 76.90 |
| Nett Amount (\$\$) | 53,276.88 | 12,305.00 | 40,971.88 | 76.90 |

INSPECTION

Date of Assignment: 23/11/2018
Date Inspected: 23/11/2018 Inspected At: H C Auto Pte Ltd (HQ)
160 Sin Ming Drive, #05-09 Sin Ming
Auto City
Singapore 575722
Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$53,000.00(EST)-LTA REIMBURSEMENT VALUE: \$41,318.00=NETT VALUE: \$11,682.00

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------------------------|-------------|--------------|
| 1 | 1 | | *BONNET | Bent | 1,067.30 FL | *1,067.30 FL |
| 2 | 2 | | *BONNET STOPPER RUBBER | Serviceable | 22.40 FL | *- FL |
| 3 | 2 | | *BONNET HINGE | Bent / Distorted | 82.00 FL | *82.00 FL |
| 4 | 1 | | *BONNET LOCK | Distorted | 211.00 FL | *211.00 FL |
| 5 | 1 | | *BONNET LOCK CATCH | Repair | 52.80 FL | *- FL |
| 6 | 2 | | *BONNET RUBBER | Cut | 175.20 FL | *175.20 FL |
| 7 | 2 | | *HEAD LAMP | O/S Cracked / N/S Mtg Cracked | 4,490.00 FL | *4,490.00 FL |
| 8 | 2 | | *HEAD LAMP LOWER BRACKET | Cracked | 30.00 FL | *30.00 FL |
| 9 | 2 | | *HEAD LAMP ECU | Mtg Cracked | 1,791.00 FL | *1,791.00 FL |
| 10 | 1 | | *FRONT BUMPER | Bent / Cracked | 1,031.70 FL | *1,031.70 FL |
| 11 | 10 | | *FRONT BUMPER CLIP | Necessary | 40.00 FL | *40.00 FL |
| 12 | 1 | | *FRONT BUMPER TOP | Serviceable | 837.90 FL | *- FL |
| 13 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 565.10 FL | *565.10 FL |
| 14 | 2 | | *FRONT BUMPER SIDE RETAINER | Distorted | 54.20 FL | *54.20 FL |
| 15 | 1 | | *FRONT BUMPER TOW COVER | Missing | 28.60 FL | *28.60 FL |
| 16 | 2 | | *FRONT BUMPER SIGNAL LAMP | Mtg Cracked | 314.60 FL | *314.60 FL |
| 17 | 2 | | *FRONT BUMPER FOG LAMP | Mtg Cracked | 351.40 FL | *351.40 FL |
| 18 | 2 | | *FRONT BUMPER FOG LAMP COVER | Missing | 92.80 FL | *92.80 FL |
| 19 | 1 | | *FRONT BUMPER LOWER GARNISH | Serviceable | 800.00 FL | *- FL |
| 20 | 2 | | *FRONT BUMPER SIDE GRILLE | Cracked | 121.00 FL | *121.00 FL |
| 21 | 2 | | *FRONT BUMPER BRACKET | Distorted | 24.00 FL | *24.00 FL |
| 22 | 1 | | *FRONT BUMPER NUMBER PLATE GARNISH | Missing | 35.00 FL | *35.00 FL |
| 23 | 1 | | *FRONT BUMPER LOWER BEAM | Bent | 444.50 FL | *444.50 FL |
| 24 | 2 | | *FRONT BUMPER NOZZLE | Missing | 484.80 FL | *484.80 FL |
| 25 | 2 | | *FRONT BUMPER NOZZLE COVER | Missing | 170.20 FL | *170.20 FL |
| 26 | 1 | | *FRONT GRILLE | Cracked | 581.10 FL | *581.10 FL |
| 27 | 2 | | *FRONT GRILLE BRACKET | Distorted | 30.20 FL | *30.20 FL |
| 28 | 10 | | *FRONT GRILLE CLIP | Necessary | 50.00 FL | *50.00 FL |
| 29 | 2 | | *FRONT GRILLE CHROME | Cracked | 353.40 FL | *353.40 FL |
| 30 | 1 | | *FRONT GRILLE MAZDA LOGO | Missing | 44.20 FL | *44.20 FL |
| 31 | 2 | | *FRONT FENDER | Buckled | 667.80 FL | *667.80 FL |
| 32 | 2 | | *FRONT FENDER TOP RUBBER | Serviceable | 188.32 FL | *- FL |
| 33 | 2 | | *FRONT FENDER INNER GARNISH | Cracked | 282.00 FL | *282.00 FL |
| 34 | 10 | | *FRONT FENDER INNER GARNISH CLIP | Necessary | 35.00 FL | *35.00 FL |
| 35 | 1 | | *N/S FRONT FENDER WIPER GARNISH | Serviceable | 216.50 FL | *- FL |
| 36 | 1 | | *N/S FRONT FENDER WIPER GARNISH SIDE (TRIANGLE) | Serviceable | 17.30 FL | *- FL |
| 37 | 1 | | *FRONT SUPPORT PANEL | Cracked | 469.70 FL | *469.70 FL |
| 38 | 1 | | *BRACE PANEL | Bent | 38.80 FL | *38.80 FL |
| 39 | 1 | | *RADIATOR | Bent / Punctured | 1,064.90 FL | *1,064.90 FL |
| 40 | 1 | | *RADIATOR TOP HOSE | Serviceable | 37.70 FL | *- FL |
| 41 | 1 | | *RADIATOR SPARE TANK | Dented | 65.80 FL | *65.80 FL |
| 42 | 1 | | *RADIATOR FAN COWLING | Cracked | 421.00 FL | *421.00 FL |
| 43 | 2 | | *RADIATOR FAN MOTOR | Jammed | 820.80 FL | *820.80 FL |
| 44 | 2 | | *RADIATOR FAN BLADE | Cracked | 555.40 FL | *555.40 FL |
| 45 | 1 | | *RADIATOR TOP PANEL | Buckled | 140.10 FL | *140.10 FL |
| 46 | 1 | | *RADIATOR TOP GARNISH | Cracked | 92.20 FL | *92.20 FL |
| 47 | 1 | | *RADIATOR SIDE GARNISH | Cracked | 35.60 FL | *35.60 FL |
| 48 | 1 | | *AIR CON CONDENSER | Bent / Punctured | 1,063.00 FL | *1,063.00 FL |
| 49 | 1 | | *AIR CON PIPE (SUCTION) | Serviceable | 345.70 FL | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 50 | 1 | | *AIR CON PIPE (LIQUID) | Bent | 463.80 FL | *463.80 FL |
| 51 | 1 | | *AIR CON DISCHARGES HOSE | Punctured | 248.80 FL | *248.80 FL |
| 52 | 1 | | *ENGINE MOUNTING REAR | Cracked | 171.30 FL | *171.30 FL |
| 53 | 1 | | *ENGINE MOUNTING LH | Cracked | 298.90 FL | *298.90 FL |
| 54 | 1 | | *ENGINE MOUNTING RH | Cracked | 377.00 FL | *377.00 FL |
| 55 | 1 | | *FRONT DASHBOARD | Torn | 1,429.10 FL | *1,429.10 FL |
| 56 | 1 | | *STEERING AIR BAG | Burst | 1,082.50 FL | *1,082.50 FL |
| 57 | 1 | | *STEERING AIR BAG CLOCK SPRING | Necessary | 484.40 FL | *484.40 FL |
| 58 | 1 | | *STEERING WHEEL | Serviceable | 779.70 FL | *- FL |
| 59 | 1 | | *AIR BAG SENSOR | Necessary | 145.90 FL | *145.90 FL |
| 60 | 1 | | *AIR BAG ECU | Necessary | 1,523.90 FL | *1,523.90 FL |
| 61 | 1 | | *PASSENGER AIR BAG | Burst | 1,169.60 FL | *1,169.60 FL |
| 62 | 2 | | *FRONT SEAT BELT | Jammed | 2,250.00 FL | *2,250.00 FL |
| 63 | 1 | | *HORN | Dented | 60.40 FL | *60.40 FL |
| 64 | 1 | | *AIR INTAKE MANIFOLD | Serviceable | 809.90 FL | *- FL |
| 65 | 1 | | *AIR CLEANER BOX (TOP) | Serviceable | 75.40 FL | *- FL |
| 66 | 1 | | *AIR CLEANER BOX (BOTTOM) | Serviceable | 79.70 FL | *- FL |
| 67 | 1 | | *AIR CLEANER BOX AIR DUCT | Serviceable | 92.70 FL | *- FL |
| 68 | 1 | | *AIR CLEANER AIR HOSE | Serviceable | 61.20 FL | *- FL |
| 69 | 1 | | *ENGINE ECU | Serviceable | 2,867.00 FL | *- FL |
| 70 | 1 | | *N/S FRONT CHASSIS | Repair | 1,569.80 FL | *- FL |
| 71 | 1 | | *STEERING RACK & PINION | Repair | 915.40 FL | *- FL |
| 72 | 1 | | *N/S FRONT DRIVE SHAFT | Repair | 1,712.00 FL | *- FL |
| 73 | 1 | | *N/S FRONT LOWER ARM | Serviceable | 484.70 FL | *- FL |
| 74 | 1 | | *N/S FRONT KNUCKLE ARM | Serviceable | 383.40 FL | *- FL |
| 75 | 1 | | *N/S FRONT KNUCKLE ARM BEARING | Not Necessary | 541.70 FL | *- FL |
| 76 | 1 | | *N/S FRONT SHOCK ABSORBER | Serviceable | 343.60 FL | *- FL |
| 77 | 1 | | *N/S FRONT ANTI-ROLL BAR SIDE LINKAGE | Serviceable | 86.40 FL | *- FL |
| 78 | 1 | | *FRONT CROSS MEMBER | Serviceable | 1,791.00 FL | *- FL |
| 79 | 1 | | *FUSE BOX | Serviceable | 478.20 FL | *- FL |
| 80 | 1 | | *FRONT WIRE HARDNESS | Repair | 333.33 FL | *- FL |
| 81 | 1 | | *ELECTRICAL CAPACITOR | Serviceable | 3,926.10 FL | *- FL |
| 82 | 1 | | *THROTTLE BODY | Serviceable | 1,021.00 FL | *- FL |
| 83 | 1 | | *WIPER TANK | Dented | 104.00 FL | *104.00 FL |
| 84 | 1 | | *WIPER TANK MOTOR | Cracked | 476.00 FL | *476.00 FL |
| 85 | 1 | | *WIPER TANK PIPE | Serviceable | 17.50 FL | *- FL |
| 86 | 1 | | *COOLANT | Necessary | 120.00 FS | *20.00 FS |
| 87 | 1 | | *FRONT NO. PLATE | Missing | 50.00 FS | *45.00 FS |
| 88 | 2 | | *CENTER PILLAR INNER GARNISH (TOP) | Serviceable | 1,000.00 FS | *- FS |
| 89 | 2 | | *CENTER PILLAR INNER GARNISH (BOTTOM) | Serviceable | 1,000.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|------------------|
| Sub Total (\$\$) | 51,759.35 | 28,766.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 9,917.87 | 5,740.20 |
| Total Parts (\$\$) | 41,841.48 | 23,025.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | LABOUR CHARGES | New | 2,500.00 | 1,200.00 |
| 2 | TO PUTTY AND SPRAY PAINTING | New | 2,000.00 | 1,200.00 |
| 3 | RE-SEAL ANTI RUST | New | 200.00 | 150.00 |
| 4 | TO CHECK CHASSIS ALIGNMENT | New | 250.00 | 250.00 |
| 5 | TOWING CHARGES (KING DOLLEY) | New | 180.00 | 120.00 |
| 6 | REMOVE AND REFIX FRONT UNDERCARRIAGE | New | 350.00 | 200.00 |
| 7 | TO CHECK FRONT WHEEL ALIGNMENT | New | 120.00 | 60.00 |
| 8 | REMOVE AND REFIX CUSHION SEAT, GARNISH, CAR PET, ETC | New | 360.00 | 120.00 |
| 9 | REFILL AIR CON GAS | New | 160.00 | 100.00 |
| 10 | TO REMOVE DASHBOARD | New | 280.00 | 250.00 |
| 11 | TO REMOVE AND REFIX ENGINE | New | 350.00 | 280.00 |
| 12 | TO REMOVE AD REFIX FRONT WINDSCREEN GLASS | New | 160.00 | 120.00 |
| 13 | TO USE COMPUTER TO INSTALL AIR BAG ECU AND RESET ABS | New | 450.00 | 250.00 |
| 14 | TO REMOVE & REFIX UPHOLSTERY, CUSHION SEAT, GARNISH CARPET | New | 350.00 | 0.00 |
| 15 | TO CHECK, REPLACE, REPAIR WIRING & RE-SET FAULT CODE | New | 240.00 | 120.00 |
| Gross Labour Cost (S\$) | | | 7,950.00 | 4,420.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >