

ASS. REC. BY:

REF:

CS/EGT18021293/Avd3

n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGT

Date/Time:

26/11/18 @ 10:02am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 4097A

Insured:

YP 7908E

at Workshop m/s

New Hook Teck

Tel:

6 747 9241

of

1 Kaki Bkt Ave 6 # 01-43

Policy No:

Claim No:

YP 7908E / SL / p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/18

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

10:22am @ 26/11/18

Person Contacted:

Sukyi

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YN 4097A - X
	YP 7908E - CS/EGT18019361/Avb
	JOA - 27/07/2018
27/11/18	Informed Pei Li pending est from repairer
21/12/18	Adrian confirmed LS \$9800 (Red. 22,203, 69%)
21/12/18	Email pref. revised to Pei Li

ASSIGNMENT

Veh No: YN4097A Yr Regn: 2013, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Center. C.C. 2977

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 320350 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FE83BEA21086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or -

Tyre Size: F: 7.00 R16C

R: 7.00 RLB

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Cambodia*

Front Rear

R/Bal. 36 mm R/Bal. 36 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 27/11/18.

Survey held at NH7

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP: Ego
	MV: 40K. PV: 27.1K Nett: 12.9K.
	RECEIVED 21 DEC 2018

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1) 2/12 - typist	2)	IN	OUT	Basic & Add.	
3)	4)			* __ S + RS, __ SI	
5)	6)			Photos	
Preli. Report:				Others	350
Final Report:				TOTAL	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: YP 7908E/SL/pl

Our ref: CS/EGI18021293/Avd3

Date : 21/12/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. YN 4097A


We thank you for your instruction on 26/11/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/11/2018 at the premises of M/s NEW HOCK TECK MOTOR PTE LTD

Workshop Estimate Amount	: S\$32,003.00
Revised Estimate Amount	: S\$9,800.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 21 December 2018 1:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018
Attachments: YN 4097A PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle YN 4097A
Date of survey: 27/11/2018
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 27 November 2018 2:04 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle YN 4097A on 27/11/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 November 2018 10:22 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Monday, 26 November 2018 10:02 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: OI : YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKUI @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 3199
Fax: +65 6829 9247

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 27 November 2018 2:04 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle YN 4097A on 27/11/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 26 November 2018 10:22 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 26 November 2018 10:02 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD,**

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKYI @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax.: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 26 November 2018 10:02 AM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : YP7908E / TP : YN4097A/LKK / DOA : 23/11/2018
Attachments: YP7908E - SAS.pdf; YN4097A - SAS.pdf; YN4097A - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **NEW HOCK TECK MOTOR PTE LTD**,

ADDRESS : 1 KAKI BUKIT AVE 6
#01-43 BLK C AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : REENA / SUKYI @ 6747 9241

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 26.11.2018
Our Reference: YP 7908E/SL/pl
Your Reference: YN 4097A

Sent via Fax 6741 7276
or
Email -

To: NEW HOCK TECK MOTOR PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: YN 4097A
Insured's Vehicle: YP 7908E
Date Of Accident: 23.11.2018


We acknowledge receipt of your request for PRS on: 23.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our Insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE - STEVE

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX: 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

ERGO

Date: 26.11.2018
Our Reference: YP 7908E/SL/pl
Your Reference: YN 4097A

Sent via Fax

6741 7276

or

Email

To: NEW HOCK TECK MOTOR PTE LTD**Pre-Repair Survey (PRS) Acknowledgement**

Vehicle For Inspection: YN 4097A
Insured's Vehicle: YP 7908E
Date Of Accident: 23.11.2018

We acknowledge receipt of your request for PRS on: 23.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from


the list below and indicate your selection in the box marked *.

*

LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:**Assessor attended workshop on:**

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [f Ways of Selling](#)

2009 Model And Jan 2010 Registration.



Well Maintained And With Super
Condition.
Direct Owner StarAd



ABWIN

ONE-STOP



VIEW OUR PROFILE

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

5 vehicles

Search

mitsubishi fe83

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	mitsubishi fe83	Any	Any	2013	Any	Any	Any	Available
------------------	-----------------	-----	-----	------	-----	-----	-----	-----------


☐ Mitsubishi Fuso Canter FE83

\$35,800

\$8,710 /yr

07-Jan-2013

2,977 cc

-

Truck

Available

Fuel Type: Diesel

LTA Approved Full Canopy, Class 3 License, VPC Not Required, Vehicle In Tip Top Condition, Low Down Payment.

Posted: 30-Oct-2018

Tags: 2013 Mitsubishi Fuso, 2013 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi


☐ Mitsubishi Fuso Canter FE83

\$43,800

\$9,860 /yr

08-May-2013

2,977 cc

-

Truck

Available

Fuel Type: Diesel

Book Your Vehicle With Us Now! And Get Insurance Rebate From Us! 14 Ft Mitsubishi Lorry With Open Metal Deck With Sliding Canopy, 1 Owner Only, Very Low Mileage. Do Not Need VPC, Class 3 Driver Able ...

KSL Automotive Pte Ltd

Posted: 27-Nov-2018

Tags: 2013 Mitsubishi Fuso, 2013 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi


☐ Mitsubishi Fuso Canter FE83

\$41,800

\$9,290 /yr

28-May-2013

2,977 cc

-

Truck

Available

Fuel Type: Diesel

High Deck, Wooden Body With LTA Approved Full Canopy, No VPC Required, Class 3 Able To Drive, New Paint, New Seat, All Repair Done Up. Door Step Viewing Can Be Arranged. Call Us Now To Arrange For Vie...

ABWIN (1994) Pte Ltd

Posted: 26-Nov-2018

Tags: 2013 Mitsubishi Fuso, 2013 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi


☐ Mitsubishi Fuso Canter FE83

\$40,800

\$8,950 /yr

19-Jun-2013

2,977 cc

205,000 km

Truck

Available

Fuel Type: Diesel

Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

Think One Automobile & Trading

Posted: 12-Nov-2018

Tags: 2013 Mitsubishi Fuso, 2013 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi



Rapid Automobile Repair Pte Ltd - Tyres & Rims

With more than 15 years in automobile repair & maintenance, Rapid Automobile Repair Pte Ltd is the place where you will be guaranteed customer satisfia

More info about this shop


☐ Mitsubishi Fuso Canter FE83

\$42,800

\$8,960 /yr

06-Sep-2013

2,977 cc

-

Truck

Available

Fuel Type: Diesel

Only 1 Owner. 14ft Deck With Freezer Box, Tip Top Condition, Low Mileage, No VPC, Flexible In House And Bank Loan Available With Low Interest. 100% Loan Can Be Arrange. Trade In Welcome. Price Negotia...

Posted: 01-Oct-2018

Tags: 2013 Mitsubishi Fuso, 2013 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

SHORTLISTED HISTORY

Compare [Home](#)[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Article](#)[Forum](#)[Resources](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 0396K

Vehicle Details

Vehicle No.: YN4097A
Vehicle to be Exported: No
Intended Deregistration Date: 23 Nov 2018
Vehicle Make: MITSUBISHI
Vehicle Model: FE83BE6SRDEA
Primary Colour: White
Manufacturing Year: 2013
Engine No.: 4M42A91797
Chassis No.: FE83BEA21086
Maximum Power Output: -
Open Market Value: \$27,732.00
Original Registration Date: 01 Jul 2013
First Registration Date: 01 Jul 2013
Transfer Count: 0
Actual ARF Paid: \$1,387.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Jun 2023
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$59,001.00
COE Rebate Amount: \$27,156.00
Total Rebate Amount: \$27,156.00

The information contained herein is correct as at 23 Nov 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

23/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPFcyo

Veron

Accident date: 21/11/2018

Estimated repair cost for vehicle no: YN4097A MITSUBISHI FUSO FE83BE

CHASSIS: FE83BEA21086

3.0 M '13

S/n	Qty	Items / List	U/price	Amount
1	2	Rear Tail Lamp <i>cracked</i>	\$262.00	\$524.00 ✓
2	2	Rear Tail Lamp Bracket <i>LH Dmgd</i>	\$188.00	\$376.00 188 ✓
3	1	Rear Number Plate Lamp <i>cracked</i>		\$83.00 ✓
4	1	Front R/H Seat Cushion <i>Damaged</i>		\$1,800.00 * 900 (6)
			795 S.N: 900 596.25 Subtotal :-	\$2,783.00

S/n	Qty	Items / Special Nett	U/price	Amount
5	1	Rear R/H Ice Box Tailgate <i>Dented</i>		\$3,500.00 1800
6	2	Rear R/H Ice Box Tailgate Hinge <i>new</i>	\$280.00	\$560.00 x
7	1	Rear R/H Ice Box Tailgate Centre Bar <i>Bent</i>		\$950.00 350
8	2	Rear R/H Ice Box Tailgate Centre Bar Lock <i>new</i>	\$280.00	\$560.00 x
9	1	Rear R/H Ice Box Tailgate Centre Bar Handle <i>Bent</i>		\$1,250.00 ± 350
10	3	Rear R/H Ice Box Tailgate Centre Bar Bracket <i>new</i>	\$380.00	\$1,140.00 x
11	1	Rear L/H Ice Box Tailgate <i>Dented</i>		\$3,500.00 1800
12	2	Rear L/H Ice Box Tailgate Hinge <i>new</i>	\$280.00	\$560.00 x
13	1	Rear L/H Ice Box Tailgate 70km/H Sticker <i>new</i>		\$20.00 10
14	1	Rear L/H Ice Box Tailgate Centre Bar <i>Bent</i>		\$950.00 350
15	2	Rear L/H Ice Box Tailgate Centre Bar Lock <i>new</i>	\$280.00	\$560.00 x
16	1	Rear L/H Ice Box Tailgate Centre Bar Handle <i>Bent</i>		\$1,250.00 + 350
17	3	Rear L/H Ice Box Tailgate Centre Bar Bracket <i>new</i>	\$380.00	\$1,140.00 +
18	1	Rear Ice Box Tailgate Body Logo <i>new</i>		\$2,500.00 1200
19	1	Rear Ice Box Lower Member <i>Bent</i>		\$1,850.00 +
20	1	Rear Ice Box Lower Member Cover <i>new</i>		\$1,200.00 x
21	1	Rear Number Plate <i>Bent</i>		\$50.00 30
22	1	Rear Number Plate Member <i>Bent</i>		\$680.00 ✓
23	1	Rear Bumper <i>Bent</i>		\$1,200.00 1000
24	2	Rear Bumper Bracket <i>Bent</i>	\$220.00	\$440.00 200
25	2	Rear Chassis Frame Stopper Rubber <i>Dmgd</i>	180	\$360.00

8360

240

Subtotal :- \$23,936.00

Labour charges

To remove & refit ice box tailgate & member cover

~~\$1,200.00~~ 800

Panel beating & repair chassis frame, replace number plate member & bumper

~~\$2,800.00~~ 800

2400

Spray painting

~~\$1,000.00~~ 800

Subtotal :- \$5,000.00

Total:- \$31,719.00

30,003

total 12256.25
h/s: 9.8K
08 Aug

9.8K

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before and after spray painting
- To display all relevant parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18021293/Avd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 24-12-2018		
Code : EGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 7908E	Veh. Inspected	YN 4097A	
Policy No.		Coverage (\$)	0.00	
Claim No.	YP7908E/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	26/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi canter	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	FE83BEA21086	Colour	WHITE	
Odometer	320350	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16C	CONDOR	6 mm	
L/H Front Tyre	7.00 R16C	CONDOR	6 mm	
R/H Rear Tyre	7.00 R16C	CONDOR	6 mm	
L/H Rear Tyre	7.00 R16C	CONDOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2018	Inspection Date	27/11/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 4097A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR TAIL LAMP @\$262.00	CRACKED	524.00	524.00
2	REAR TAIL LAMP BRACKET @\$188.00	N/S DAMAGED	376.00	188.00
1	REAR NUMBER PLATE LAMP	CRACKED	83.00	83.00
	LESS 25% DISCOUNT		-	-198.75
			983.00	596.25
SPECIAL NETT ITEMS				
1	FRONT R/H SEAT CUSHION (SN)	DAMAGED	1,800.00	900.00
1	REAR R/H ICE BOX TAILGATE (SN)	DENTED	3,500.00	1,800.00
2	REAR R/H ICE BOX TAILGATE HINGE @\$280.00 (SN)	NOT NECESSARY	560.00	-
1	REAR R/H ICE BOX TAILGATE CENTRE BAR (SN)	BENT	950.00	350.00
2	REAR R/H ICE BOX TAILGATE CENTRE BAR LOCK @\$280.00 (SN)	NOT NECESSARY	560.00	-
1	REAR R/H ICE BOX TAILGATE CENTRE BAR HANDLE (SN)	BENT	1,250.00	350.00
3	REAR R/H ICE BOX TAILGATE CENTRE BAR BRACKET @\$380.00 (SN)	NOT NECESSARY	1,140.00	-
1	REAR L/H ICE BOX TAILGATE (SN)	DENTED	3,500.00	1,800.00
2	REAR L/H ICE BOX TAILGATE HINGE @\$280.00 (SN)	NOT NECESSARY	560.00	-
1	REAR L/H ICE BOX TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR L/H ICE BOX TAILGATE CENTRE BAR (SN)	BENT	950.00	350.00
2	REAR L/H ICE BOX TAILGATE CENTRE BAR LOCK @\$280.00 (SN)	NOT NECESSARY	560.00	-
1	REAR L/H ICE BOX TAILGATE CENTRE BAR HANDLE (SN)	BENT	1,250.00	350.00
3	REAR L/H ICE BOX TAILGATE CENTRE BAR BRACKET @\$380.00 (SN)	NOT NECESSARY	1,140.00	-
1	REAR ICE BOX TAILGATE BODY LOGO (SN)	NECESSARY	2,500.00	1,200.00
1	REAR ICE BOX LOWER MEMBER (SN)	TO REPAIR SEE LABOUR	1,850.00	-
1	REAR ICE BOX LOWER MEMBER COVER (SN)	NOT NECESSARY	1,200.00	-
1	REAR NUMBER PLATE (SN)	BENT	50.00	30.00
1	REAR NUMBER PLATE MEMBER (SN)	BENT	680.00	680.00
1	REAR BUMPER (SN)	BENT	1,200.00	1,000.00

Report Ref No. CS/EGI18021293/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER BRACKET @\$220.00 (SN)	BENT	440.00	200.00
2	REAR CHASSIS FRAME STOPPER RUBBER @\$180.00 (SN)	DAMAGED	360.00	240.00
			26,020.00	9,260.00
	LABOUR			
	TO REMOVE & REFIT ICE BOX TAILGATE & MEMBER COVER.		1,200.00	800.00
	PANEL BEATING & REPAIR CHASSIS FRAME, REPLACE NUMBER PLATE MEMBER & BUMPER. INCLUSIVE OF THE REPAIR OF REAR ICE BOX LOWER MEMBER.		2,800.00	800.00
	SPRAY PAINTING.		1,000.00	800.00
			5,000.00	2,400.00
GRAND TOTAL			32,003.00	12,256.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,800.00

Report Ref No. CS/EGI18021293/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.