



Your Ref : S8M0148A

Date: 24th December 2018

Our Ref : CS/ASM18021294/Ztd3s2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Lynn Khong

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: SJZ 2191M ACCIDENT ON 22/11/2018

Instruction was received to inspect the vehicle Reg. No. SJZ 2191M. The inspection was conducted on 26/11/2018 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit) Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SJZ 2191M
Make/Model	: Toyota Estima
Year of Registration	: 2006
Body Colour	: Silver
Chassis Number	: ACR507028322
Engine Capacity	: 2362 cc
Speedometer Reading	: Burnt

The vehicle half front severely burnt. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	29,000.00
Less: LTA Reimbursement Value (RV)	(S\$	12,564.00)
Nett Liability	S\$	<u>16,436.00</u>

Vehicle Inspected By:



ROHAIZAL A. RAHIM (HAIZAL)
Technical Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.